

Common Defects and Structural Problems in the Buildings of Northern Cyprus, their Reasons and Prevailing Applicable Solutions

Mohammed Akilah

Submitted to the
Institute of Graduate Studies and Research
in partial fulfilment of the requirements for the degree of

Master of Science
in
Civil Engineering

Eastern Mediterranean University
August 2017
Gazimağusa, North Cyprus

Approval of the Institute of Graduate Studies and Research

Assoc. Prof. Dr. Ali Hakan Ulusoy
Acting Director

I certify that this thesis satisfies the requirements as a thesis for the degree of Master of Science in civil Engineering.

Assoc. Prof. Dr. Serhan Şensoy
Chair, Department of Civil Engineering

We certify that we have read this thesis and that in our opinion it is fully adequate in scope and quality as a thesis for the degree of Master of Science in Civil Engineering.

Assoc. Prof. Dr. Giray Özyay
Supervisor

Examining Committee

1. Assoc. Prof. Dr. Mehmet Cemal Geneş

2. Assoc. Prof. Dr. Giray Özyay

3. Asst. Prof. Dr. Umut Yıldırım

ABSTRACT

In the recent years, building sector grows rapidly parallel to the human needs. Sometimes these quick productions cause several types of problems on the buildings. These problems occur in varying intensities depending on the type, location, environment, materials and the construction conditions of the building. Problems and failures in buildings can be broadly attributed to either defects, deteriorations or structural problems. Mostly, these defects or structural problems arise due to error or omission that is breach of contract or negligence by designer, contractor, or user. In general, lack of care and knowledge in specification or workmanship are the main reasons of various defects and structural problems. On the other hand, deterioration is natural process, which may be unavoidable, although minimized by care in design and the selection of materials. Cracks, efflorescence, peeling on painting, mouldiness, rising dampness, soft storey, short column, shear cracks, compression cracks, irregularities in plan, irregularities in elevation and etc. are some of the most significant problems that occur in building of Northern Cyprus.

These defects, deteriorations and structural problems have negative effects both on human and building lives. They mostly harm to the health and economy. Besides, they reduce the aesthetic quality. On this basis, the aim of the study is to discuss these prevailing defects and structural problems with their reasons which occur in North Cyprus. It is also expected to present the most common precautions and available applied methods for preventing or reducing these problems.

Work to be carried out:

1. General search about the building defects and structural problems and categorization.
2. According to the first step (researches), the most common precautions and available applied methods for preventing or reducing these defects and structural problems were investigated and presented.
3. Case studies in different districts of North Cyprus were visited and the collected data were analysed and compared. There are a total of 125 case studies in this thesis divided into two samples. The first sample represents completed buildings contains 100 case studies consisting of 25 case studies for each of the four following districts: Mağusa, İskele, Lefkoşa and Girne. This sample is aimed for the study of reinforced concrete defects and non-structural defects. The second sample represents buildings under construction contains 25 case studies. This sample is aimed for the study of seismic design faults.

Keywords: Building Defects, Deteriorations, Structural Problems, Seismic Design, Northern Cyprus.

ÖZ

Son yıllarda, inşaat sektörü insanların ihtiyaçlarına paralel olarak hızla büyümektedir. Bazen bu hızlı büyüme, binalarda çeşitli sorunlara sebep olmaktadır. Bu sorunlar, binanın tipi, konumu, kullanılan malzeme, çevre koşulları ve binanın yapım şartlarına bağlı olarak değişen seviyelerde meydana gelmektedir. Binalardaki problemler, kusurlara, bozulmalara ve/veya yapısal sorunlara dayanır. Çoğunlukla, bu kusurlar ve yapısal sorunlar tasarımcının, yüklenicinin ve/veya kullanıcının ihmali nedeniyle ortaya çıkar. Genel olarak, ihmal, şartnamelerle ilgili bilgi eksikliği veya işçilik problemleri binalardaki kusurlar ve yapısal sorunların ana nedenleridir. Öte yandan, binalardaki problemler, tasarım, periyodik bakım ve doğru malzeme seçimi ile minimize edilse de doğası gereği tamamen engellenemeyebilir. Çatlaklar, çiçeklenme, boyada soyulma, küf, zeminden yükselen nem, yumuşak kat, kısa kolon, kesme kuvveti çatlakları, basınç çatlakları, planda düzensizlik durumları, düşey doğrultuda düzensizlik durumları gibi sorunlar Kuzey Kıbrıs'ta bulunan binalarda meydana gelen en önemli sorunlar arasında yer almaktadır.

Bu kusurların, bozulmaların ve yapısal problemlerin insan sağlığı ve binaların ömrü üzerinde olumsuz etkileri vardır. Çoğunlukla da sağlık ve ekonomiye zarar vermektedirler. Bunun yanında, binalardaki estetik kalitesini de düşürmektedirler. Bu temele dayanarak, çalışmanın amacı Kuzey Kıbrıs'taki yapılarda meydana gelen bu problemleri ve sebeplerini ortaya koymaktır. Buna ek olarak seçilen vaka incelemeleriyle, bu problemlerin önlenmesi veya azaltılmasına yönelik çözüm önerileri ve metotlarını sunmaktır.

Gerçekleştirilecek çalışmada:

1. Bina kusurları, yapısal sorunlar ve bunların sebepleri ile ilgili detaylı bilgi verilmesi.
2. İlk adımda yapılan arařtırmalar ışığında, bina problemlerinin önlenmesi veya azaltılması için gerekli çözüm önerileri ve metodlarını arařtırmak ve sunmak.
3. Kuzey Kıbrıs'ın farklı şehirlerindeki (Mağusa, İskele, Lefkoşa ve Girne) yapılardan örnekler seçilerek incelenmesi ve toplanan verilerin analiz edilmesi ve karşılaştırılması.

Bu tez kapsamında toplam 125 örnek vaka incelenmiştir. İlk 100 vaka çalışmasında her şehirden (Mağusa, İskele, Lefkoşa ve Girne) 25 bina seçilerek betonarme kusurları ve yapısal olmayan problemler incelenmiştir. Geriye kalan 25 bina yine bu şehirlerden ve yapım aşamasındaki binalardan seçilerek sismik tasarım hataları incelenmiştir.

Anahtar Kelimeler: Bina kusurları, bozulmalar, yapısal sorunlar, sismik tasarım, Kuzey Kıbrıs.

*This thesis is dedicated To My Parents
for sponsoring my education financially*

*And To Humanity
wishing for peace, tolerance and better future for the world through science*

ACKNOWLEDGMENT

I would like to thank and record my gratitude to Asst. Prof. Dr. Giray Özyay for his supervision, advice, support and guidance in the preparation from the very early stage of this thesis. Without his invaluable supervision, all my efforts could have been short-sighted. I am indebted to him more than he knows.

I also want thank the General Secretary of the Chamber of Civil Engineers Mr. Bora Kutruza for his time allowing me to interview him for some related information and clarifications.

I am obliged and thankful to a number of my friends who had been around to help and encourage me during the period of my studies and this thesis such as Mr. Kaan Kirtiz and Ms. Teresa.

I owe quit a lot to my parents who allowed me to travel all the way from Saudi Arabia to North Cyprus and supported me financially all throughout my studies.

TABLE OF CONTENTS

ABSTRACT.....	iii
ÖZ.....	v
ACKNOWLEDGMENT.....	viii
LIST OF TABLES.....	xiv
LIST OF FIGURES.....	xv
1 INTRODUCTION.....	1
1.1 General.....	1
1.2 Literature Review and Previous Work Done.....	5
1.3 Aim and Scope.....	6
1.4 Organization of the Thesis.....	7
2 SEISMIC DESIGN FAULTS.....	9
2.1 Introduction.....	9
2.2 Strong Beam and Weak Column Problem.....	12
2.3 Structural Configuration Problems.....	13
2.3.1 Horizontal Structure Configuration Problems.....	14
2.3.1.1 Irregularities in Plan.....	14
2.3.1.1.1 Torsional Irregularity (Torsion Eccentricity).....	14
2.3.1.1.2 Floor Discontinuities.....	17
2.3.1.1.3 Projections in Plan (Re-Entrant Corners).....	21
2.3.1.2 Beams' Elementary Design Faults.....	24
2.3.1.2.1 Non-Continuous Beams.....	24
2.3.1.2.2 Non-Uniform Beam's Span and Cross-Section.....	25
2.3.1.2.3 Absence of Vertical Support at Beams' Intersections.....	26

2.3.1.2.4 Beams and Frames with Broken Axis	27
2.3.1.3 Slabs' Elementary Design Faults	27
2.3.1.3.1 Over-Stretched One-Way Slabs	27
2.3.1.3.2 Cantilever Slabs.....	28
2.3.1.4 Pounding and Separation Problems between Buildings	29
2.3.2 Vertical Structure Configuration Problems	31
2.3.2.1 Irregularities in Elevation	31
2.3.2.1.1 Inter-Storey Strength Irregularity (Weak Storey)	31
2.3.2.1.2 Inter-Storey Stiffness Irregularity (Soft Storey).....	32
2.3.2.1.3 Discontinuity of Columns or Shear Walls.....	34
2.3.2.2 Vertical Structural Elements' Elementary Design Faults	35
2.3.2.2.1 Broken Axis Columns	35
2.3.2.2.2 Irregular Column and Shear-Wall Plan Configuration.....	36
2.3.2.3 Short Column	38
3 CONCRETE AND REINFORCED CONCRETE PROBLEMS	42
3.1 Introduction	42
3.2 Corrosion of Metals Embedded in Concrete	42
3.2.1 Accelerators of Corrosion.....	43
3.2.1.1 Chlorides	44
3.2.1.2 Carbonation.....	47
3.2.1.3 Embedment of Dissimilar Metals	48
3.2.2 Corrosion-Induced Cracking and Spalling	49
3.2.3 Precautions, Prevention, Remedies and Repair	50
3.2.3.1 Precautions and Prevention.....	50
3.2.3.2 Common Remedies and Repair Methods	51

3.2.3.2.1 Patch Repair	51
3.2.3.2.2 Replacement of Reinforcement Bars.....	51
3.2.3.2.3 Strengthening by using Carbon Fiber Reinforced Polymer (CFRP)	51
3.3 Cracks Due to Drying Shrinkage (Cracks Due to Moisture Effect).....	52
3.3.1 Precautions and Prevention	53
3.4 Construction Defects Due to Faulty Workmanship	53
3.4.1 Improper Reinforcing Steel Placement	55
3.4.2 Premature Removal of Forms.....	59
3.4.3 Cold Joints	59
3.4.4 Segregation	61
3.4.5 Honeycombing	62
3.4.6 Improper Grades of Slab Surfaces.....	64
3.5 Cracks in RC Due to Load Effects (Structural Cracks).....	64
3.5.1 Slab/Beam-to-Column Shear (Punching Shear) Cracks.....	65
3.5.1.1 Precautions and Prevention.....	68
3.5.2 Cantilevered Members' Cracks	68
3.5.2.1 Precautions, Prevention, Remedies and Repair	69
3.5.2.1.1 Precautions and Prevention	69
3.5.2.1.2 Remedies and Repair.....	69
3.5.3 Problems and Cracks Associated with Foundation/Soil Settlement.....	69
3.5.3.1 Precautions, Prevention, Remedies and Repair	71
3.5.3.1.1 Precautions and prevention	71
3.5.3.1.2 Remedies and repair.....	71
3.5.3.1.2.1 Soil settlement.....	71

3.5.3.1.2.2 Cracks	72
4 NON-STRUCTURAL PROBLEMS	73
4.1 Introduction	73
4.2 Surface Defects.....	73
4.2.1 Dampness	73
4.2.2 Surface Cracks on Wall Finishes.....	78
4.2.2.1 Crazeing and Map or Pattern Cracking	78
4.2.3 Efflorescence	80
4.2.3.1 Precautions, Prevention, Remedies and Repair	81
4.2.3.1.1 Precautions and Prevention	81
4.2.3.1.2 Remedies and Repair.....	82
4.2.4 Paint Peeling.....	82
4.2.4.1 Remedies and Repair	83
4.2.5 Mouldiness	83
4.2.5.1 Precautions, Prevention, Remedies and Repair	84
4.2.5.1.1 Precautions and Prevention	84
4.2.5.1.2 Remedies and Repair.....	84
4.2.6 Staining.....	84
4.2.6.1 Precautions and Prevention.....	84
4.3 Waterproofing Defects, Water Leakage and Seepage.....	84
4.3.1 Precautions, Prevention, Remedies and Repair.....	86
4.3.1.1 Precautions and Prevention.....	86
4.3.1.2 Remedies and Repair	87
4.3.1.2.1 Repair of Water Leakage in Roof	87
4.3.1.2.2 Repair of Water Leakage in External Walls	88

4.4 Non-Structural Cracks	89
4.4.1 Joint Cracks	89
4.4.1.1 Remedies and Repair	89
4.5 Wooden Door Defects	89
4.5.1 Remedies and Repair	89
5 CASE STUDIES	90
5.1 Introduction	90
5.2 Methodology	90
5.3 Challenges and Limitations	91
5.4 Case Studies	93
5.5 Findings and Discussion.....	217
5.5.1 Sample 1: Completed Buildings	218
5.5.1.1 Building Ages of the Case Study Sample.....	218
5.5.1.2 Building Type	220
5.5.1.3 Building Status	222
5.5.1.4 Defects	224
5.5.1.4.1 Corrosion Statistics	230
5.5.2 Sample 2: Buildings Under Construction.....	231
6 CONCLUSION AND RECOMMENDATION.....	234
6.1 Conclusion.....	234
6.2 Recommendations for Future Studies	237
REFERENCES	238
APPENDIX.....	242
Appendix A: Case Study Checklist Sample	243

LIST OF TABLES

Table 1.1: Number of Buildings Constructed Between 1993 and 2014 (TRNC Statistical Yearbook 2014).....	3
Table 2.1: Local Site Classes in North Cyprus (Regulation on Buildings to Be Constructed in Earthquake Region in TRNC, 2015, p.165)	10
Table 2.2: List of Earthquakes that Hit Cyprus in the Recent Years (United States Geological Survey (USGS)).....	10
Table 2.3: Turkish Earthquake Code Expectation of Structural and Non-Structural Elements Behaviour during Different Earthquake Intensities	11
Table 3.1: Tolerable Crack Widths in Reinforced Concrete According to ACI 224R-01.....	45
Table 3.2: Suggested Chloride Ion Limits in Concrete Before Concrete Is Placed in Service According to ACI 201.2R-01	46
Table 3.3: Factors Affecting Drying Shrinkage (Emmons, 1993).....	53
Table 3.4: ACI-Required Concrete Cover for Corrosion Protection	56
Table 3.5: Primary Causes of Honeycomb	63
Table 3.6: Building Importance Factor (I) (Ministry of Public Works and Settlement, 2007, p.11)	71
Table 5.1: Relationship Between Corrosion and Age of Case Study	230
Table 5.2: Statistics for the Under Construction Case Study Group (C1-C25)	231

LIST OF FIGURES

Figure 1.1: Buildings Constructed Between the Years 1993 and 2014 (TRNC Statistical Yearbook 2014).....	4
Figure 2.1: A Comparison Between Two Frames; the Undesirable Weak Column-Strong Beam on the left and the Desirable Strong Column-Weak Beam on the right	12
Figure 2.2: A Symmetrical Structure is Modified to Illustrate Torsion and How it Causes a Building to Twist (Charleston, 2008)	15
Figure 2.3: Modifying the Centre of Rigidity/Resistance (Ozmen and Unay, 2007)	16
Figure 2.4: Location of Shear-Walls (Ozmen and Unay, 2007)	17
Figure 2.5: Diaphragm Cavities in Various Locations (Charleston, 2008).....	19
Figure 2.6: A Stepped Diaphragm (Charleston, 2008)	20
Figure 2.7: When a Building is Under the Dynamic Loads of Earthquake, Re-Entrant Corners Can Deflect in a Way Creating Possible Damage at Joints (Charleston, 2008)	21
Figure 2.8: 2007 Turkish Earthquake Code Definition of an Irregular Projections in Plan (Ministry of Public Works and Settlement, 2007).....	22
Figure 2.9: The Plan Irregularity of Re-entrant Corners can be solved by separating the structure into several blocks (Charleston, 2008).....	23
Figure 2.11: Non-Continuous Beam in a Floor Plan (Ozmen and Unay, 2007).....	24
Figure 2.12: Non-Uniform Span and Cross-Section of a Beam (Ozmen and Unay, 2007)	25
Figure 2.13: Beams Intersecting Without Vertical Supports (Ozmen and Unay, 2007)	26

Figure 2.14: Beams with Broken Axis (Özmen, 2008).....	27
Figure 2.15: Over-Stretched One-way Slab (Özmen, 2008).....	28
Figure 2.16: Cantilever Slabs (Özmen, 2008)	29
Figure 2.17: Factors Contributing in the Occurrence of Soft Story (Charleson, 2008)	33
Figure 2.18: Discontinuity of Vertical Structural Elements Irregularity (Ministry of Public Works and Settlement, 2007, P.10)	35
Figure 2.19: Broken Axis Columns (Ozmen and Unay, 2007).....	36
Figure 2.20: Irregular vs. Regular Configuration of Columns (ozmen and unay, 2007)	37
Figure 2.21: Irregular vs. Regular Configuration of Shear-Walls (Özmen, 2008)	38
Figure 2.22: Examples of Short Columns Among Longer Columns (Charleson, 2008)	39
Figure 2.23: A Way to Overcome Short on Column on Sloped Site (Charleson, 2008)	39
Figure 2.24: Short Column Occur When a Column is Partially Restricted from Deflecting Leading to Potential Damage in Form of Shear Cracking in the Unrestricted portion of the Column Under Lateral Force (Charleson, 2008).....	40
Figure 2.25: A Method of Avoiding Short Columns (Charleson, 2008)	41
Figure 3.1: Relationship Between pH of Concrete and Corrosion Rate (Emmons, 1993)	43
Figure 3.2: Corrosion Crack in the Lower Part of a Column. Mağusa, North Cyprus. (Case Study #1 (Page 93)).	45

Figure 3.3: Corrosion-Induced Spalling and Cracking Due to Cast-in Chlorides in an Abundant Old Building. Palm Beach Area, Mağusa, North Cyprus. (Case Study #23 (Page 115)).....	47
Figure 3.4: Cracks Due to Dissimilar Metal Corrosion around Handrail’s Embedded Metal Balusters of Balconies. Residential Building, Palm Beach, Mağusa, North Cyprus. (Case Study #24 (Page 116)).....	48
Figure 3.5: Cracks and spalls in concrete short walls. Public structures, Mağusa, North Cyprus.....	49
Figure 3.6: Corrosion-induced spalling (Emmons, 1993).....	49
Figure 3.7: Strengthening of the Old Bazaar by Using CFRP in İskele, North Cyprus (Naimi and Celikag, 2010).....	52
Figure 3.8: Illustrations of Improper Reinforcing Steel Placement: (a) Shifted Cage Causing Inadequate Concrete Cover. (b) Congested Reinforcement. (Emmons, 1993)	56
Figure 3.9: Shifted Reinforcing Bar Cages in: a Beam (a) and in a Sheer Wall (b). Residential Buildings, Mağusa, North Cyprus. (Case Study #111 (Page 203)).	56
Figure 3.10: Visible Voids around Reinforcements Due to High Congestion. Residential Building, Mağusa, North Cyprus. (Case Study #104 (Page 196)).	58
Figure 3.11: Illustration of Premature Removal of Forms (Emmons, 1993).....	59
Figure 3.12: Cold Joints in Columns. Residential Buildings, Mağusa, North Cyprus. (Case Study #111 (Page 203)).	60
Figure 3.13: Cold Joint in Column. Residential Buildings, Mağusa, North Cyprus. (Case Study #104 (Page 196)).	60
Figure 3.14: Cold Joint Between Column and Slab. Residential Buildings, Mağusa, North Cyprus. (Case Study #111 (Page 203)).....	61

Figure 3.15: Illustration of Segregation (Emmons, 1993)	61
Figure 3.16: Honeycomb in a Column. Residential Building, Mağusa, North Cyprus. (Case Study #104 (Page 196)).	62
Figure 3.17: Improper Grades of Slab Surfaces (Emmons, 1993).....	64
Figure 3.18: Illustration of Punching Shear (Sacramento et al., 2012, p. 594).....	66
Figure 3.19: Plan View of Punching Shear Cracks in a Test Specimen at University of Waterloo, Ontario. (Curtis, 2013).....	66
Figure 3.20: Some Methods of Increasing Punching Shear Resistance.....	67
Figure 3.21: Punishing Shear Reinforcement http://www.bpress.cn/ex/tag/PEIKKO/	67
Figure 3.22: Illustration of Cracks in Cantilevered Slab (Emmons, 1993)	69
Figure 2.23: Before (on the left) and After (on the right) the Treatment Using Resin Injection at Social Security Organisation (SOCISO) Building in Penang, Malaysia (Suffian, 2013).	72
Figure 4.1: Dampness on the Upper Section of the Wall Due to Rain Penetration. Civil Engineering Department, Eastern Mediterranean University (EMU), Mağusa, North Cyprus.....	77
Figure 4.2: Dampness on The Lower Part of Second Floor Walls Due to Wet Floors Caused by Frequent Floor Washing Using Too Much Water Which Can Be Mistaken Easily as Rising Damp. Akdeniz Gormitory, Eastern Mediterranean University (EMU), Mağusa, North Cyprus.	77
Figure 4.3: Map cracking on the Column of the Top Floor That Led to the fall of some of the Paint Cover. English Preparatory School, Eastern Mediterranean University, Mağusa, North Cyprus.	80

Figure 4.4: Efflorescence on Concrete Surface. http://www.docfoc.com/concrete-cast-in-place-flat-grey-efflorescence	81
Figure 5.1: Pie Chart Showing the Statistics for Ages of the Case Studies.....	218
Figure 5.2: Pie Chart Showing the Statistics for Building Types of the Case Studies	220
Figure 5.3: Pie Chart Showing the Statistics for Status of the Case Studies (Whether Occupied or Abandoned) and the Ages of Abandoned Buildings for Mağusa, İskele and Lefkoşa Districts	222
Figure 5.4: Pie Chart Showing the Statistics for Status of the Case Studies (Whether Occupied or Abandoned) and the Ages of Abandoned Buildings for Girne District and Overall.....	223
Figure 5.6: Bar Chart Showing the Occurrence of Defects in Mağusa District (M1-M25).....	224
Figure 5.7: Bar Chart Showing the Occurrence of Defects in İskele District (İ1- İ25)	225
Figure 5.8: Bar Chart Showing the Occurrence of Defects in Lefkoşa District (L1-L25).....	226
Figure 5.9: Bar Chart Showing the Occurrence of Defects in Girne District (G1-G25)	227
Figure 5.10: Bar Chart Showing the Overall Occurrence of Defects (M1-M25, İ1-İ25, L1-L25 and G1-G25).....	228
Figure 5.11: Bar Chart Showing the Statistics for the Under Construction Case Study Group (C1-C25).....	232

Chapter 1

INTRODUCTION

1.1 General

Since the dawn of mankind, humans lived in various types of homes. Buildings are very important for sustaining life. Defected buildings can cause problems to its occupants. In earthquake regions these problems may result in injuries or even worst; death. It is a natural desire wanting to be safe in our homes.

There are several types of structural systems, construction methods and building materials used around the world. The types of structures and construction methods used in any country depend not only on availability of material but also soil type, weather conditions, infrastructure, availability of professionals and workers to carry out required tasks.

In North Cyprus, RC skeletons are the most common structural system constructed using conventional methods and bricks as infill walls. Furthermore, the most common surface finishing practice is 3-layer plastering using cement sand based plaster (gypsum is used as the 3rd layer sometimes) before carrying on painting. Reinforced concrete structures started to become more popular in North Cyprus since mid-1960s. From late 1970 till today the conventional reinforced concrete structures are still dominating building construction in Cyprus. Steel framed buildings are rarely found as their number is so far less than 5% of all the buildings in North

Cyprus. Steel as a material is not available locally but imported mainly from Turkey and mainly used for industrial buildings. Therefore steel structure and other locally rarely found building materials are excluded from this thesis as they are not common in North Cyprus.

Currently TS 500 (Turkish Reinforced Concrete Design Code, 2000) is commonly used for reinforced concrete structures design in North Cyprus. The concrete grade used in North Cyprus is minimum C20 (20 N/mm²). Therefore, it is critical to take into consideration any defects or factors that could reduce the compressive strength of concrete members or alternatively increase the design load in concrete members particular when subjected to earthquake forces.

The functions of the buildings found in North Cyprus range between industrial, military, commercial, residential, public and educational buildings. However, this investigation is focused on mainly residential and some commercial buildings.

The prevailing heights of buildings of North Cyprus are normally ranged between low to medium rise. Table 1.1 and Figure 1.1 show the statistics of the number of buildings constructed in North Cyprus between the years 1993 and 2014. In the recent years there has been a construction boom in North Cyprus. The local construction industry was not ready for such increase in demand. The lack of enforcement of the existing rules and regulations are added to the poor supervision on site and increased number of inexperienced labour working for unqualified contractors result in a significant drop in the quality of buildings.

Table 1.1: Number of Buildings Constructed Between 1993 and 2014 (TRNC Statistical Yearbook 2014)

		District					Total	
		Lefkoşa	Mağusa	Girne	Güzelyurt	İskele		
Year	1993	Urban	76	42	79	-	-	520
		Rural	134	114	75	-	-	
	1994	Urban	44	50	48	-	-	509
		Rural	187	85	95	-	-	
	1995	Urban	52	79	56	-	-	610
		Rural	167	107	149	-	-	
	1996	Urban	30	68	104	-	-	578
		Rural	99	114	163	-	-	
	1997	Urban	76	160	52	-	-	835
		Rural	174	204	169	-	-	
	1998	Urban	110	161	52	-	-	782
		Rural	147	146	166	-	-	
	1999	Urban	55	121	116	-	-	780
		Rural	186	154	148	-	-	
	2000	Urban	45	136	109	17	18	794
		Rural	150	80	139	63	37	
	2001	Urban	43	278	67	32	48	761
		Rural	84	40	84	39	46	
	2002	Urban	45	95	60	21	14	651
		Rural	157	58	86	32	83	
	2003	Urban	63	115	108	5	21	845
		Rural	179	75	190	53	36	
	2004	Urban	109	147	95	17	112	1,149
		Rural	169	67	331	46	56	
	2005	Urban	80	176	84	10	127	1,597
		Rural	215	116	647	32	110	
	2006	Urban	229	221	123	27	102	2,395
		Rural	320	137	995	55	186	
	2007	Urban	205	253	230	42	57	2,805
		Rural	389	186	1,178	76	189	
	2008	Urban	170	315	157	28	55	2,847
		Rural	432	181	1,217	83	209	
2009	Urban	245	227	117	18	103	2,470	
	Rural	346	140	1,013	58	203		
2010	Urban	297	247	140	21	114	2,479	
	Rural	348	141	906	56	209		
2011	Urban	289	155	89	76	149	2,618	
	Rural	424	227	967	58	184		
2012	Urban	136	178	90	54	93	2,127	
	Rural	339	241	822	52	122		
2013	Urban	168	165	247	63	91	2,559	
	Rural	460	509	754	48	54		
2014	Urban	310	141	137	65	85	2,416	
	Rural	354	445	766	5	108		
Overall Total		8,337	7,097	13,420	1,252	3,021	33,127	




Figure 1.1: Buildings Constructed Between the Years 1993 and 2014 (TRNC Statistical Yearbook 2014)

Non-structural defects and deteriorations in buildings have negative effects both on human and building lives. They mostly harm to the health and economy causing relevant socioeconomic harm to individuals and companies associated with the construction industry. Besides, reducing buildings' efficiency and aesthetic quality. On the other hand, structural problems develop risks leading to injuries or casualties. Most of these problems can be detected at their early stages through visible evidences. If not immediately treated, minor problems can grow into severe ones, becoming more expensive to repair, leading to failure or sudden collapse and jeopardizing lives.

Defects take place in numerous patterns and to various intensities in all sorts of structures of all ages. Mostly, these defects or structural problems arise due to error or omission that is breach of contract or negligence by designer/detailer, contractor, or user. In general, lack of care and knowledge in specification or workmanship are

the main reasons of various defects and structural problems. On the other hand, deterioration is natural process, which may be unavoidable, although minimized by care in design and the selection of materials and regular maintenance. Cracks, efflorescence, peeling on painting, mouldiness, rising dampness, soft storey, short column, shear cracks, compression cracks, irregularities in plan, irregularities in elevation and etc. are some of the most significant problems that occur in building of Northern Cyprus.

This thesis investigates the defects and problems of buildings and structures in North Cyprus. Reasons of these defects and problems were identified together with their most common precautions and available applied methods for preventing or reducing these problems. Selected case studies in different cities of North Cyprus were investigated, analysed and compared.

1.2 Literature Review and Previous Work Done

Various studies have been done on structural configuration design flaws and in describing building defects' symptoms and classifying them in deferent ways. Besides investigated their sources and proposing remedies and ways of prevention.

Suffian (2013) expressed the importance of maintenance role on building defects by examining a number of Social Security Organization (SOCSO) buildings across Malaysia. Celikag and Ozbilen (2007) examined over 100 construction sites in North Cyprus and to identify construction defects and inadequacies. Naimi and Celikag (2010) investigated 14 buildings in Mağusa, North Cyprus devided into 2 groups: under-construction, recently constructed and old buildings to indentify their defects and their reasons. Celikag and Naimi (2011) identified variety of construction

problems in North Cyprus and promoted for the use of alternative construction system (steel structure). Sassu and De Falco (2014) collected and reported data of defects from buildings in Italy and classified them according to various categories based on the type of damage encountered and carried out a comparison statistical study. Ozmen and Unay (2007) wrote about and gatogorized comonly encountered seismic design faults of residential buildings in Turkey. Ozay and Ozay (2005) discussed in their article the most common defects on housing surfaces in Northern Cyprus.

Emmons (1993) illustrated and classified concrete defects and described their causes together with their repair technique. Charleson (2008) wrote and illustrated about seismic design. Trotman, Sanders, and Harrison, (2004) explained and illustrated in their book about dampness and its effects, causes, diagnosis and remedies.

Chin-man (2002) publish a Building Maintenance Guidebook under the national Codes of Practice, Design Manuals and Guidelines of Hong Kong when he describes the symptoms, causes and common appropriate solutions of buildings' defects in Hong Kong.

1.3 Aim and Scope

The dissemination of failure-related information, with detailed description of their causes, mainly for civil engineers and architects, is necessary for developing awareness on the building construction process and preventing further failures.

The aim of this thesis is to identify, highlight and help to provide knowledge and awareness about building defects and problems due to design and construction faults to construction professionals such as engineers and architects in order to resolve and

avoid these problems through proper design, construction process and quality control for RC structures.

This thesis investigates various common defects and problems in RC buildings of different ages together with their causes and ways of avoiding them. Selected case studies in North Cyprus were visited to identify inadequacies in building design and construction.

1.4 Organization of the Thesis

The first chapter of this thesis starts with a general introduction by defining the problem, describing the regional construction practice and urban context of North Cyprus. Published previous work done related to the topic of building defects both structural and non-structural were reviewed. The aim of the study were stated and the scope were defined.

Chapter 2 starts by presenting a category of structural problems which is related to earthquake and designing, namely: seismic design faults. The title is then divided and subdivided into various problem types in the following sections. The second section is concerned about weak column-strong beam problem. While the third section is about horizontal and vertical structural configuration problems, such as: irregularities in plan and elevation, elementary design faults about structural members and short column.

Chapter 3 describes the types of defects which occur in concrete and reinforce concrete which is the dominant material used for the construction in North Cyprus together with their precautions, prevention, remedies or repair if available. After the introduction section, the second section is concerned about corrosion of metals

embedded in concrete and the accelerators of such corrosion together with the accompanied consequences of cracks and spalls. The third section describes drying shrinkage cracks or cracks due to moisture effects. The fourth section is concerned about construction defects particularly those due to faulty workmanship of designers, detailers or contractors, e.g., improper reinforcing steel placement, premature removal of forms, cold joints, segregation, honeycombing and improper grades of slab surfaces. The fifth and last section is concerned about structural cracks in concrete, i.e., cracks due to load effects, e.g., punching shear cracks, cantilevered member's cracks and settlement cracks.

Chapter 4 describes the non-structural defects, such as: waterproofing defects, defected wooden doors and non-structural cracks, e.g., joint cracks. Besides, common surface defects, e.g., dampness, efflorescence, paint peeling, mouldiness, staining and wall finished workmanship problems.

Chapter 5 is the case studies chapter. It starts with brief introduction followed by defining the methodology of the carried investigation and the faced challenges and limitation of the investigation before presenting the case studies and ending by presenting the findings and discussing the results.

The conclusion chapter starts with a highlight and summary of the problem, causes and solutions. Followed by recommendation for the construction and maintenance practice for the buildings of North Cyprus.

Chapter 2

SEISMIC DESIGN FAULTS

2.1 Introduction

Natural disasters, e.g. earthquakes, can expose flaws in the design of structures. Flaws in design, conceptual planning or in some cases an inefficient system of codes and regulation may lead to disastrous results in urban contexts. Seismic design faults negatively affect the seismic performance and structural behaviour of buildings.

During the last century there has been fast progress in design standards and construction methods. Introduction of earthquake codes for structural design helped researchers and engineers to design buildings for more realistic loads. North Cyprus contains earthquake zones 2 and 3 only (Table 2.1). There are a number of tremors throughout the year some of which are high in magnitude. Cyprus has been hit in the recent years by earthquakes of magnitude up to 6.8 (Table 2.2). Therefore it is necessary when designing structures to take into account earthquake loads and pursuit achieving quality design and work to increase the safety of structures and their occupants.

Table 2.1: Local Site Classes in North Cyprus (Regulation on Buildings to Be Constructed in Earthquake Region in TRNC, 2015, p.165)

Municipality	Earthquake Zone
Akdoğan	2
Akıncılar	2
Alayköy	3
Alsancak	3
Beyarmudu	2
Büyükkonuk	3
Çatalköy	3
Değirmenlik	3
Dikmen	3
Dipkarpaz	3
Esentepe	3
Mağusa	2
Geçitkale	3
Girne	3
Gönyeli	3
Güzelyurt	2
İnönü	3
İskele	3
Lapta	3
Lefke	2
Lefkoşa	3
Mehmetçik	3
Paşaköy	3
Serdarlı	3
Tatlısu	3
Vadili	2
Yeni Boğaziçi	3
Yeni Erenköy	3

Table 2.2: List of Earthquakes that Hit Cyprus in the Recent Years (United States Geological Survey (USGS))

Date	1995/2/23	1996/10/9	1999/8/11
Magnitude	5.9	6.8	5.6

Before 1982 earthquake resistant structural analysis for building of up to four stories was not obligatory and could be skipped if the structural elements were buffed or if a certain configuration of shear walls were provided. The 1975 version of Turkish earthquake code was the first earthquake code to be followed in North Cyprus (in the early 1990s) followed by the 1997 version before North Cyprus having its own earthquake code in 2005 which is basically an adapted 1997 Turkish Earthquake Code. Hence, the majority of old buildings were not designed to withstand realistic earthquake loads and some may need strengthening.

The main goal for any earthquake code is the prevention of casualties. Table 2.3 below shows what the Turkish Earthquake Code expects for the structural and non-structural elements of a building to behave during different earthquake intensities (Ministry of Public Works and Settlement, 1997, 2007).

Table 2.3: Turkish Earthquake Code Expectation of Structural and Non-Structural Elements Behaviour during Different Earthquake Intensities

Small earthquake	Medium earthquake	Strong earthquake
No damage	Damage should be within repairable limits	No partial or total collapse

This chapter attempts to contribute to the effort of raising an awareness about the concept of earthquake resistant design and explores the design flaws that are made by designers.

2.2 Strong Beam and Weak Column Problem

The aim of seismic design is to prevent building collapse in an event of an earthquake. This can be achieved by absorbing the earthquake energy through ductile hinges at the joints between columns and beams. In weak column-strong beam frames, hinges form at column ends. While in strong column-weak beam frame, hinges form at beam ends. Figure 2.1 below compares between the undesirable weak column-strong beam frame (Figure 2.1a) and the desirable strong column-weak beam frame (Figure 2.1b). The basic idea behind adopting the strong column-weak beam method is to avoid columns failing first, losing a beam is less dangerous than losing a column. Therefore, weak column-strong beam designs are prohibited by all codes and must be avoided. Column depths must never be less than those of the beams in order to avoid strong beam-weak column problem and achieve the seismically desirable frames ductility.




Figure 2.1: A Comparison Between Two Frames; the Undesirable Weak Column-Strong Beam on the left and the Desirable Strong Column-Weak Beam on the right

2.3 Structural Configuration Problems

Configuration in structural design means the horizontal and/or vertical arrangement of structure and its elements. The seismic performance of a building configuration is the combination the seismic performance of all individual structural members with it. The structural configuration quality determines the survivability of a building after an earthquake.

Building configuration is mainly the responsibility of designers because designers decides on the overall scheme of a structure. The approach towards regularity and symmetricity of plans and elevations should be adopted by designers while designing any building. Buildings are classified into regular and irregular buildings. Designers should always aim for regularity by minimizing or eliminating irregularities. Irregularities lead to unfavourable seismic behaviour. Irregularities are also uneconomical since codes ask for structural members of irregular buildings to be stronger than ordinary. The American Institute of Civil Engineers standard ASCE/SEI 7-05 (2006) forbids the construction of irregular buildings in high seismicity regions.

Irregularities increases the chance for a structural and non-structural damage during an earthquake. However, by implementing advanced engineering techniques some little to medium irregularities can be tolerated by structural engineers and design codes. Normally the structural designer builds a 3D digital model of buildings with irregularity before applying code-specified seismic forces into it. This topic is subdivided in the followings into horizontal and vertical structure configuration problems.

2.3.1 Horizontal Structure Configuration Problems

Horizontal structure is a crucial part of any earthquake force path since earthquake forces travel horizontally first through horizontal structure before traveling vertically downwards all the way to the foundations. Every building needs a horizontal structure which resists and circulate earthquake forces into columns and shear walls. For that reason, the description of horizontal structure always goes before vertical structure in almost every seismic design related literature.

In general, the best method to approach an adequate horizontal configuration is to reduce the complexity of floor plan geometry by dividing it into regular shapes using seismic separation gaps. This section is concerned about horizontal configuration, i.e., floor plan shapes and its structural layout in plan. This section is subdivided in the followings into these subtopics: irregularities in plan, elementary design faults in beams and slabs.

2.3.1.1 Irregularities in Plan

In 2007 Turkish Earthquake Code, irregularities in plan are ordered as: torsional irregularity, floor discontinuities and projections in plan.

2.3.1.1.1 Torsional Irregularity (Torsion Eccentricity)

To minimize torsion in buildings during earthquake, it should be taken into consideration by designers when designing floor plans to minimize the distance between the centre of mass and the centre of rigidity or resistance as much as possible (making them coincide is the best scenario). Distance between centre of mass and centre of rigidity creates eccentricity and as a sequence, a torsion moment equal to the inertia force (lateral earthquake force) multiplied by eccentricity twists the building around the centre of rigidity. Efforts must be made to prevent torsion. If a structure twists, the columns furthest away from the centre of rigidity endure the

most damage caused by excessive torsion-induced horizontal deflections. The location of the centre of mass usually influenced by the geometrical centre of the floor plan and therefore not convenient to manipulate; on the other hand, the location of the centre of rigidity/resistance can be manipulated by modifying the cross-sections (stiffness) and the locations of vertical structural members (Figure 2.2).

Figure 2.2a shows an ideal situation of a perfectly symmetrical plan where the centre of rigidity and centre of mass coincide, thus zero eccentricity exist. Figure 2.2b shows how increasing the size of columns on one side on a plan shifts the centre of rigidity and thus creating eccentricity. Figure 2.2c shows how the columns furthest away from the centre of rigidity endure the most deflection and thus damage.




Figure 2.2: A Symmetrical Structure is Modified to Illustrate Torsion and How it Causes a Building to Twist (Charleson, 2008)

The uniform earthquake force acting on the floor plan is simplified to a point force acting at the centre of mass. This horizontal forces is resisted by columns and shear walls. In general, in both direction x and y, the length of eccentricity should be kept less than quarter the length of the structure measured perpendicular to the direction of earthquake force (Charleson, 2008).

Ozmen and Unay (2007) illustrated in an asymmetrical floor plan example the possibility of moving the centre of resistance closer to the centre of mass in order to minimize the torsion eccentricity and the resultant shear forces by the addition of shear-walls (Figure 2.3).




Figure 2.3: Modifying the Centre of Rigidity/Resistance (Ozmen and Unay, 2007)

Lift cores or staircases enclosed in shear walls should be located in a way to eliminate or minimize the distance between the centres of mass and the centre of rigidity/resistance. Locating them on one side of the structure will create excessive torsion eccentricities and unequal deflections (Figure 2.4a). They should be

distributed symmetrically across the plan or placed at the centre of the building (Figure 2.4b) (Ozmen and Unay, 2007).




Figure 2.4: Location of Shear-Walls (Ozmen and Unay, 2007)

According to the 2007 Turkish Earthquake Code, a building is considered torsionally irregular if the ratio of the maximum displacement to the average displacement for any of the two orthogonal earthquake directions at any storey is more than 1.2 in the same direction. In any torsionally irregular building where the rigidity is not symmetrically distributed, the less rigid portion of the structure will do more shift (and damage) than the more rigid portion.

2.3.1.1.2 Floor Discontinuities

Cavities in floor plans serve variety of purposes, such as:

- To provide stairs, escalators or lifts.
- Air ventilation or light cavity purposes.
- Spatial comfort and aesthetics purposes.
- Building services cavities, such as; air ducts and pipes.

The lateral inertia forces on the structure are distributed to vertical structural members by the floor slabs. Large cavities within floor plans ruin their structural integrity. Thus, designers should locate them in a way that they will not endanger the diaphragm's ability to transfer horizontal loads to columns or shear-walls. Any interruption on the earthquake force path must be avoided. Thus, the optimal locations for cavities are where bending moments or shear stresses are low. Figure 2.5d shows a cavity located in minimum shear stress area. Generally, the following two principles should be considered by designers when locating a floor slab cavity:

- The cavity should not cut through a chord or beam (Figure 2.5a). If cavity location cannot be adjusted, then the edge beam must continue through the cavity to restore continuity of the diaphragm chord (Figure 2.5b). The Cavity in Figure 2.5d is in the centre of the floor plan safely away from beams which carry tension and compression stresses.
- Placement of a cavity should not be located on areas of maximum shear forces as shown in Figure 2.5c. There are 2 ways that can be implemented to prevent undesirable shear failure mode in this case:
 - a) The length of Cavity must be shortened.
 - b) The depth of floor slab or/and beams must be increased and far more heavily reinforced in those areas.




Figure 2.5: Diaphragm Cavities in Various Locations (Charleson, 2008)

The 2007 Turkish Earthquake Code consider a building to be irregular by floor discontinuity if the total area of openings exceed third of gross floor area. Cavities introduce potential weakness into diaphragms and could negatively affect the dynamic behaviour of the building as there will be uneven horizontal deflections leading to additional shear stresses. The following are some options and methods that can be applied when designing Cavities in floor plans to reduce and overcome their negative effects:

- Increasing the rigidity of the columns and beams surrounding the opening.
- Positioning shear-walls around the openings.
- Reducing the dimensions of openings.
- Thickening and reinforcing the surrounding of an opening.

- Bridging the opening slot by introducing a section of diagonal steel framing or inserting horizontal vierendeel frame.
- Separating the structure into portions/sections (independent structures) with the cavity between them.

Another type of diaphragm discontinuity is when a floor diaphragm consists of two or more levels. Figure 2.6 illustrates this scenario and shows a step in a diaphragm.




Figure 2.6: A Stepped Diaphragm (Charleson, 2008)

Two ways to overcome this type of discontinuity:

- Divide the structure into two independent structures
- Introduce a shear-wall or moment frame, depending on the existing structural system, along the line of the step.

2.3.1.1.3 Projections in Plan (Re-Entrant Corners)

Projections in plan can be in many geometry shapes (Figure 2.8). If these projections are too large they impose possibility for damage due to the different dynamic responses of each projection which leads to additional stresses on the structure (Figure 2.7). During an earthquake, the more flexible wing, depending on the direction of inertia force, swings about the stiffer area (torsional rotation effect) which may result in:

- Damage in diaphragm joint between projections, due to critical shear forces and moments occurring in the intersection line of the projection and the main body.
- Damage in the far end columns of the more flexible wing, due to torsion eccentricities.




Figure 2.7: When a Building is Under the Dynamic Loads of Earthquake, Re-Entrant Corners Can Deflect in a Way Creating Possible Damage at Joints (Charleston, 2008)

Codes require undertaking a 3D dynamic analysis for buildings with re-entrant corners. Most codes define projections in plan irregularity as where the ratio of the length of a projecting corner to the length of the entire plane exceeds 15% in the

same. However, in the 2007 Turkish Earthquake Code the ratio is set to 20% (Figure 2.8).




Figure 2.8: 2007 Turkish Earthquake Code Definition of an Irregular Projections in Plan (Ministry of Public Works and Settlement, 2007)

If re-entrant corners are necessary, there are two ways to design them as to avoid diaphragm tearing and excessive horizontal deflections damaging columns:

- Balancing the projections' relative stiffness by playing with shape and reinforcements. Nevertheless, this method might not be structurally sound, if the wings are long or if the diaphragm is weakened by cavities where the projections join.
- The common and most preferable solution method which should be applied for re-entrant corner buildings whenever possible is to divide and separate the structure into independent structures or sections with structural joints in between (Figure 2.9).




Figure 2.9: The Plan Irregularity of Re-entrant Corners can be solved by separating the structure into several blocks (Charleson, 2008)

2.3.1.2 Beams' Elementary Design Faults

2.3.1.2.1 Non-Continuous Beams

Designing non-continuous beams in floor plans should be avoided. When having a non-continuous beam, the lateral earthquake inertia force within this beam is transferred to the structural elements in the opposing side through the relatively thin floor slab (Figure 2.11). Calculating the pattern and the effects of this force distribution is complicated. The lateral displacement properties of the entire structure should always be considered by the designer. Two design approaches which increase the rigidity of the slab that could be applied if such configuration is absolutely necessary (Ozmen and Unay, 2007):

- Increasing the slab thickness between the non-continuous beam.
- Using joist slab between the non-continuous beam.




Figure 2.11: Non-Continuous Beam in a Floor Plan (Ozmen and Unay, 2007)

2.3.1.2.2 Non-Uniform Beam's Span and Cross-Section

Designers should avoid non-uniform beam's span and cross-section. Non-uniform spans of beams will vary the lateral rigidity of the diaphragm. Furthermore, these changes in span lengths are often accompanied with alternation of beam cross-section; with the longer spanning beam having greater depth and the shorter spanning beam having less depth, due to varying imposed loads on them. These non-uniformities makes it difficult to estimate critical stresses and difficult to predict the behaviour of the building during an earthquake. Moreover, there will be an increase in the cost of formworks due to non-uniformity (Özmen, 2008). Besides, complications in the details of steel bars reinforcements and difficulties in producing them (Figure 2.12). However, variations of beam spans could be acceptable if the design is symmetrical in plan. Yet, care should be taken in minimizing eccentricities in joints of beams with different cross-sections. If the joint is not properly reinforced, failure can easily occur at the joint.




Figure 2.12: Non-Uniform Span and Cross-Section of a Beam (Ozmen and Unay, 2007)

2.3.1.2.3 Absence of Vertical Support at Beams' Intersections

In some designs, vertical load-bearing member at beam-to-beam intersection are either absent or shifted (Figure 2.13). This could be dangerous under horizontal earthquake inertia forces since one beam will be exposed to a large point load from another at the intersection generating critical moments which may lead to large deflections and cracks on the beams. Furthermore, such a configuration would require additional reinforcements and a big increase in the beam cross-section, therefore increase in the cost. When such a configuration cannot be avoided, the intersection point should not be close to the column/shear-wall (Figure 2.13b). One should remember that stiffness is negatively proportional with the length of the element. The short beam shown in Figure 2.13b can create very critical torsion moments on itself and the adjacent beam and column (Özmen, 2008).




Figure 2.13: Beams Intersecting Without Vertical Supports (Ozmen and Unay, 2007)

2.3.1.2.4 Beams and Frames with Broken Axis

Breaking the axis of beams and columns in plans makes them less resistant to lateral forces as additional torsion forces will develop during force transferring between them (Figure 2.14a). The configuration shown in Figure 2.14b forms a short and over-rigid beam, thus should be avoided (Özmen, 2008).




Figure 2.14: Beams with Broken Axis (Özmen, 2008)

2.3.1.3 Slabs' Elementary Design Faults

2.3.1.3.1 Over-Stretched One-Way Slabs

Sometimes when designing central long corridors for circulation purpose in multi-storey buildings, designers use over-stretched one-way slabs. This over-stretched one-way slabs are created by omitting the beams below the corridors to avoid visual or service obstacles in the ceiling of the corridor below. Thus, breaking the continuity of the structural axes which leads to structural deficiencies (Figure 2.15). Designers should avoid such a design by not omitting beams and adding suspended ceilings to overcome and hide visual and service problems without sacrificing

structural integrity. Over-stretched one-way slabs break the continuity of beams which leads to non-continuous beams design fault explained earlier.

Over-stretched one-way slab creates an area of weekend rigidity within the diaphragm that transfers lateral earthquake inertial forces to vertical structural elements. Therefore, relatively large deflections can easily occur under lateral earthquake inertial forces. Moreover, since it is difficult to place reinforcement in the long direction of such a long slab, frequent contraction cracks will occur (Özmen, 2008).




Figure 2.15: Over-Stretched One-way Slab (Özmen, 2008)

2.3.1.3.2 Cantilever Slabs

Cantilever projections in RC buildings are either open as in balconies or enveloped by masonry to act as extension for rooms. If the projection of cantilevered slab is long, it is prone to large deflection even without earthquake lateral inertia loads. Enveloped cantilevers are more prone to critical deflections than open cantilevers especially under earthquake forces due to the weight of the masonry wall positioned at the far end of the cantilevered slab, which may result in partial collapse. While

designing cantilevered projections, it is best to have four beams under the cantilevered slab as following (Figure 2.16):

- Two cantilevered beams which should be continuous and
- Two side beams one of them under the far end of the cantilevered slab and the other connecting the columns supporting the cantilever.

This way increases the overall rigidity of the cantilever. Besides, the earthquake lateral inertia forces will be transferred directly to the supporting columns without being distributed to the relatively less rigid floor slabs (Özmen, 2008).




Figure 2.16: Cantilever Slabs (Özmen, 2008)

2.3.1.4 Pounding and Separation Problems between Buildings

The shape of the building and its mass distribution influences its seismic behaviour. Complex buildings with irregular mass distribution, like those consisting of large numbers of blocks, will have varying natural periods and lateral rigidities between its block, each block will behave independently during an earthquake. As a result, critical torsions and shear stresses will develop at the regions where they join. Therefore, to solve this problem and accomplish a successful seismic behaviour of

such complex buildings, each block have to be divided into structurally independent sections. The blocks should be disconnected from one another by separation joints, which can be designed in multiple styles.

Irregular distribution of masses can take place within a building in multiple ways. A structure can appear to be regular from outside but additional masses of building services, such as heavy machines and water tanks can develop torsion eccentricities and additional shear stresses depending on where they are located within a building. Projections in Plan (Re-entrant corners), projections in elevation (cantilevers) and setbacks are another patterns of irregular mass distribution frequently detected in residential buildings. Especially, if they were not symmetrical around the centre of the structure as they will cause torsion eccentricities.

On the other hand, some urban residential building patterns contains buildings very close to each other which could be very dangerous during an earthquake and should be avoided. Every building will swing differently during an earthquake according to its own natural period. Therefore, buildings should be located after setbacks of their boundary except street frontage in order to achieve some gaps between them. The drift of a building during an earthquake should not reach the neighbouring site boundary. If there are no adequate separation between the buildings and they swing toward each other, they will hit each other which could critically damage or destroy structural elements leading to a collapse or partial collapse.

The amount of spacing between buildings is calculated on the flexibility and height of a building. The required gap obviously increases with height. On the other hand, to avoid uneconomical wide gaps, stiff structural system could be adopted in the

design. The maximum allowed drift of a building during an earthquake is specified in typical codes as $0.02 \times$ height. Some codes allow a 50% reduction of the spacing with the condition that the floor levels of adjacent buildings align, since pounding a floor slab into a floor slab is not as dangerous as a floor slab hitting columns or shear-walls of the adjacent building. The minimum spacing requirement between buildings specified by the 2007 Turkish Earthquake Code is 30 mm for buildings up to a height of 6m. From there on, the spacing should be increased 10 mm for every 3 m raise in the height. However, even if these suggestions of the code are followed, sometimes it could still be inadequate. The adequacy of spacing should be checked and confirmed by calculations or computer simulation (Ozmen and Unay, 2007). Separation gaps are usually lined and covered using flexible sacrificial materials to allow movements, as trying the separated structures should be avoided (Charleston, 2008).

2.3.2 Vertical Structure Configuration Problems

This section is subdivided in the followings into these subtopics: irregularities in elevation, elementary design faults in vertical structural elements and short column.

2.3.2.1 Irregularities in Elevation

In 2007 Turkish Earthquake Code, Irregularities in elevation are: inter-story strength irregularity (weak story), inter-storey stiffness irregularity (soft storey), and discontinuity of vertical structural elements.

2.3.2.1.1 Inter-Storey Strength Irregularity (Weak Storey)

Weak storey occurs when omitting or reducing the cross section area of columns, shear walls and masonry partition walls of the storey immediately bellow. Weak storey can occur at any storey level (except top storey level), but it most commonly

occurs in ground storey level. This is because a lot of medium-rise apartment building in North

Cyprus are designed with an open ground storey to function as parking. Masonry partition walls contribute to the resistance of earthquake force together with columns and/or shear walls. Therefore omitting masonry partition walls in a story make it weaker than the storeys above and as a result higher stresses are imposed on the columns of the weak storey which might lead to failure during an earthquake.

The 2007 Turkish Earthquake Code specifies for a storey to be weak is when the ratio of the sum of cross section area of columns and shear walls and 0.15 of masonry partition walls of a storey to the storey immediately above is less than 0.8.

It is best to design continuous masonry partition walls and not to omit them on lower storeys, but if an open storey is unavoidable and the ratio is between 0.8 and 0.6, then the columns and/shear walls of the weak storey must be buffed while taking into consideration that the cross section area of columns and/or shear walls in a storey should never be greater than the storeys below). However, if the ratio is less than 0.6, the codes prohibits such a design and redesigning shall be carried (Turkish Earthquake Code, 2007).

2.3.2.1.2 Inter-Storey Stiffness Irregularity (Soft Storey)

Soft storey irregularity is much the same as weak storey irregularity. It occurs when a level in a structure is more flexible and/or weaker than the level immediately above. However in soft storey irregularity, average story drift is in concern rather than the storey effective shear area which is linked to weak story irregularity. Soft storey occurs commonly in on ground floors in residential building in North Cyprus, which are functioning as shopping stores or more commonly as car parking. The danger of

such irregularity is that earthquake energy will concentrate on this weaker soft storey, which will cause serious damage to the storey's columns leading to collapse. The followings are three factors that contribute in the occurrence of soft story in floors (Ozmen and Unay, 2007):

- I. Relative absence of masonry infill walls in one of the floors (Figure 2.17a). Masonry infill walls contribute in the lateral rigidity of a floor, omitting them in a floor, such as in the case of ground floor car parking, would subject its columns to a significant increase in moment and shear forces (this cause both weak and soft storey).
- II. Increasing the height of the floor than the height of the floors above without decreasing the columns cross-section of those on the floors above (Figure 2.17b). The lateral rigidity of the floor will be less than of those above and thus its drift will be more (this cause soft storey only).
- III. Omitting columns or shear-walls in a lower floor (non-continuous column or shear-wall) (Figure 2.17c). It is more critical in lower floors such in the case of ground floor which would subject its columns to very critical shear stresses (this cause both weak and soft storey).




Figure 2.17: Factors Contributing in the Occurrence of Soft Story (Charleson, 2008)

According to Charleson (2008) this irregularity is the most serious among irregularities in elevation and it is the most prevalent cause for multi-storey buildings collapses. A seismic code may tolerate some reasonably minor degree of soft storey. However, special analyses must be undertaken with additional strength and ductile detailing.

The 2007 Turkish Earthquake Code specifies for a storey to be soft is when the ratio of average storey drift at a storey to the storey immediately above or below is greater than 2.

2.3.2.1.3 Discontinuity of Columns or Shear Walls

In some old designs, columns or shear-walls are omitted in some floors due to spatial, functional or aesthetical purposes. A beam could support the load of a column, but it would be uneconomical as it will need a relatively huge beam dimensions since the 2007 Turkish Earthquake Code requires a 50% increase of the design loads of the beam supporting the column and the other beams and columns neighbouring to the beam. Besides, the beam will be subject to critical moments and shear stresses under earthquake forces (Ozmen and Unay, 2007). However, it is prohibited by the 2007 Turkish Earthquake Code for:

- Columns to be supported by cantilever beams or gussets of the columns underneath.
- Shear-walls to rest on columns or/and beams.

The 2007 Turkish Earthquake Code described the cases which causes this type of irregularity as: where columns or structural walls are omitted at lower stories which causes columns of the stories immediately above to be carried by bellow gusseted columns (Figure 2.18a) or beams (Figure 2.18b), or where shear walls to

be carried by columns (Figure 2.18c) or beams (Figure 2.18d) of the storey immediately below.




Figure 2.18: Discontinuity of Vertical Structural Elements Irregularity (Ministry of Public Works and Settlement, 2007, P.10)

2.3.2.2 Vertical Structural Elements' Elementary Design Faults

2.3.2.2.1 Broken Axis Columns

A broken axis column creates eccentricities and additional moments within the column, thus broken axis columns should be avoided during design stage. Interior broken axis columns are not usually found as often as in exterior columns due to the desire of smooth façade. If smooth façade are desired when the cross-section of upper levels exterior columns are reduced, a plaster or masonry wall could be used to

fill the areas of reduced sections. However these fillings could be danger as it can fall off during earthquake motion if not installed properly. The centre line of a column should be continuous from foundation to roof to avoid any additional eccentricities and moments which may lead to cracks on structural members (Figure 2.19) (Ozmen and Unay, 2007).




Figure 2.19: Broken Axis Columns (Ozmen and Unay, 2007)

2.3.2.2.2 Irregular Column and Shear-Wall Plan Configuration

Having Irregular column plan configuration will result in two elementary design faults about beams; namely: non-continuous beams and broken-axis beams (Figure 2.20a). As a result, critical torsion moments will be developed on the system under earthquake lateral inertia forces. Uneven deflections will develop due to varying rigidity throughout the diaphragm. Another disadvantage of irregular column plan configuration is that it requires uneconomical large cross-section structural element to compensate its lack of lateral resistivity. On the other hand, having a regular column plan configuration (Figure 2.20b) where column are regularly placed and organized according to an axial column grid system to resist X and Y earthquake

force directions, will result in even rigidity, limited deflections and reduced stresses on structural elements (Ozmen and Unay, 2007).




Figure 2.20: Irregular vs. Regular Configuration of Columns (ozmen and unay, 2007)

A shear-wall is a load-bearing wall having a longer edge to a shorter edge ratio >7 . The minimum width of a shear-wall according to the 2007 Turkish Earthquake Code is 20 cm. Similar to columns, the configuration of shear-walls should be also regular by organizing them according to an axial grid system. Additionally, it is always preferable to distribute shear-walls symmetrically across the plan and evenly for X and Y directions (Figure 2.21). A shear wall have a high rigidity in the long direction which makes it very effective in reducing excessive deflections in that direction. Therefore, when using mix system of columns and shear-walls combination, it is best to place shear-walls parallel to the shorter edge of the building which is the direction of critical lateral earthquake force (Özmen, 2008).




Figure 2.21: Irregular vs. Regular Configuration of Shear-Walls (Özmen, 2008)

2.3.2.3 Short Column

When the length of a column is reduced, its lateral rigidity increases which as a result attracts more lateral forces to it. Therefore short columns will be the first column to fail and in shear causing disasters during an earthquake. Short columns can occur in two scenarios:

- I. Some columns are shorter than others within the structure.
- II. Columns which most of their lengths are restricted from deflecting

Examples of the first short column scenario where some columns are shorter than others can be where columns are shortened by beams and in foundation columns on sloped topography (Figure 2.22).




Figure 2.22: Examples of Short Columns Among Longer Columns (Charleston, 2008)

One way to overcome the type of short column problem shown in Figure 2.22a is to pin both ends of the beams that form short columns. However, this solution could generate a soft storey problem which must be considered. On the other hand, to overcome the problem of short columns on sloped site (Figure 2.22b), short columns can be lengthened and prevented from contacting the ground by sleeves or casings which allow the column to freely deflect (Figure 2.23). However, soft story could generate by this solution and should be checked.




Figure 2.23: A Way to Overcome Short on Column on Sloped Site (Charleston, 2008)

In the second short column scenario where most of the column's length is restricted from deflection, columns are partially restricted usually by masonry infill walls (Figure 2.24). Masonry infill walls can intentionally or unintentionally act as shear-walls in buildings. Short columns are commonly caused by short masonry walls such as those found in parking buildings. Charleson (2008) mentioned the following rule-of-thumb on judging short columns: a column can be called a short column if the unrestricted length is less than twice its depth.




Figure 2.24: Short Column Occur When a Column is Partially Restricted from Deflecting Leading to Potential Damage in Form of Shear Cracking in the Unrestricted portion of the Column Under Lateral Force (Charleson, 2008)

To avoid the creation of short columns here, these short walls have to be isolated from the vertical structural elements using earthquake joints. Another method is illustrated in Figure 2.25. In this method, short column failure wouldn't occur because compression forces will act diagonally into the joint between column and beam (Charleson, 2008).




Figure 2.25: A Method of Avoiding Short Columns (Charleston, 2008)

Chapter 3

CONCRETE AND REINFORCED CONCRETE

PROBLEMS

3.1 Introduction

Concrete does not always behave as desired; some of the undesirable defects can be seen as disintegration, spalling, cracking, leakage, wear, deflection or settlement. There are a combination of factors working together which contribute to concrete defects. These factors can be listed as: exposure conditions, service conditions, service load, construction, materials and design. The defects listed in this chapter can jeopardize the structural integrity and/or reduce the strength capacity of concrete. Thus, these defects can be categorised under structural defects as well.

In this chapter the following defects in concrete will be discussed together with their types, symptoms, causes, precautions, prevention, remedies and repair: corrosion of embedded metals, drying shrinkage cracks, construction defects, and structural cracks.

3.2 Corrosion of Metals Embedded in Concrete

Concrete is a high alkalinity material. A fresh concrete usually has a pH value between the range of 12 and 13. Within this range of alkalinity, a passive film is formed on the surface of steel embedded in concrete which protect it. Therefore, corrosion will start when this passive film is faded.

Corrosion rate is very slow in low permeable concrete (high quality concrete) because it is harder for water and oxygen to find their way to embedded steel which are the requirements for corrosion to initiate. However, the mistake of adding extra water to the concrete mix at construction sites is committed sometimes which increases the permeability of the concrete and thus increasing the chance of steel corrosion.

The ultimate structural load capacity of concrete members decreases as the percentage of corrosion increases due to reduction of bar diameter and cracking of concrete surrounding the embedded steel bar which may occur.

3.2.1 Accelerators of Corrosion

If the alkalinity (pH) is dropped (carbonation) or if aggressive chemicals or dissimilar metals are introduced into concrete, corrosion will be accelerated. Figure 3.1 shows the relationship between pH of concrete and corrosion rate. Corrosion of reinforcing bars is one of the most common building defect that can be found in the buildings of North Cyprus. The following subsections are the three accelerators of corrosion, namely: chlorides, carbonation and embedment of dissimilar metals.




Figure 3.1: Relationship Between pH of Concrete and Corrosion Rate (Emmons, 1993)

3.2.1.1 Chlorides

Steel Corrosion could take place even if concrete is high alkaline when chlorides are present. Corrosion does not consume chlorides, they remain present in concrete because they only act as motivator to the process of corrosion (Emmons, 1993).

There are 3 ways for chlorides to be introduced into concrete:

- a) By coming contacting environments that contain chlorides, like sea water or salts.

Chlorides penetration begins from surface, then moves inward. The rate of penetration time depends on: Chlorides amount contacting concrete, concrete permeability (durability) and available moisture amount.

When chlorides concentrations contact steel bars, corrosion occurs with the presence of moisture and oxygen. When the rust around steel grows and expands, tensile stresses will be developed and cause concrete to crack and delaminate. Those cracks and spalls accelerate corrosion as they evolve because they will make it easier for corrosive salts, oxygen, and moisture to access concrete. Deeper embedded steel bars will then be affected by corrosion.

Concentration level of chlorides necessary to promote corrosion decreases as the pH value of concrete decreases. Therefore it is easier for chlorides to promote corrosion as the alkalinity of concrete is lowering.

North Cyprus has a problem of high salt levels in its underground water. Therefore, when the water isolation is absent or inadequate, these is a good chance for corrosion

of reinforcing bars to start in the foundations reaching to the lower parts of the column causing cracks (Figure 3.2).



Figure 3.2: Corrosion Crack in the Lower Part of a Column. Mağusa, North Cyprus. (Case Study #1 (Page 93)).

b) Through existing cracks.

Cracks in concrete permits corrosive chemicals such as salts to enter the concrete and access embedded reinforcing steel bars easier. Table 3.1 presents tolerable crack widths in reinforced concrete according to ACI 224R-01.

Table 3.1: Tolerable Crack Widths in Reinforced Concrete According to ACI 224R-01

Exposure condition	Tolerable crack width	
	in	mm
Dry air or protective membrane	0.016	0.41
Humidity, moisture air, soil	0.012	0.30
De-icing chemicals	0.007	0.81
Seawater and seawater spray, wetting and drying	0.006	0.15
Water- retaining structure excluding non-pressure pipes	0.004	0.10

c) Cast-in chlorides.

Chlorides can be introduced intentionally to concrete during concrete mix stage as an accelerator, or in the form of natural ingredients found in some aggregates. Concrete made with beach sand or using seawater as mixing water will result in cast-in chlorides. Table 3.2 shows suggested chloride ion limits in concrete before concrete is placed in service according to ACI 201.2R-01.

Table 3.2: Suggested Chloride Ion Limits in Concrete Before Concrete Is Placed in Service According to ACI 201.2R-01

Service condition	% of chloride ion to weight of cement
Pre-stressed concrete	0.06
Conventionally reinforced concrete in a moist environment and exposed chloride	0.10
Conventionally reinforced concrete in a moist environment not exposed chloride	0.15
Above-ground building construction where concrete will stay dry	No limit

In old constructions of North Cyprus (buildings constructed more than 30-40 years ago) especially before 1974 water, sand and aggregate used in mixing concrete were mainly supplied from seawater and seashore. This is one of the most important reasons of corrosion in reinforced concrete and deterioration of RC buildings from that time. Figure 3.3 shows an old building constructed around 40 years ago suffering from corrosion-induced spalling due to cast-in chlorides in Palm Brach area in Mağusa, North Cyprus.




Figure 3.3: Corrosion-Induced Spalling and Cracking Due to Cast-in Chlorides in an Abundant Old Building. Palm Beach Area, Mağusa, North Cyprus. (Case Study #23 (Page 115)).

3.2.1.2 Carbonation

The reaction between acidic gases in atmosphere and cement hydration products (calcium hydroxide dissolved in the pore water) is called carbonation. Normal air contains relatively low concentrations of carbon dioxide (0.03%). Industrial atmospheres contains higher level of carbon dioxide. Carbon dioxide penetrates into the pores of concrete by diffusion and existing cracks would help reducing the travel distance of carbonation. Carbonation reaction would result in reducing the alkalinity of concrete to a pH value of 10 which will lead to loss of concrete protection of the reinforcing steel. The passivity of the protective film on steel will be destroyed. If passive film of steel is lost and the concrete is acidic or mildly alkaline, corrosion will take place when moisture and oxygen are present in concrete. When the rust around steel grows and expands, tensile stresses will be developed and cause concrete to crack and delaminate.

In low permeable concrete (high quality concrete), carbonation is very slow (1mm/year). Besides, carbonation needs constant drying and wetting cycle, carbonation will not take place if concrete is constantly submerged under water (Emmons, 1993).

3.2.1.3 Embedment of Dissimilar Metals

Corrosion can occur in concrete when two different materials are cast into concrete structure, along with an adequate electrolyte (known as galvanic corrosion). A moist concrete matrix provides for a good electrolyte. Different metals promote different levels of electrochemical activity. Gold for example, is very active, while zinc is inactive, followings are some metals in order of increasing activity: zinc, aluminium, steel, iron, nickel, tin, lead, brass, copper, bronze, stainless steel and gold.

When two metals are in contact via an active electrolyte, the less active metal will be corroded. One of the most common examples found in buildings is the use of aluminium cast into reinforced concrete. Aluminium was used as an electrical conduit, and more recently, as hand rails. Aluminium has less activity than steel; therefore, the aluminium is the metal that corrodes. The steel will actually become cleaned, and the aluminium surfaces will grow a white oxide, which will cause tensile forces to crack the surrounding concrete. Figure 3.4 shows residential building's balconies having cracks due to dissimilar metal corrosion around handrail's embedded metal balusters.



Figure 3.4: Cracks Due to Dissimilar Metal Corrosion around Handrail's Embedded Metal Balusters of Balconies. Residential Building, Palm Beach, Mağusa, North Cyprus. (Case Study #24 (Page 116)).

3.2.2 Corrosion-Induced Cracking and Spalling

The following factors influencing concrete cracks and spalls due to corrosion of reinforcing steel bars: tensile strength of concrete, concrete cover quality, passive film condition, steel bar diameter, corrosion percentage. In order for spalling and delamination to occur, natural gravity force must act on loose concrete. As the cover-to-bar diameter ratio (C/D) increases the percentage of corrosion needed to cause cracking increases (Alsulaimani et al., 1990) (Figure 3.6).



Figure 3.5: Cracks and spalls in concrete short walls. Public structures, Mağusa, North Cyprus.




Figure 3.6: Corrosion-induced spalling (Emmons, 1993)

3.2.3 Precautions, Prevention, Remedies and Repair

3.2.3.1 Precautions and Prevention

The followings are methods for precautions and prevention of embedded metal corrosion in concrete:

1. Any permanent direct water at concrete surface or persistent water leakage should be dealt with and eliminated.
2. Deteriorative concrete caused by aging such as those of aged buildings should be cured.
3. Avoiding using salty water or/and seashore aggregate in concrete mix.
4. Cracks due to overloading should be dealt with immediately to avoid ease access of O₂ and H₂O to steel bars through cracks.
5. Precautions in handrail detailing, material selection and installation to avoid galvanic corrosion.
6. Adequate concrete cover above steel bars should be selected during design and detail stage. Besides, ensuring the proper execution of these details through adequate site supervision.
7. Water isolation should be properly installed and any defects in water isolation should be minimized. Besides, proper selection of water isolation type.
8. Minimizing the direct exposure of concrete to CO₂ to avoid reduction of concrete alkalinity (carbonation) especially in polluted cities and industrial areas.

3.2.3.2 Common Remedies and Repair Methods

3.2.3.2.1 Patch Repair

If the damage is limited within concrete only, like concrete cover spalling, but reinforcing bars are still considered fine, then this method is the most common repair method for such a situation. Loose concrete must be removed till reaching intact concrete bed. Then, the exposed area of rusty steel bars and concrete must be well cleaned and dust free. Otherwise, they won't bond properly with the patching up mortars. Before patching up, the cleaned exposed steel bars should be primed using special cement/epoxy based primer suitable for the patching up mortar. Finally, patch up using suitable repair mortars to cover and prevent rusting of reinforcement bars. There are 2 material types commonly used for ordinary patching up (Chin-man, 2002):

- 1) Cementitious mortars, e.g. cement mortar and polyester-modified cementitious mortar.
- 2) Resin-based mortars, e.g. epoxy resin mortar and polyester resin mortar.

3.2.3.2.2 Replacement of Reinforcement Bars

The addition or replacement of reinforcement steel bars method is applicable when the damage is more severe in a way, after cleaning out the rust, it is revealed that the steel bars have lost significant amount of its diameter. The specifications of the old reinforcement bars have to be identified before carrying on estimates on the needed steel bars replacement or addition and the needed lapping of the existing and introduced bars.

3.2.3.2.3 Strengthening by using Carbon Fiber Reinforced Polymer (CFRP)

After carrying out the proper repairs of cracks, spalls and corroded bars, structural members can be strengthened using Carbon Fiber Reinforced Polymer (CFRP)

which is one of the materials being used recently for strengthening of RC buildings in North Cyprus (Figure: 3.7). The old bazaar in İskele was also built around 40 years ago. The use of salty water and aggregate were the main reasons for the deterioration of the building and the corrosion of reinforcing bars in the structural members. This building is currently being repaired and strengthened by using CFRP. Also new columns and new foundations were introduced for proper strengthening of this old building (Naimi and Celikag, 2010).



Figure 3.7: Strengthening of the Old Bazaar by Using CFRP in İskele, North Cyprus (Naimi and Celikag, 2010)

3.3 Cracks Due to Drying Shrinkage (Cracks Due to Moisture Effect)

When exposed to air, concrete loses some of its original water by means of evaporation and shrinks as a result. Shrinkage cracks are commonly found on the floor screed surface and normally caused by improper curing process.

Drying shrinkage, if unrestrained, results in shortening of the member without a build-up of shrinkage stress. If the member is restrained from moving, stress build-up may exceed the tensile strength of the concrete. This over-stressing results in dry

shrinkage cracking. Shrinkage cracks are commonly found on the floor screed surface and normally caused by improper curing process. (Emmons, 1993) showed the factors affecting drying shrinkage in Table 3.3.

Table 3.3: Factors Affecting Drying Shrinkage (Emmons, 1993)

Factor	Reduced Shrinkage	Increased shrinkage
Cement type	Type I, II	Type III
Aggregate size	38 mm	19 mm
Aggregate type	quarts	sandstone
Cement content	325 (kg/m ³)	415 (kg/m ³)
Slump	76 mm	152 mm
Curing	7 days	3 days
Placement temperature	16°C	29°C
Aggregate state	washed	dirty

3.3.1 Precautions and Prevention

Correct placement of reinforcing steel in the member distributes the shrinkage stresses and controls crack widths. Adequate curing process must be insured to avoid drying shrinkages.

3.4 Construction Defects Due to Faulty Workmanship

Methods used to construct concrete structures are different from methods used in other type of construction. Concrete is one of the few materials in which raw ingredients are brought together at, or near, the construction site, where they are mixed, placed and moulded into final product. There are numerous variables influencing the production of concrete that there is a probability at all times for something to go wrong. Every building process includes a sequence of necessary step-by-step operations from conceptual plan to finished structure.

Mistakes can be classified into two groups: wrong detailing and inexperienced labourers. Errors can be committed at one or more of the following main stages: conceptual planning, design, construction, and maintenance. Sometimes, designers are not paying adequate attention and not giving importance to some of the construction and structural details at design stage which are essential for sufficient building design and preventing defective workmanship or wrong detailing and design errors. Furthermore, inadequacy of quality control and problems in workmanship due to shortage of experienced and skilled workers to perform construction works, which is the consequence of unusual increase in the demand of construction industry in recent years, lead to the poor construction quality in RC building construction in North Cyprus.

On the other hand, workmanship issues are always associated with small contractors as they are not well trained to be in the construction industries. In many cases their quality of works is low due to lacks of experiences and improper guidance from the relevant parties. Workmanship issue are less to arise among established contractors/suppliers as they have strong financial record and expertise in carrying the works. The local government should through various entities make efforts to improve knowledge and skill of those small contractors by conducting field training, seminar and short courses.

Unfortunately, inadequacy in supervision of the construction at the sites in North Cyprus is a main factor of construction defects. Buildings are constructed with insufficient site control. This causes various construction defects in the construction industry. Chambers of the architect and engineers could only carry out the project control on submitted paper work (Özbilen, 2004).

The following subsections are aimed to highlight the problems in RC structures that can be seen mostly in buildings under construction due to mainly wrong/inadequate detailing, lack of workmanship and vibration. Some of these faults are not recognized by the professionals or construction workers since over the years they are naturally being accepted as necessary applications and no body questions why a particular work is done in such away.

3.4.1 Improper Reinforcing Steel Placement

There are three important reasons to control the proper location of reinforcing steel in structures:

- a) Steel bars are used in concrete to carry tensile loads, and if the steel is placed improperly, that might denies the concrete the ability to carry tensile loads. Cantilevered slabs, and negative moment areas near columns pose particular risk.
- b) Steel bars needs sufficient concrete cover to prevent them from getting rusty. The alkalinity of the concrete is a natural corrosive inhibitor. If the concrete cover is inadequate, steel bars will be vulnerable to corrosion in short time (Figure 3.8 a). Shifted reinforcing bar cages in columns, walls or beams may also cause the reinforcing steel to lose proper cover as shown in Figure 3.9. The ACI-required concrete cover for corrosion protection is shown in Table 3.4.




Figure 3.8: Illustrations of Improper Reinforcing Steel Placement: (a) Shifted Cage Causing Inadequate Concrete Cover. (b) Congested Reinforcement. (Emmons, 1993)



Figure 3.9: Shifted Reinforcing Bar Cages in: a Beam (a) and in a Sheer Wall (b). Residential Buildings, Mağusa, North Cyprus. (Case Study #111 (Page 203)).

Table 3.4: ACI-Required Concrete Cover for Corrosion Protection

Condition	Cover required (mm)
Concrete deposited on the ground	76
Formed surfaces exposed to weather: bars > 19 mm	51
Formed surfaces exposed to weather: Bars < 16 mm	38
Formed surfaces not exposed to weather: Beams, girders, columns	38
Slabs, walls, joists: Bars < 36 mm	19
Slabs, walls, joists: Bars 43 mm, 57 mm	38

- c) Beams and columns are usually heavily reinforced members. Lap splices require overlaps of bars and may result in a mat of steel that concrete mix cannot pass through during placement and consolidation. The result is either a visible, or worse, a latent void around the reinforcement (Figure 3.8b) and (Figure 3.10). High congested reinforcement should be reduced by taking it into consideration during design stage.



Figure 3.10: Visible Voids around Reinforcements Due to High Congestion.
Residential Building, Mağusa, North Cyprus.
(Case Study #104 (Page 196)).

3.4.2 Premature Removal of Forms

Removal of forms (including shoring) before the concrete reaches a suitable strength may result in compression and tensile stresses, leading to cracks, deflection, and probable collapse (Figure 3.11).




Figure 3.11: Illustration of Premature Removal of Forms (Emmons, 1993)

3.4.3 Cold Joints

Cold joints are regions of discontinuity within a member where concrete may not tightly bond to itself. Cold joints may occur within a planned placement if a part of concrete in one placement sets, and then the rest of the concrete is placed on it. During the set, laitances form, providing for a weakened plane. The result is a weak connection between placements that could rebuilt in weakness. To achieve proper bond and water-tightness, the surface of hardened concrete must be free of dirt, debris, and laitance. Figures 3.12 and 3.13 shows some cold joints in columns.



Figure 3.12: Cold Joints in Columns. Residential Buildings, Mağusa, North Cyprus. (Case Study #111 (Page 203)).



Figure 3.13: Cold Joint in Column. Residential Buildings, Mağusa, North Cyprus. (Case Study #104 (Page 196)).

Cold joints can also be found at intersections between members where timber is not properly removed from the reinforced concrete as shown in Figure 3.14. This can ease the initiation of corrosion in exposed bars which can lead to other serious problems during the building's lifespan.



Figure 3.14: Cold Joint Between Column and Slab. Residential Buildings, Mağusa, North Cyprus. (Case Study #111 (Page 203)).

3.4.4 Segregation

Segregation of concrete results in non-uniform distribution of its constituents (Figure 3.15). High slump mixes, incorrect methods of handling concrete and over-vibration are causes of this problem. Segregation causes upper surfaces to have excessive water-cement ratio. The resultant concrete may lack acceptable durability.




Figure 3.15: Illustration of Segregation (Emmons, 1993)

3.4.5 Honeycombing

Honeycomb is a void found in concrete because mortar has failed to fill the gaps between coarse aggregates (Figure 3.16). This air void creates a low compressive strength spot within the concrete member. Honeycombing occurs mainly because of insufficient vibration of concrete during pouring. Excessive honeycombing in columns could result in a failure of the column under earthquake forces. Emmons (1993) summarized the primary causes of honeycomb in Table 3.5.



Figure 3.16: Honeycomb in a Column. Residential Building, Magusa, North Cyprus. (Case Study #104 (Page 196)).

Honeycombing in concrete if not fixed can lead to water seepage which in return lead to: rust staining, paint/wallpaper peeling, water dripping, mouldiness and defective concrete, plaster or tiles (Chin-man, 2002).

Table 3.5: Primary Causes of Honeycomb

	Design of members	Forms	Construction conditions	Properties of fresh concrete	Placement	Consolidation
a	Highly congested reinforcement	Leaking at joints	Reinforcement too close to forms	Insufficient fines	Excessive free-fall	Vibrator too small
b	Narrow section	Sever grout loss	High temperature	Low workability	Excessive travel in forms	Frequency too low
c	Internal interference	-	Accessibility	Early stiffening	Lift that is too high	Amplitude too small
d	Reinforcement splices	-	-	Excessive mixing	Improper tremie or drop chute	Short immersion time
e	-	-	-	Aggregate that is too large	Segregation	Excessive spacing between insertion
f	-	-	-	-	-	Inadequate penetration

3.4.6 Improper Grades of Slab Surfaces

Slabs requiring drainage for proper runoff need special attention. Drains should be at low, not high points. Proper slop-to-pitch for quick runoff is important to prevent deterioration and leakage within the structure. Standing water provides concrete with the potential for saturation (Figure 3.17). The quicker the water runs off the structure, the less leakage can occur through joints and cracks.




Figure 3.17: Improper Grades of Slab Surfaces (Emmons, 1993)

3.5 Cracks in RC Due to Load Effects (Structural Cracks)

Concrete structures and individual members all carry loads. Some carry only their own weight, while others carry loads applied to the structure. All materials change volume when subject to stress. Concrete is no exception. Most concrete members are subject to tensile forces. Slabs and beams are the most common members subject to significant tension. When subject to tensile stress, concrete stretches; when subject to compressive stress, it shortens. Reinforced concrete is a structural composite made up of two types of materials: concrete and reinforcing steel. Concrete possesses high compressive strength but low tensile strength (about 10 percent of its compressive

strength), and reinforcing steel bars are placed in the concrete to provide the needed strength in tension. Steel and concrete work effectively together in a composite material for several reasons:

1. Similar thermal expansion coefficient.
2. Rebar-concrete bond prevents slipping of rebars relative to the concrete.
3. Good quality concrete adequately protects reinforcing steel from corrosion.

Concrete problems, such as excessive deflection, cracking, or spalling may be caused by volume change associated with load effects. A simply supported beam with loading from top experiences tension in its bottom portion (maximum tension at midspan). While compressive forces are acting in the top portion (maximum compression at midspan).

When reinforcing bars are subjected to tension, they stretch. The concrete around the reinforcing bars is consequently subject to tension and stretches. When tension in excess of tensile strength of concrete is reached, transverse cracks may appear near the reinforcing bars.

When structural cracks are observed, the building must be checked immediately by experts. Structural cracks mean the building or part of it is overstressed which may lead to a sudden collapse.

3.5.1 Slab/Beam-to-Column Shear (Punching Shear) Cracks

Column connections to slabs and beams experience considerable shear stress. Excessive stress produces cracks in the beams and in the surrounding slab (Figures 3.18 and 3.19).




Figure 3.18: Illustration of Punching Shear (Sacramento et al., 2012, p. 594)




Figure 3.19: Plan View of Punching Shear Cracks in a Test Specimen at University of Waterloo, Ontario. (Curtis, 2013)

Shear cracking at column-beam/slab connections can also be caused by horizontal movement. Horizontal forces can accumulate from: Volume changes caused by temperature changes and foundation movements caused by settlement or earthquakes.

In seismic/moment resisting frames, columns support beams (Figure 3.20a). These beams usually provide enough thickness to resist punching shear. However, some structures do not only consist of seismic/moment resisting frames, but a combination of seismic resisting frames and gravity only columns. These gravity only columns

support flat slabs directly, and here where punching shear is in high concern (Figure 3.20b).




Figure 3.20: Some Methods of Increasing Punching Shear Resistance.




Figure 3.21: Punching Shear Reinforcement
<http://www.bpress.cn/ex/tag/PEIKKO/>

3.5.1.1 Precautions and Prevention

There are several design methods to increase punching shear resistance. The simplest method is to increase the slab depth, yet it is the least economical method. It would be more economical to increase the depth of the slab in the column area only by providing column heads (capital) or/and drop panels (Figure 3.20c and d). Another method can be by playing with reinforcements, such as providing additional negative reinforcements, shear links or shear studs (Figure 3.21).

3.5.2 Cantilevered Members' Cracks

Cantilevered members are supported only on one side, balcony slabs are a typical example. Tension forces are acting in the member's top portion. Top portion tension is also known as negative moment. Tension is greatest at the member's fixed end. Tension forces are carried by the reinforcing steel located in the top portion of the member. Two critical factors should be considered when using cantilevered members:

1. The negative moment steel must be placed in the correct position near the member's top surface. Improper placement of the reinforcing steel may result in bending failure of a structural member.
2. Tension cracks that develop over the negative moment steel are natural canyons for moisture and other corrosion-inducing substances (Figure 3.22). Heavy corrosion results in section loss and causes proportional loss in tension capacity. Yielding of reinforcing steel may result in hinging and complete failure.




Figure 3.22: Illustration of Cracks in Cantilevered Slab (Emmons, 1993)

3.5.2.1 Precautions, Prevention, Remedies and Repair

3.5.2.1.1 Precautions and Prevention

Avoiding overloading and exceeding the designed strength capacity of the cantilevered member. Besides, care in designing and placing the reinforcement bars in their correct position on top to counteract negative moment.

3.5.2.1.2 Remedies and Repair

After the provision of temporarily external supports, the cracks are commonly repaired by carrying out pressure injection of non-shrinkage grout or epoxy resin or by open-up and refill/recast with concrete (Chin-man, 2002).

3.5.3 Problems and Cracks Associated with Foundation/Soil Settlement

When the soil underlying the building is inadequately compacted or when it get swollen or shrunk by the effect of water in some soil types such as clays, the building or part of it subsides by the help of its weight leading to structural cracks and other serious problems.

Soil settlement is critical to buildings and infrastructures. Settlements lead to structural movements and can be caused by the mistake of selecting wrong foundation types due to lack of soil investigation.

Unwanted ground settlements and excessive movement of the building structure can result in causing diagonal cracks at corners of openings such as windows and doors. Besides, long continuous crack across width of walls or/and possibly structural elements. Those cracks on external wall not just destroying finishes but actually penetrate all the way to the other side through the masonry wall or concrete member. If not fixed, they can lead to water seepage which in return lead to: rust staining, paint/wallpaper peeling, water dripping, mouldiness and defective concrete, plaster or tiles (Chin-man, 2002).

Earthquake codes specifies whether site specific soil investigation is to be carried or not. For example in the 2007 Turkish Earthquake Code, site specific soil investigation is mandatory only if:

- I. The height of the building is more than 60m in the first and second seismic zone (see Table 2.1 to refer to seismic zones in North Cyprus).
- II. Buildings with importance factor of 1.5 and 1.4 irrespective of height and seismic zones (highlighted in red in Table 3.6).

Worthy to mention, the chamber of civil engineers funded a project to create a macro map of soil bearing capacity, soil liquefaction and settlement properties for Tuzla region which is located in Mağusa.

Table 3.6: Building Importance Factor (I) (Ministry of Public Works and Settlement, 2007, p.11)

<i>Purpose of Occupancy or Type of Building</i>	<i>Importance Factor (I)</i>
<p><u>1. Buildings to be utilised after the earthquake and buildings containing hazardous materials</u></p> <p>a) Buildings required to be utilised immediately after the earthquake (Hospitals, dispensaries, health wards, fire fighting buildings and facilities, PTT and other telecommunication facilities, transportation stations and terminals, power generation and distribution facilities; governorate, county and municipality administration buildings, first aid and emergency planning stations)</p> <p>b) Buildings containing or storing toxic, explosive and flammable materials, etc.</p>	1.5
<p><u>2. Intensively and long-term occupied buildings and buildings preserving valuable goods</u></p> <p>a) Schools, other educational buildings and facilities, dormitories and hostels, military barracks, prisons, etc.</p> <p>b) Museums</p>	1.4
<p><u>3. Intensively but short-term occupied buildings</u></p> <p>Sport facilities, cinema, theatre and concert halls, etc.</p>	1.2
<p><u>4. Other buildings</u></p> <p>Buildings other than above-defined buildings. (Residential and office buildings, hotels, building-like industrial structures, etc.)</p>	1.0

3.5.3.1 Precautions, Prevention, Remedies and Repair

3.5.3.1.1 Precautions and prevention

Soil investigation and compaction should be carried out properly and the foundation design is based on the results of soil investigation. Construction work should not start on site without any soil investigation.

3.5.3.1.2 Remedies and repair

3.5.3.1.2.1 Soil settlement

Solving foundation settlement problem caused by problematic soils is difficult, expensive and often of limited effectiveness. Any solution must stabilize the water content of the soil beneath the building.

There are many remedial methods for soil settlement due to inadequate soil compaction, one of them is slab lifting method using special resin where resin is to be injected into the ground at various levels so that it mixes and improves the soil properties. It is much faster compare to other method despite its higher cost. Figure 2.23 shows the improvement before and after the treatment at Social Security Organisation (SOCSO) building in Penang, Malaysia.



Figure 2.23: Before (on the left) and After (on the right) the Treatment Using Resin Injection at Social Security Organisation (SOCSO) Building in Penang, Malaysia (Suffian, 2013).

3.5.3.1.2.2 Cracks

Crack on brick walls can be repaired easily with straight forward methods such as applying repair mortar / putty onto the affected area (for cracks $< 3\text{mm}$) together with suitable wire meshes provided the surface preparation is carried out in proper ways (Suffian, 2013).

On the other hand, structural cracks (cracks found on structural elements) deserve immediate attention. The cracks are commonly repaired by carrying out pressure injection of non-shrinkage grout or epoxy resin or by open-up and refill/recast with concrete (as Chin-man, 2002).

Chapter 4

NON-STRUCTURAL PROBLEMS

4.1 Introduction

Non-structural defects vary widely, ranging from finishing flaws, water or moisture problems, and deterioration of materials. They usually don't jeopardize the structural integrity of a building but may affect the aesthetics and may cause health and comfort problems. The following non-structural defects will be discussed in this chapter: dampness, crazing, map cracking, efflorescence, paint peeling, mouldiness, staining, waterproofing defects, joint cracks and wooden door defects.

4.2 Surface Defects

Façade finishes of buildings in north Cyprus are of aluminium cladding and most commonly plaster and paint.

4.2.1 Dampness

Many surface defects are observed as dampness, resulted from insufficient protection of exterior surfaces, inadequate or poor water insulation, or capillary action. Dampness is the presence of undesirable moisture in the building's walls or ceilings etc. This undesirable moisture can lead to discolouration, staining, degradation of finishes or mouldiness on the damp surface. There are several types of dampness depending of the source of the moisture. However, the most common types of dampness in buildings are: condensation, rising damp and rain penetration (Trotman et al., 2004).

Dampness does not only affect buildings but it can also affect the health of buildings' inhabitants, known as sick building syndrome, as the unwanted moisture allows for growth and multiplication of microbes such as moulds, fungi and bacteria causing poor indoor air quality. Besides, dampness deteriorates and disintegrates materials into air causing indoor air pollution. The followings are the effects of dampness on buildings:

- It causes corrosion of metals.
- It deteriorates furniture and other various building materials, such as: wood, plaster and paint.
- It damages electric installations.
- It shortens the life-span of the building.
- It is visually unpleasant (stains and discolouration).
- It causes mouldiness and efflorescence, which will be discussed later in this chapter.

Condensation, which is damp from the air, is the type of dampness caused by high air humidity. Indoor activities such as cooking, bathing/showering, washing and drying dishes and cloths and even breathing emit moisture and vapour into air increasing the air humidity and if not ventilated the risk of condensation damp within a building. Condensation normally occurs in tropical climates and in winter as for condensation to happen warm vapour needs to meet a colder surface. Condensation affects the performance of buildings and hence the liveability of interior areas. Condensation can allow for mould to grow creating black spots on walls or ceilings, and if left untreated, condensation can damage paint and plaster. Sassu and De Falco (2014) listed the primary causes of water condensation as follows:

- Inadequate air circulation and ventilation.
- Deficient thermal insulation (as in order for condensation to occur, warm vapour must meet colder surfaces).
- Thermal bridges.
- Prevention of wall breathing by External cladding.
- Insufficient drying time of newly constructed walls and floors before cladding.

To prevent and solve the damp problem of condensation, dehumidifier can be used, adequate insulation, heating and ventilation should be applied and moisture generation should be minimized (e.g. dry cloths outdoor instead of indoor).

Rising damp is the type of dampness where moisture from groundwater moves upwards through the pores in walls of basements and ground floors by capillary action. It occurs in old building where damp-proof course (DPC) is not installed or in case of modern buildings, when ground water bypass it or penetrate a defective DPC. The damp-proof course (DPC) is the line of black waterproofing material, usually seen between two rows of bricks about 150mm above ground level. If left untreated, rising damp can cause degradation and damage of skirting, crumbling of plaster, as well as peeling of paint and wallpaper on the lower section of the wall (usually not higher than 1.5m), often with wet patches. In rising dampness, mouldiness can only occur in the early stages as rising dampness brings with it salts that prevent the growth of moulds. To overcome rising damp:

- Firstly: moisture sources should be eliminated, methods of removing groundwater usually expensive and requires experts. Or prevent moisture from bridging and bypassing the DPC.

- Secondly: replacement or/and adequate installation of water proofing insulation should be applied, such as damp-proof course (DPC).
- Thirdly: re-plastering of the affected area.

Rain penetration is the type of dampness where rainwater makes its way into a wall or ceiling by leakage or even through the surface itself. Additionally, sometimes moving cars can splash rainwater into external walls of buildings adjacent to streets causing them to damp. Eaves and overhangs play an important role in protecting of external surfaces from getting damped by rainwater. Therefore pitched roof building, which usually have eaves acting as overhangs, performs better than flat roofs in the protection against rainwater. Modern building designs, which favours flat roofs, requires special attention in detailing efficient rainwater drainage system. Waterproofing specially in flat roofs is essential for preventing rainwater to access buildings. If the roof waterproofing membranes is defected or not well sealed at joints, such as the joints between the roof and external walls, there will be higher chance for dampness to occur. Traditional pitched roof design such as gabled or hipped roof doesn't only perform better than flat roof, but they also do not require as much attention in detailing waterproofing and drainage as for those in flat roofs since they simply allow the rainwater flow out of the building (Sassu and De Falco, 2014). Rain penetration causes discolouration, staining, mouldiness and efflorescence on walls (Figure 4.1). Designing roof and windows with sufficient eaves or overhangs can to some extends protect walls from rainwater. Defective roof guttering or deficient drainage system increases the change for rain penetration dampness to occur: when rainwater drainage system get blocked or fail, rainwater running down the walls may damage them, accelerating the deterioration of the facade.

Spills and leaks are another moisture sources witch often causes dampness. Dampness causes by leakage of defected pipes or frequent floor washing with too much water can be easily mistaken for rising damp, rain penetration or condensation (Figure 4.2). The first and most important step of treating any kind of dampness is to eliminate the moisture sources.



Figure 4.1: Dampness on the Upper Section of the Wall Due to Rain Penetration. Civil Engineering Department, Eastern Mediterranean University (EMU), Mağusa, North Cyprus.



Figure 4.2: Dampness on The Lower Part of Second Floor Walls Due to Wet Floors Caused by Frequent Floor Washing Using Too Much Water Which Can Be Mistaken Easily as Rising Damp. Akdeniz Gormitory, Eastern Mediterranean University (EMU), Mağusa, North Cyprus.

4.2.2 Surface Cracks on Wall Finishes

Sometimes multi-directional hair-line cracks develops on walls and sometimes accompanied with paint peeled off. They are mostly cosmetic shrinkage cracks developed within wall finishes such as plaster or other cement sand based rendering finishes. These cracks disturb the finishes and the wall's aesthetic only and doesn't usually lead to structural hazard as they do not penetrate down to the reinforced concrete structure. Besides they do not pose any safety concern. These cracks should be repaired by open-up and repair by mortar with the required key (Chin-man, 2002).

4.2.2.1 Crazeing and Map or Pattern Cracking

Crazing appears on the surface as a net arrangement of hair-line cracks which doesn't penetrate a lot beyond the surface (rarely more than 3 mm deep). Crazeing cracks encompass small concrete areas less than 50 mm (2 in.). The cause of crazing is minor surface shrinkage due to rapid surface drying of unhardened concrete due to low humidity, high air temperature, hot sun, or drying wind, either separately or in any combination. This drying at the surface causes the concrete at the surface to shrink at a faster rate than the concrete below causing stresses at the surface. Prevention of crazing lies in curing, curing should start as early as possible to stop rapid surface drying and lower the surface temperature specially when the temperature is high and the sun is out. The concrete should be protected against rapid changes in temperature and moisture wherever feasible.

Map/pattern cracking is similar to crazing, but the difference between crazing and map or pattern cracking is that the cracks of crazing are very fine and hard to notice unless when the concrete surface is allowed to dry after being wetted. While map/pattern cracking is more visible and its cracks encompass larger areas of concrete.

Another difference is that the cause of map cracking is not only because of surface drying shrinkage restrained by underlying concrete that shrinks less, but it can also be one of the followings non-common causes:

- Expansion due to alkali-silica reaction within the concrete (ASR). Alkalis in Portland cement combine with reactive silica in some aggregates to form a gel around the aggregate particles. The gel absorbs water, causing internal expansion of the concrete and map cracking. Crack widths usually are large, reaching 1/2 inch in severe instances.
- Restrained thermal contraction, particularly at early ages. This typically occurs in thick concrete sections with enough mass to develop significant heat during cement hydration. The surface cools and then tries to contract, but the interior concrete that hasn't yet cooled restrains it. Map cracking then occurs.

Other than early water loss prevention and early curing mentioned in the prevention of crazing, map cracking can also be prevented by considering ASR in mix design. In the case when placing a large mass of concrete, concrete temperature can be minimized by cooling or by reducing cement content, or by using insulation blankets so the concrete surface doesn't cool too rapidly while the interior is still hot.

Although, both types of cracks are not structurally serious (except for map cracking caused by one of the two non-common causes mentioned above), they are undesirable as they may be aesthetically unacceptable and they can collect dirt, besides could lead to paint peeling(Figure 4.3).



Figure 4.3: Map cracking on the Column of the Top Floor That Led to the fall of some of the Paint Cover. English Preparatory School, Eastern Mediterranean University, Mağusa, North Cyprus.

4.2.3 Efflorescence

Efflorescence is a whitish bleeding or deposit on concrete (Figure 4.4) and brick wall surfaces which occurs due to chemical reaction between chemicals in the wall materials and chemicals in the atmosphere prior to painting process. Another cause is when moisture dissolves the soluble salts in the wall material, this salt-water solution is then moved toward the surface by evaporation or hydrostatic pressure. Left on the surface, water then evaporates, leaving a salt deposit at the surface. Efflorescence is structurally harmless but it is visually unattractive.



Figure 4.4: Efflorescence on Concrete Surface.

<http://www.docfoc.com/concrete-cast-in-place-flat-grey-efflorescence>

4.2.3.1 Precautions, Prevention, Remedies and Repair

4.2.3.1.1 Precautions and Prevention

If one of the following components which cause efflorescence are absent, efflorescence will not occur: water, evaporation or salts. When mixing concrete avoid the use unwashed sand and aggregate. Sand should meet the requirements in the standard of the American Section of the International Association for Testing Materials ASTM C33. Besides, ensure the use clean water and avoid using seawater. Less permeable concrete is less prone to efflorescence and thus lower permeability is favoured.

4.2.3.1.2 Remedies and Repair

This problem can be resolved by determining and isolating or eliminating the source of moisture, completely removing the finishes and removing the salts on the affected surface by brushing and washing and then repainting in suitable condition (Suffian, 2013).

4.2.4 Paint Peeling

Paint is a common wall finishing in North Cyprus. Paint peeling is when paint loses its adhesion to the wall and curls or fall off, also known as delamination. Paint peeling affects the aesthetic of the building and if wall surface is wet, it can lead to fungal and mould growth unless the used paint type has the property to prevent them. As discussed earlier in dampness, one of the symptoms of dampness is peeling of paint. Other than moisture there are causes for paint peeling, the followings are the common reasons for paint peeling:

- Age of paint: as time passes, paint degrades and loses its adhesive bond strength with the wall. Bad weather and intense or prolonged exposure to UV lights can accelerate this process. This is why paint peeling is more often on exterior walls. Therefore, periodic maintenance is necessary.
- Applying paint on dirty, dusty, wet, too smooth/glossy or hot surfaces: these reduces the adhesion of the paint.
- Incompatible paint: this is common when applying a new paint over an older one without checking the compatibility between them which can cause the newer one separating off the older one, known as intercoat peeling.
- Moisture and damp Walls (most common cause): Moisture transmission through a wall forces off the paint.
- Using cheap/poor quality paint.

- Poor workmanship, such as: presence of trapped air, application of thick paint coat and un-dried undercoat.

4.2.4.1 Remedies and Repair

To solve the problem of paint peeling on a wall, the loose paint must be removed and surface roughed and sanded before dust removal and cleaning prior to repainting under a good condition with a compatible good quality paint.

4.2.5 Mouldiness

Mouldiness in houses is where surfaces such as walls and ceilings are covered with moulds which have grown on them. As discussed earlier in dampness, mouldiness can be caused by dampness, especially condensation. Mould spores are always present in the air and they are invisible to the naked eye. However, they become apparent when they land on a surface and start multiplying. To achieve that, moulds need four elements: food, moisture, a suitable temperature (between 2 and 40 degrees Celsius) and oxygen. At houses, oxygen is available always naturally in the air and the temperature usually is suitable. Moisture is offered by condensation and food (starch) is usually obtained from surface finishes such as wallpaper or emulsion paint and from ceiling tiles. Of these four things, we can only control mould growth by cutting out moisture or cutting out their food by using other wall finishing materials that prevent mouldiness such as anti-mould paint. The longer the material is exposed to water, the higher the risk of mouldiness. The quantity of water is not as important as the duration of exposure for moulds to grow.

Mouldiness affect the aesthetic appearance and causes stains or discolouration to the surface finishing material. Besides, the presence of moulds in the interior is

unhealthy and can cause health problems. Hence, it should be dealt with as early as possible.

4.2.5.1 Precautions, Prevention, Remedies and Repair

4.2.5.1.1 Precautions and Prevention

Preventing moisture from reaching surfaces and using wall finishing materials that prevent mouldiness such as anti-mould paint.

4.2.5.1.2 Remedies and Repair

The first and most important step in treating mouldiness is to eliminate the source of the dampness (refer to dampness section). Light mould staining on hard surfaces such as painted walls can be removed using a solution of water and vinegar, otherwise wipe down the walls with a fungicidal wash or diluted bleach. The final step is repainting with a good quality fungicidal paint to help prevent mould recurring.

4.2.6 Staining

After few years of painting, many building facades experience staining problems such as water mark, rust marks, existence of moss, fungus and algae attacks, etc.

4.2.6.1 Precautions and Prevention

To minimize these problems, high quality external paint containing antifungal agents can be used. It may not offer a total solution but it helps to prolong a good appearance of the buildings.

4.3 Waterproofing Defects, Water Leakage and Seepage

To suit a modern concept of design and ease of maintenance, many building designers in North Cyprus have opted for a flat roof concept rather than traditional pitched roof. However, the problem that mostly associates with the flat roof is a

waterproofing-related issues. Flat roofs are usually more vulnerable to leakage problems compare to that of pitched roof (Douglas and Ransom, 2006).

There are numerous waterproofing systems that are used around the world, such as; liquid, bituminous membrane and cementations water proofing system. There are two techniques of applying waterproofing materials: liquid-application and membrane-application. Some waterproofing materials are able to withstand exposure to atmosphere and others need to be covered with finishes like cement sand screeding or tiles. Some materials are more elastic and suitable for anticipated movements in the roof structure. Waterproofing materials have life expectancy starting from of 5 years to more than 20 years.

Tests need to be performed after applying waterproofing to check its performance. Some water proofing test examples: flooding/ponding tests and thermal scanning

According to a study done by (Suffian, 2013) on Buildings in Malaysia, the bituminous membrane caused regular problem which its root causes was identified as follows:

- The burning process of membrane was not properly carried out resulting weak bonding to the substrates. Water may have tracked between the membrane and the slab thus makes it difficult to trace the source of the leak (Figure 4.5).
- No screed to protect the membrane from punching forces.
- Failure to repair minor defects at early stage that escalated to become major.



Figure 4.5. Failed Torch-on Membrane at Social Security Organisation (SOC SO) in Seberang Jaya, Malaysia (Suffian, 2013).

Suffian (2013) shows that increasing the thickness of membrane from 3 mm to 4 mm makes it performs better. The reason being that the burning process is more stable and easier resulting better bond to the slab.

Defective waterproofing can lead to water seepage which in return lead to: rust staining, paint/wallpaper peeling, water dripping, mouldiness and defective concrete, plaster or tiles (Chin-man, 2002).

4.3.1 Precautions, Prevention, Remedies and Repair

4.3.1.1 Precautions and Prevention

Some problems can be avoided much at early stage if the installer strictly follows the instruction such as constructing angle fillet at corners, fully cleaned the substrate surface prior to installation, accurately mixed components, etc. Installing waterproofing requires special attention to workmanship:

- To avoid ponding on roofs, waterproofed surfaces must have adequate sloping surface to allow for water to run off and find its way to drainage.
- Attention must be paid to the thickness of the applied waterproofing. If the thickness is for some reason is less than intended, problems might arise.
- Attention must be paid to overlapping the water proofing membranes at their edges.
- Corners are potential areas of problems. Therefore waterproofing material must be upturned and downturned where necessary such as walls, pipes and drain holes.
- When installing machines on roofs, attention must be paid to avoid excessive movement which can damage waterproofing integrity.

4.3.1.2 Remedies and Repair

4.3.1.2.1 Repair of Water Leakage in Roof

When it comes to repairing roof leakage problems, the easiest way is to totally replace the old or damaged waterproofing material. On the other hand, partial patch repair has some limitations and it has a higher probability to fail than the total replacement method. Partial patch repair can be applicable only if the source of the leakage such as

Partial application of waterproofing materials may be effective provided that the source of leakage such as cuts and holes can be precisely located, and the new material is compatible with the old one for effective bonding. Additionally, attention must be paid for sufficient overlapping and gradient of the surface to allow for water to run off and prevent ponding.

There are some temporary leakage repair technique which can be applied from ceilings, such as the use of chemical additives to existing concrete surfaces or chemical injection into the cracks and voids. These temporary leakage repair technique are applicable in apartments when the residents of the apartment above are not cooperative. These repair leakage methods can be applied as temporary solution only as water will still leak through other weak points.

4.3.1.2.2 Repair of Water Leakage in External Walls

Water can leak through external walls because of one or more of the followings:

- Penetrating cracks.
- Concrete defects such as honeycombing.
- Defects or loss of external finishes which protect the wall from the rain.

Common repair techniques:

- Penetrating cracks are either chemically injected or opened up before being repaired using waterproofing mortar.
- Honeycombing is cleaned before being patched using compatible waterproofing mortar.

Repairs can be applied internally or externally, depending on the location of the problem. After the repair is done, the surface can be smoothed, plastered and covered with finishes matching the existing ones. Special additives to the repair mortar or rendering can be used to improve waterproofing capabilities.

4.4 Non-Structural Cracks

4.4.1 Joint Cracks

Joint cracks are commonly seen at the joint between column or beams and infill walls. The common causes of such cracks are identified due to the difference thickness of plastering, insufficient bonding element that holds bricks to the column or beams and thermal movement.

4.4.1.1 Remedies and Repair

These cracks should be repaired by injection of specially designed chemicals (Chin-man, 2002).

4.5 Wooden Door Defects

Sometime the door frame and leaf of the toilet and other wet areas is found to be darkened in colour and fine dust of wood falls out of them on the floor. This symptom indicates termite attacks. Soft or damp timber attracts termites. This phenomenon happens when timber is dampened due leakage or insufficient floor tiles slope which allows water to travel to or near the door.

4.5.1 Remedies and Repair

A pest control professionals should be appointed to check and treat the problem. Infected wooden doors must be disposed (Chin-man, 2002).

Chapter 5

CASE STUDIES

5.1 Introduction

In order to highlight defects and inadequacies of design and construction in North Cyprus, numerous case studies were visited and data was collected about the types of defects and mistakes done. The priority of this investigation is to mainly identify the construction inadequacies, design faults, defects of structural members and non-structural members as well such as walls, finishes, insulations etc.

5.2 Methodology

There are a total of 125 case studies in this thesis divided into two groups. The first group which represents completed buildings contains 100 case studies divided into 25 case studies for each of the following four districts: Mağusa, İskele, Lefkoşa and Girne. The second group contains 25 case studies and represents uncompleted buildings, i.e., buildings under construction. The reason for dividing case studies into two groups is because it is easier to detect and consider seismic design faults for buildings which are not completed, i.e., buildings under construction. Case studies in this thesis were coded by using a letter followed by sequence number. For example, Mağusa case studies are M1-M25, İskele İ1- İ25, Lefkoşa L1-L25, Girne G1-G25 and for under construction buildings are C1-C25.

Upon visiting a case studies, visual inspection was carried merely by naked eye. Observation of defects and problems then were checked into a prepared checklist


(Check Appendix A for checklist sample) and documented by photographs when possible. The camera used for photographs is Nikon D5300 which has a built-in GPS, so the coordinates of each case study is recorded as well. The case studies were chosen randomly from noticeably defected buildings while driving, cycling or walking around the country. The location information, i.e., coordinates were extracted using ViewNX 2 software program. Using the coordinates, area and street names are determined through Google maps. Aided by the registered coordinates, the approximate age of the building are determined as well by using Google Earth software program which contain a set of historical imaginary satellite maps dating as far as 2003 (Note the age is approximate as there are missing maps such as those of the years between 2003-3008). If the building age is less than 14 years old, then the approximate age is determined by using Google Earth software program. However if it is more than 14 years old, there is no way to know the age of the building if not told by the owners of the buildings. Moreover, some of the 43+ years old building can be determined easily from the construction methods and materials used such as uncrushed aggregates (note that 43 is the age of the conflict of Cyprus).

5.3 Challenges and Limitations


- Most of the buildings were inspected exteriorly only as it is very difficult to inspect each of them interiorly.
- Without the provision of floor plans, elevations and detailed drawings, calculations to precisely determine irregularities cannot be carried. Visual determination of potential seismic design fault can only be possible if the building is under construction and in its skeleton form.
- Some of dampness defects are seasonal defects which occur mainly in winter. Crazeing on the other hand is a surface defect which hard to detect unless if

the surface is allowed to dry after being wet, e.g. by rain. However, sometimes they leave evidences behind them which lead to their determination such as discoloration, stains and paint peeling.


5.4 Case Studies

Case Study #1 (M1)				
Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Projections in plan			
	Non-continuous beams			
Slab elementary design faults	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
District:	Mağusa	Broken axis beams and frames		
Area:	Sakarya			
Street name:	Salamis Yolu	Over-stretched one-way slab		
Latitude:	N 35°8.789' (35°8'47.3")	Poorly supported or heavily loaded cantilevered slabs		
Longitude:	E 33°54.630' (33°54'37.8")	Pounding and separation problem		
Structure age:	<14 years	Date (if available):		
	Between 14 and 43 years (1974-2003)		Weak storey	
	>43 years (Before 1974)		Soft storey	
Building type:	Residential	Apartment	Discontinuity of columns or shear walls	
		House		Broken axis columns
		Dormitory	Irregular column and/or shear-wall plan configuration	
	Public	Short column		
Commercial				
Building status:	Under Construction		Non-Structural Defects	
	Occupied		Waterproofing defects, water leakage and seepage	
	Abandoned		Defected wooden door	
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	Condensation
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Rising damp
	Corrosion-induced spalling			Rain penetration
	Cracks due to embedment of dissimilar metals (handrails)			Leaking pipes, spills and other moisture sources
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Surface cracks on wall finishes	crazing	
	Premature removal of forms			Map/pattern cracking
	Cold joints	Efflorescence		
	Segregation	Paint peeling		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Non-structural cracks	Joint cracks	Mouldiness
	Cantilevered member cracks			Wall finishes workmanship problem
	Settlement cracks			Staining


Case Study #2 (M2)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Beam elementary design faults	Projections in plan
			Non-continuous beams		
			Non-uniform beam span and cross-section		
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
		Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
			Discontinuity of columns or shear walls		
			Broken axis columns		
		Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration		
			Short column		
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	cr crazing	
				Map/pattern cracking	
			Efflorescence		
			Paint peeling		
			Mouldiness		
			Wall finishes workmanship problem		
		Staining			
		Non-structural cracks	Joint cracks		
		Reinforced Concrete Defects			
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		<u>Other notes (if available):</u>			


Case Study #3 (M3)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Projections in plan			
	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
District:	Mağusa	Over-stretched one-way slab		
Area:	Sakarya			
Street name:	Salamis Yolu	Poorly supported or heavily loaded cantilevered slabs		
Latitude:	N 35°9.137' (35°9'8.2")			
Longitude:	E 33°54.365' (33°54'21.9")	Pounding and separation problem		
Structure age:	<14 years	Date (if available):	Weak storey	
	Between 14 and 43 years (1974-2003)		Soft storey	
	>43 years (Before 1974)		Discontinuity of columns or shear walls	
Building type:	Residential	Apartment	Broken axis columns	
		House	Irregular column and/or shear-wall plan configuration	
		Dormitory		
	Public	Short column		
Building status:	Commercial	Non-Structural Defects		
	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
Reinforced Concrete Defects Drying shrinkage cracks Corrosion of metals embedded in concrete Construction defects (faulty workmanship): designer, detailer, and contractor Cracks in RC due to load effects (structural cracks)	Abandoned	Condensation		
	Surface defects	dampness	Rising damp	
			Rain penetration	
			Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	crazing
	Non-structural cracks	Surface defects	dampness	Map/pattern cracking
				Efflorescence
				Paint peeling
				Mouldiness
				Wall finishes workmanship problem
Staining				
Cracks in RC due to load effects (structural cracks)	Joint cracks	<u>Other notes (if available):</u>		
	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			


Case Study #4 (M4)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
					Projections in plan
			Beam elementary design faults	Non-continuous beams	
				Non-uniform beam span and cross-section	
	Absence of vertical support at beams intersection				
	Slab elementary design faults	Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
	Vertical structural configuration	Irregularity in elevation	Weak storey		
			Soft storey		
			Discontinuity of columns or shear walls		
		Vertical structural element elementary design fault	Broken axis columns		
	Irregular column and/or shear-wall plan configuration				
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
		Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface cracks on wall finishes	crazing
Map/pattern cracking					
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)	Efflorescence			
		Paint peeling			
	Mouldiness				
	Wall finishes workmanship problem				
	Staining				
	Cold joints		Non-structural cracks	Joint cracks	
Segregation		Other notes (if available):			
Honeycombing					
Improper grades of slab surfaces					
Slab/beam-to column shear (punching shear) cracks					
Cracks in RC due to load effects (structural cracks)		Cantilevered member cracks			
		Settlement cracks			


Case Study #5 (M5)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
				Discontinuity of columns or shear walls
			Broken axis columns	
			Irregular column and/or shear-wall plan configuration	
		Vertical structural element elementary design fault	Short column	
		Non-Structural Defects		
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
		Surface defects	dampness	Condensation
				Rising damp
Drying shrinkage cracks			Surface cracks on wall finishes	Rain penetration
				Leaking pipes, spills and other moisture sources
		Non-structural cracks	crazing	
			Map/pattern cracking	
		Efflorescence		
		Paint peeling		
		Mouldiness		
		Wall finishes workmanship problem		
		Staining		
		Joint cracks		
		Reinforced Concrete Defects		
		Corrosion of metals embedded in concrete		
		Construction defects (faulty workmanship): designer, detailer, and contractor		
		Cracks in RC due to load effects (structural cracks)		
		Other notes (if available):		


Case Study #6 (M6)

Profile		Seismic Design Faults	
		Week column-strong beam	
		Structural configuration	Horizontal structural configuration
Floor discontinuity			
Projections in plan			
Beam elementary design faults	Non-continuous beams		
	Non-uniform beam span and cross-section		
	Absence of vertical support at beams intersection		
Slab elementary design faults	Broken axis beams and frames		
	Over-stretched one-way slab		
		Poorly supported or heavily loaded cantilevered slabs	
		Pounding and separation problem	
Vertical structural configuration		Irregularity in elevation	Weak storey
			Soft storey
			Discontinuity of columns or shear walls
		Vertical structural element elementary design fault	Broken axis columns
Irregular column and/or shear-wall plan configuration			
		Short column	
Non-Structural Defects			
Building status:		Under Construction	
		Waterproofing defects, water leakage and seepage	
		Occupied	
		Defected wooden door	
		Abandoned	
Reinforced Concrete Defects			
Structure age:		Dampness	Condensation
			Rising damp
Building type:		Surface defects	Rain penetration
			Leaking pipes, spills and other moisture sources
Building status:		Surface cracks on wall finishes	crazing
			Map/pattern cracking
Reinforced Concrete Defects		Non-structural cracks	Efflorescence
			Paint peeling
Corrosion of metals embedded in concrete		Non-structural cracks	Mouldiness
			Wall finishes workmanship problem
Construction defects (faulty workmanship): designer, detailer, and contractor		Non-structural cracks	Staining
			Joint cracks
Cracks in RC due to load effects (structural cracks)		Other notes (if available):	
		The building is used as storage	
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks	
		Cantilevered member cracks	
		Settlement cracks	


Case Study #7 (M7)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
			Over-stretched one-way slab			
			Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem			
			Vertical structural configuration	Irregularity in elevation	Weak storey	
					Soft storey	
				Vertical structural element elementary design fault	Discontinuity of columns or shear walls	
					Broken axis columns	
			Irregular column and/or shear-wall plan configuration			
			Short column			
			Non-Structural Defects			
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	Non-structural cracks	cracking	
					Map/pattern cracking	
			Efflorescence			
			Paint peeling			
			Mouldiness			
			Wall finishes workmanship problem			
			Staining			
			Joint cracks			
			Reinforced Concrete Defects			
Drying shrinkage cracks						
Corrosion of metals embedded in concrete	Corrosion-induced cracking					
	Corrosion-induced spalling					
	Cracks due to embedment of dissimilar metals (handrails)					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					
			<u>Other notes (if available):</u>			


Case Study #8 (M8)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Projections in plan	
			Beam elementary design faults	Non-continuous beams	
				Non-uniform beam span and cross-section	
				Absence of vertical support at beams intersection	
		Slab elementary design faults	Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs		
				Pounding and separation problem	
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural element elementary design fault	Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects Drying shrinkage cracks Corrosion of metals embedded in concrete Corrosion-induced cracking Corrosion-induced spalling Cracks due to embedment of dissimilar metals (handrails) Construction defects (faulty workmanship): designer, detailer, and contractor Improper reinforcing steel placement Premature removal of forms Cold joints Segregation Honeycombing Improper grades of slab surfaces Cracks in RC due to load effects (structural cracks) Slab/beam-to column shear (punching shear) cracks Cantilevered member cracks Settlement cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
				Surface cracks on wall finishes	crazing
				Map/pattern cracking	
			Non-structural cracks	Efflorescence	
				Paint peeling	
				Mouldiness	
				Wall finishes workmanship problem	
		Staining			
		Joint cracks			
<u>Other notes (if available):</u>					


Case Study #9 (M9)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
	Vertical structural element elementary design fault	Broken axis columns		
Irregular column and/or shear-wall plan configuration				
		Short column		
		Non-Structural Defects		
Building status:	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
	Abandoned			
Reinforced Concrete Defects		Surface defects	dampness	Condensation
Drying shrinkage cracks				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling	
	Premature removal of forms		Mouldiness	
	Cold joints		Wall finishes workmanship problem	
	Segregation		Staining	
	Honeycombing			
	Improper grades of slab surfaces			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Non-structural cracks	Joint cracks	
	Cantilevered member cracks			
	Settlement cracks			
		Other notes (if available):		
		Martı Apt. NO 11		


Case Study #10 (M10)

Profile		Seismic Design Faults			
		Week column-strong beam			
District:	Mağusa	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Area:	Karakol			Floor discontinuity	
Street name:	Fadıl Rıza Sk			Projections in plan	
Latitude:	N 35°7.954' (35°7'57.3")			Beam elementary design faults	Non-continuous beams
Longitude:	E 33°55.584' (33°55'35.0")				Non-uniform beam span and cross-section
Structure age:	Between 14 and 43 years (1974-2003)				Absence of vertical support at beams intersection
Structure age:	<14 years	Vertical structural configuration	Irregularity in elevation	Broken axis beams and frames	
	Date (if available):			Over-stretched one-way slab	
	>43 years (Before 1974)			Poorly supported or heavily loaded cantilevered slabs	
Building type:	Residential	Pounding and separation problem			
	Apartment	Vertical structural configuration	Irregularity in elevation	Weak storey	
	House			Soft storey	
	Dormitory			Discontinuity of columns or shear walls	
	Public	Vertical structural element elementary design fault	Broken axis columns	Broken axis columns	
	Commercial			Irregular column and/or shear-wall plan configuration	
Building status:	Under Construction	Short column			
	Occupied	Non-Structural Defects			
	Abandoned	Waterproofing defects, water leakage and seepage			
Reinforced Concrete Defects		Defected wooden door			
Drying shrinkage cracks		Surface defects	dampness	Condensation	
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Rising damp	
	Corrosion-induced spalling			Rain penetration	
	Cracks due to embedment of dissimilar metals (handrails)			Leaking pipes, spills and other moisture sources	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Surface cracks on wall finishes	crazing
	Premature removal of forms		Map/pattern cracking		
	Cold joints		Efflorescence		
	Segregation		Paint peeling		
	Honeycombing		Mouldiness		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Non-structural cracks	Joint cracks	
	Cantilevered member cracks	<u>Other notes (if available):</u>			
	Settlement cracks				


Case Study #11 (M11)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
		Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Broken axis columns		
		Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration		
			Short column		
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	crazing	
				Map/pattern cracking	
			Efflorescence		
			Paint peeling		
			Mouldiness		
			Wall finishes workmanship problem		
		Staining			
		Non-structural cracks	Joint cracks		
		Reinforced Concrete Defects			
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		<u>Other notes (if available):</u>			


Case Study #12 (M12)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
				Discontinuity of columns or shear walls
			Broken axis columns	
		Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration	
			Short column	
		Non-Structural Defects		
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
				Surface cracks on wall finishes
			crazing	
			Map/pattern cracking	
			Efflorescence	
			Paint peeling	
			Mouldiness	
		Wall finishes workmanship problem		
		Staining		
		Non-structural cracks	Joint cracks	
			<u>Other notes (if available):</u>	
		Reinforced Concrete Defects		
Drying shrinkage cracks				
Corrosion of metals embedded in concrete	Corrosion-induced cracking			
	Corrosion-induced spalling			
	Cracks due to embedment of dissimilar metals (handrails)			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			
	Premature removal of forms			
	Cold joints			
	Segregation			
	Honeycombing			
	Improper grades of slab surfaces			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			
District:	Mağusa			
Area:	Karakol			
Street name:	Zümrüt Sk			
Latitude:	N 35°7.903' (35°7'54.2")			
Longitude:	E 33°55.837' (33°55'50.2")			
Structure age:	<14 years	Date (if available):		
	Between 14 and 43 years (1974-2003)			
	>43 years (Before 1974)			
Building type:	Residential	Apartment		
		House		
		Dormitory		
	Public			
Commercial				
Building status:	Under Construction			
	Occupied			
	Abandoned			


Case Study #13 (M13)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
				Discontinuity of columns or shear walls
Vertical structural element elementary design fault	Broken axis columns			
	Irregular column and/or shear-wall plan configuration			
		Short column		
Non-Structural Defects				
Building status:		Under Construction	Waterproofing defects, water leakage and seepage	
		Occupied	Defected wooden door	
		Abandoned		
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling	
	Premature removal of forms		Mouldiness	
	Cold joints		Wall finishes workmanship problem	
	Segregation	Staining		
	Honeycombing			
	Improper grades of slab surfaces			
		Non-structural cracks	Joint cracks	
<u>Other notes (if available):</u>				
Cracks in RC due to load effects (structural cracks)			Slab/beam-to column shear (punching shear) cracks	
		Cantilevered member cracks		
		Settlement cracks		


Case Study #14 (M14)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Over-stretched one-way slab					
	Poorly supported or heavily loaded cantilevered slabs					
			Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural element elementary design fault	Broken axis columns				
Irregular column and/or shear-wall plan configuration						
			Short column			
Non-Structural Defects						
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	Cracking	cracking			
		Spalling	Map/pattern cracking			
		Cracks due to embedment of dissimilar metals (handrails)	Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Non-structural cracks	Improper reinforcing steel placement	Paint peeling			
		Premature removal of forms	Mouldiness			
		Cold joints	Wall finishes workmanship problem			
		Segregation	Staining			
		Honeycombing	Joint cracks			
Cracks in RC due to load effects (structural cracks)	<u>Other notes (if available):</u>					
						Slab/beam-to column shear (punching shear) cracks
						Cantilevered member cracks
			Settlement cracks			


Case Study #15 (M15)

Profile		Seismic Design Faults																												
		Week column-strong beam																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">District:</td> <td style="text-align: center;">Mağusa</td> </tr> <tr> <td>Area:</td> <td style="text-align: center;">Namık Kemal</td> </tr> <tr> <td>Street name:</td> <td style="text-align: center;">İker Karter Cd</td> </tr> <tr> <td>Latitude:</td> <td style="text-align: center;">35° 6'59.31"N</td> </tr> <tr> <td>Longitude:</td> <td style="text-align: center;">33°56'43.25"E</td> </tr> <tr> <td rowspan="3">Structure age:</td> <td><14 years Date (if available):</td> </tr> <tr> <td>Between 14 and 43 years (1974-2003)</td> </tr> <tr> <td>>43 years (Before 1974)</td> </tr> <tr> <td rowspan="4">Building type:</td> <td>Residential</td> </tr> <tr> <td>Apartment</td> </tr> <tr> <td>House</td> </tr> <tr> <td>Dormitory</td> </tr> <tr> <td>Public</td> </tr> <tr> <td>Commercial</td> </tr> <tr> <td rowspan="3">Building status:</td> <td>Under Construction</td> </tr> <tr> <td>Occupied</td> </tr> <tr> <td>Abandoned</td> </tr> </table>		District:	Mağusa	Area:	Namık Kemal	Street name:	İker Karter Cd	Latitude:	35° 6'59.31"N	Longitude:	33°56'43.25"E	Structure age:	<14 years Date (if available):	Between 14 and 43 years (1974-2003)	>43 years (Before 1974)	Building type:	Residential	Apartment	House	Dormitory	Public	Commercial	Building status:	Under Construction	Occupied	Abandoned	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
		District:	Mağusa																											
		Area:	Namık Kemal																											
		Street name:	İker Karter Cd																											
		Latitude:	35° 6'59.31"N																											
		Longitude:	33°56'43.25"E																											
		Structure age:	<14 years Date (if available):																											
			Between 14 and 43 years (1974-2003)																											
			>43 years (Before 1974)																											
		Building type:	Residential																											
Apartment																														
House																														
Dormitory																														
Public																														
Commercial																														
Building status:	Under Construction																													
	Occupied																													
	Abandoned																													
Floor discontinuity																														
Projections in plan																														
Beam elementary design faults	Non-continuous beams																													
	Non-uniform beam span and cross-section																													
	Absence of vertical support at beams intersection																													
Slab elementary design faults	Broken axis beams and frames																													
	Over-stretched one-way slab																													
Poorly supported or heavily loaded cantilevered slabs																														
Pounding and separation problem																														
Vertical structural configuration	Irregularity in elevation	Weak storey																												
		Soft storey																												
		Discontinuity of columns or shear walls																												
	Vertical structural element elementary design fault	Broken axis columns																												
Irregular column and/or shear-wall plan configuration																														
Short column																														
Non-Structural Defects																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2" style="text-align: center;">Reinforced Concrete Defects</td> </tr> <tr> <td colspan="2" style="text-align: center;">Drying shrinkage cracks</td> </tr> <tr> <td rowspan="3">Corrosion of metals embedded in concrete</td> <td>Corrosion-induced cracking</td> </tr> <tr> <td>Corrosion-induced spalling</td> </tr> <tr> <td>Cracks due to embedment of dissimilar metals (handrails)</td> </tr> <tr> <td rowspan="6">Construction defects (faulty workmanship): designer, detailer, and contractor</td> <td>Improper reinforcing steel placement</td> </tr> <tr> <td>Premature removal of forms</td> </tr> <tr> <td>Cold joints</td> </tr> <tr> <td>Segregation</td> </tr> <tr> <td>Honeycombing</td> </tr> <tr> <td>Improper grades of slab surfaces</td> </tr> <tr> <td rowspan="3">Cracks in RC due to load effects (structural cracks)</td> <td>Slab/beam-to column shear (punching shear) cracks</td> </tr> <tr> <td>Cantilevered member cracks</td> </tr> <tr> <td>Settlement cracks</td> </tr> </table>		Reinforced Concrete Defects		Drying shrinkage cracks		Corrosion of metals embedded in concrete	Corrosion-induced cracking	Corrosion-induced spalling	Cracks due to embedment of dissimilar metals (handrails)	Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Premature removal of forms	Cold joints	Segregation	Honeycombing	Improper grades of slab surfaces	Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Cantilevered member cracks	Settlement cracks	Surface defects	dampness	Waterproofing defects, water leakage and seepage							
		Reinforced Concrete Defects																												
		Drying shrinkage cracks																												
		Corrosion of metals embedded in concrete	Corrosion-induced cracking																											
			Corrosion-induced spalling																											
			Cracks due to embedment of dissimilar metals (handrails)																											
		Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement																											
			Premature removal of forms																											
			Cold joints																											
			Segregation																											
Honeycombing																														
Improper grades of slab surfaces																														
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks																													
	Cantilevered member cracks																													
	Settlement cracks																													
Defected wooden door																														
Condensation																														
Rising damp																														
Rain penetration																														
Surface cracks on wall finishes	Leaking pipes, spills and other moisture sources																													
	crazing																													
	Map/pattern cracking																													
	Efflorescence																													
	Paint peeling																													
Non-structural cracks	Mouldiness																													
	Wall finishes workmanship problem																													
	Staining																													
Joint cracks																														
<u>Other notes (if available):</u>																														


Case Study #16 (M16)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
					Floor discontinuity	
					Projections in plan	
			Beam elementary design faults	Non-continuous beams		
				Non-uniform beam span and cross-section		
Absence of vertical support at beams intersection						
Slab elementary design faults	Over-stretched one-way slab					
	Poorly supported or heavily loaded cantilevered slabs					
				Pounding and separation problem		
District: <b style="color: red;">Mağusa Area: <b style="color: red;">Suriçi Street name: <b style="color: red;">Kışla Yolu Sk Latitude: <b style="color: red;">N 35°7.511' (35°7'30.7") Longitude: <b style="color: red;">E 33°56.462' (33°56'27.7")		Vertical structural configuration	Irregularity in elevation	Weak storey		
				Soft storey		
				Discontinuity of columns or shear walls		
			Vertical structural element elementary design fault	Broken axis columns		
				Irregular column and/or shear-wall plan configuration		
				Short column		
Non-Structural Defects						
Building status: Under Construction Occupied Abandoned		Waterproofing defects, water leakage and seepage				
		Defected wooden door				
Reinforced Concrete Defects						
Drying shrinkage cracks		Surface defects	dampness	Condensation		
Corrosion of metals embedded in concrete Corrosion-induced cracking Corrosion-induced spalling Cracks due to embedment of dissimilar metals (handrails)				Rising damp		
				Rain penetration		
				Leaking pipes, spills and other moisture sources		
Construction defects (faulty workmanship): designer, detailer, and contractor Improper reinforcing steel placement Premature removal of forms Cold joints Segregation Honeycombing Improper grades of slab surfaces			Surface cracks on wall finishes	crazing		
				Map/pattern cracking		
			Efflorescence			
			Paint peeling			
			Mouldiness			
			Wall finishes workmanship problem			
Staining						
		Non-structural cracks	Joint cracks			
<u>Other notes (if available):</u>						
Cracks in RC due to load effects (structural cracks) Slab/beam-to column shear (punching shear) cracks Cantilevered member cracks Settlement cracks						


Case Study #17 (M17)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Beam elementary design faults	Projections in plan
			Slab elementary design faults		Non-continuous beams
					Non-uniform beam span and cross-section
Vertical structural configuration	Irregularity in elevation		Absence of vertical support at beams intersection		
		Broken axis beams and frames			
		Over-stretched one-way slab			
	Vertical structural element elementary design fault	Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
		Weak storey			
Building type:	Residential	Soft storey			
		Discontinuity of columns or shear walls			
		Broken axis columns			
	Public	Irregular column and/or shear-wall plan configuration			
		Short column			
Reinforced Concrete Defects		Non-Structural Defects			
Building status:	Under Construction	Waterproofing defects, water leakage and seepage			
	Occupied	Defected wooden door			
	Abandoned				
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	Leaking pipes, spills and other moisture sources	crazing
					Corrosion-induced spalling
	Cracks due to embedment of dissimilar metals (handrails)	Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Premature removal of forms	Paint peeling		
			Mouldiness		
	Cold joints	Segregation	Wall finishes workmanship problem		
			Staining		
	Honeycombing	Improper grades of slab surfaces	Non-structural cracks	Joint cracks	
			Other notes (if available):		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	The building is for sale			
	Cantilevered member cracks				
	Settlement cracks				


Case Study #18 (M18)

Profile		Seismic Design Faults	
		Week column-strong beam	
		Structural configuration	Horizontal structural configuration
Floor discontinuity			
Beam elementary design faults	Projections in plan		
	Non-continuous beams		
	Non-uniform beam span and cross-section		
Slab elementary design faults	Absence of vertical support at beams intersection		
	Broken axis beams and frames		
District:	Mağusa		
Area:	Baykal		
Street name:	Mustafa Kurtuluş Sk		
Latitude:	N 35°7.236' (35°7'14.2")		
Longitude:	E 33°56.088' (33°56'5.3")		
Structure age:	<14 years	Date (if available):	
	Between 14 and 43 years (1974-2003)		
	>43 years (Before 1974)		■
Building type:	Residential	Apartment	
		House	■
		Dormitory	
	Public		
Commercial			
Building status:	Under Construction		
	Occupied		
	Abandoned		■
Reinforced Concrete Defects		Non-Structural Defects	
Drying shrinkage cracks		Waterproofing defects, water leakage and seepage	
		Defected wooden door	
		Surface defects	dampness
Rising damp			
Rain penetration	■		
Leaking pipes, spills and other moisture sources			
Corrosion of metals embedded in concrete	Corrosion-induced cracking		■
	Corrosion-induced spalling		■
	Cracks due to embedment of dissimilar metals (handrails)		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		
	Premature removal of forms		
	Cold joints		
	Segregation		
	Honeycombing		
	Improper grades of slab surfaces		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		
	Cantilevered member cracks		
	Settlement cracks		■
		Non-structural cracks	
		Joint cracks	
Other notes (if available):			


Case Study #19 (M19)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
			Beam elementary design faults	Projections in plan	
				Non-continuous beams	
		Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
Vertical structural configuration		Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
		Irregularity in elevation	Weak storey		
			Soft storey		
			Discontinuity of columns or shear walls		
Vertical structural element elementary design fault	Broken axis columns				
	Irregular column and/or shear-wall plan configuration				
Short column					
Non-Structural Defects					
Building status:		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
				Surface cracks on wall finishes	crazing
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Map/pattern cracking			
	Corrosion-induced spalling	Efflorescence			
	Cracks due to embedment of dissimilar metals (handrails)	Paint peeling			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Mouldiness			
	Premature removal of forms	Wall finishes workmanship problem			
	Cold joints	Staining			
	Segregation	Non-structural cracks			
	Honeycombing	Joint cracks			
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Other notes (if available):			
	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #20 (M20)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
	Over-stretched one-way slab				
		Pounding and separation problem			
District:	Mağusa	Vertical structural configuration	Irregularity in elevation	Weak storey	
Area:	Sakarya			Soft storey	
Street name:	Köroğlu Sk			Discontinuity of columns or shear walls	
Latitude:	35° 8'7.64"N			Broken axis columns	
Longitude:	33°55'1.04"E	Vertical structural element elementary design fault	Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration	
Structure age:	<14 years			Date (if available):	
	Between 14 and 43 years (1974-2003)				
Building type:	Residential	Apartment			
		House			
		Dormitory			
	Public				
	Commercial				
		Non-Structural Defects			
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing	
	Corrosion-induced spalling			Map/pattern cracking	
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling		
	Premature removal of forms		Mouldiness		
	Cold joints		Wall finishes workmanship problem		
	Segregation		Staining		
	Honeycombing				
Improper grades of slab surfaces		Non-structural cracks	Joint cracks		
Slab/beam-to column shear (punching shear) cracks			<u>Other notes (if available):</u>		
Cracks in RC due to load effects (structural cracks)					
Cantilevered member cracks					
Settlement cracks					


Case Study #21 (M21)

Profile				Seismic Design Faults							
				Week column-strong beam							
				Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)				
Floor discontinuity											
Projections in plan											
Beam elementary design faults	Non-continuous beams										
	Non-uniform beam span and cross-section										
Slab elementary design faults	Absence of vertical support at beams intersection										
	Broken axis beams and frames										
Over-stretched one-way slab											
Poorly supported or heavily loaded cantilevered slabs											
Pounding and separation problem											
Vertical structural configuration	Irregularity in elevation	Weak storey									
		Soft storey									
		Discontinuity of columns or shear walls									
	Vertical structural element elementary design fault	Broken axis columns									
		Irregular column and/or shear-wall plan configuration									
Short column											
Non-Structural Defects											
				Waterproofing defects, water leakage and seepage							
				Defected wooden door							
Reinforced Concrete Defects Drying shrinkage cracks				dampness	Condensation						
					Rising damp						
					Rain penetration						
					Leaking pipes, spills and other moisture sources						
				Surface defects	Surface cracks on wall finishes	crazing					
Map/pattern cracking											
				Efflorescence							
				Paint peeling							
				Mouldiness							
				Wall finishes workmanship problem							
				Staining							
				Non-structural cracks	Joint cracks						
				Other notes (if available):							
				Corrosion of metals embedded in concrete		Corrosion-induced cracking					
						Corrosion-induced spalling					
Cracks due to embedment of dissimilar metals (handrails)											
Construction defects (faulty workmanship): designer, detailer, and contractor		Improper reinforcing steel placement									
		Premature removal of forms									
		Cold joints									
		Segregation									
		Honeycombing									
Cracks in RC due to load effects (structural cracks)		Improper grades of slab surfaces									
		Slab/beam-to column shear (punching shear) cracks									
		Cantilevered member cracks									
		Settlement cracks									


Case Study #22 (M22)

Profile			Seismic Design Faults				
			Week column-strong beam				
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
Floor discontinuity							
Projections in plan							
Beam elementary design faults	Non-continuous beams						
	Non-uniform beam span and cross-section						
Slab elementary design faults	Absence of vertical support at beams intersection						
	Broken axis beams and frames						
	Over-stretched one-way slab						
				Pounding and separation problem			
				Vertical structural configuration	Irregularity in elevation	Weak storey	
			Soft storey				
			Discontinuity of columns or shear walls				
			Vertical structural elementary design fault		Broken axis columns		
					Irregular column and/or shear-wall plan configuration		
			Short column				
Non-Structural Defects							
			Waterproofing defects, water leakage and seepage				
			Defected wooden door				
Reinforced Concrete Defects			Surface defects	dampness	Condensation		
					Rising damp		
					Rain penetration		
					Leaking pipes, spills and other moisture sources		
			Surface cracks on wall finishes	crazing			
				Map/pattern cracking			
			Efflorescence				
			Paint peeling				
			Mouldiness				
			Wall finishes workmanship problem				
			Staining				
			Non-structural cracks	Joint cracks			
Other notes (if available):							
						Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks
							Cantilevered member cracks
							Settlement cracks


Case Study #23 (M23)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem	
			Vertical structural configuration	Irregularity in elevation
		Soft storey		
		Discontinuity of columns or shear walls		
		Vertical structural element elementary design fault		Broken axis columns
				Irregular column and/or shear-wall plan configuration
		Short column		
Non-Structural Defects				
Building status:		Under Construction		
		Occupied		
		Abandoned		
Reinforced Concrete Defects				
Drying shrinkage cracks				
Surface defects	dampness	Waterproofing defects, water leakage and seepage		
		Defected wooden door		
		Condensation		
		Rising damp		
		Rain penetration		
		Leaking pipes, spills and other moisture sources		
		Surface cracks on wall finishes	crazing	
			Map/pattern cracking	
		Efflorescence		
		Paint peeling		
		Mouldiness		
		Wall finishes workmanship problem		
		Staining		
		Non-structural cracks	Joint cracks	
Other notes (if available):				
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks		
		Cantilevered member cracks		
		Settlement cracks		
<p style="color: red;">The structural system of this house is mixed between loadbearing walls and reinforced concrete frames.</p>				


Case Study #24 (M24)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
			Over-stretched one-way slab			
			Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem			
			Vertical structural configuration	Irregularity in elevation	Weak storey	
					Soft storey	
				Discontinuity of columns or shear walls		
				Vertical structural element elementary design fault	Broken axis columns	
			Irregular column and/or shear-wall plan configuration			
			Short column			
Non-Structural Defects						
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
	Surface cracks on wall finishes	crazing				
		Map/pattern cracking				
		Efflorescence				
			Paint peeling			
			Mouldiness			
			Wall finishes workmanship problem			
			Staining			
			Non-structural cracks	Joint cracks		
Other notes (if available):						
Cracks in RC due to load effects (structural cracks)						Slab/beam-to column shear (punching shear) cracks
						Cantilevered member cracks
						Settlement cracks


Case Study #25 (M25)

Profile			Seismic Design Faults		
			Week column-strong beam		
			Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
			Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural element elementary design fault	Broken axis columns			
Irregular column and/or shear-wall plan configuration					
			Short column		
Non-Structural Defects					
			Waterproofing defects, water leakage and seepage		
			Defected wooden door		
Surface defects	dampness	Condensation			
		Rising damp			
Rain penetration					
Leaking pipes, spills and other moisture sources					
Surface defects	Surface cracks on wall finishes	cracking			
		Map/pattern cracking			
Surface defects	Efflorescence				
	Paint peeling				
Surface defects	Mouldiness				
	Wall finishes workmanship problem				
Surface defects	Staining				
		Non-structural cracks	Joint cracks		
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces				
	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
			Settlement cracks		
Other notes (if available):					


Case Study #26 (I1)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
					Floor discontinuity	
					Projections in plan	
			Beam elementary design faults	Non-continuous beams		
				Non-uniform beam span and cross-section		
Absence of vertical support at beams intersection						
Slab elementary design faults	Broken axis beams and frames					
	Over-stretched one-way slab					
Poorly supported or heavily loaded cantilevered slabs						
				Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural element elementary design fault	Broken axis columns				
		Irregular column and/or shear-wall plan configuration				
				Short column		
Non-Structural Defects						
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned					
Reinforced Concrete Defects						
Drying shrinkage cracks						
Corrosion of metals embedded in concrete	Corrosion-induced cracking					
	Corrosion-induced spalling					
	Cracks due to embedment of dissimilar metals (handrails)					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					
		Surface defects		Non-structural cracks		
		dampness	Condensation			
			Rising damp			
			Rain penetration			
		Leaking pipes, spills and other moisture sources				
		Surface cracks on wall finishes	crazing			
			Map/pattern cracking			
		Efflorescence				
		Paint peeling				
		Mouldiness				
		Wall finishes workmanship problem				
		Staining				
		Joint cracks				
Other notes (if available):						
Rain penetration in this case is evident on the terrace which acts as a flat roof (not the pitched roof)						


Case Study #27 (12)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
			Beam elementary design faults	Projections in plan	
				Non-continuous beams	
		Vertical structural configuration	Irregularity in elevation	Slab elementary design faults	Non-uniform beam span and cross-section
					Absence of vertical support at beams intersection
					Broken axis beams and frames
		Structure age:		Over-stretched one-way slab	
				Poorly supported or heavily loaded cantilevered slabs	
Building status:		Pounding and separation problem			
		Weak storey			
Building type:		Soft storey			
		Discontinuity of columns or shear walls			
Building status:		Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
Building status:		Short column			
		Non-Structural Defects			
Reinforced Concrete Defects		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Drying shrinkage cracks		Condensation			
		Rising damp			
Corrosion of metals embedded in concrete		Rain penetration			
		Leaking pipes, spills and other moisture sources			
Construction defects (faulty workmanship): designer, detailer, and contractor		Surface cracks on wall finishes			
		crazing			
Cracks in RC due to load effects (structural cracks)		Map/pattern cracking			
		Efflorescence			
Cracks in RC due to load effects (structural cracks)		Paint peeling			
		Mouldiness			
Cracks in RC due to load effects (structural cracks)		Wall finishes workmanship problem			
		Staining			
Cracks in RC due to load effects (structural cracks)		Non-structural cracks			
		Joint cracks			
Cracks in RC due to load effects (structural cracks)		Other notes (if available):			
		Rain penetration here is acting on the terrace acting as a flat roof (not the pitched roof)			


Case Study #28 (I3)

Profile		Seismic Design Faults					
		Week column-strong beam					
District:	İskele	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
Area:	Boğaz				Beam elementary design faults	Floor discontinuity	
Street name:	Karpaz Anayolu					Projections in plan	
Latitude:	35°18'49.24"N			Non-continuous beams			
Longitude:	33°57'7.29"E			Non-uniform beam span and cross-section			
Structure age:	<14 years			Slab elementary design faults	Absence of vertical support at beams intersection		
	Between 14 and 43 years (1974-2003)		Broken axis beams and frames				
	>43 years (Before 1974)		Over-stretched one-way slab				
Building type:	Residential		Vertical structural configuration	Irregularity in elevation	Poorly supported or heavily loaded cantilevered slabs		
	Apartment				Pounding and separation problem		
	House	Weak storey					
	Dormitory	Soft storey					
	Public	Vertical structural elementary design fault	Vertical structural elementary design fault	Discontinuity of columns or shear walls			
	Commercial			Broken axis columns			
	Under Construction			Irregular column and/or shear-wall plan configuration			
Building status:	Occupied	Non-Structural Defects					
Reinforced Concrete Defects		Waterproofing defects, water leakage and seepage					
Drying shrinkage cracks		Defected wooden door					
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface defects	dampness	Condensation			
	Corrosion-induced spalling			Rising damp			
	Cracks due to embedment of dissimilar metals (handrails)			Rain penetration			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Leaking pipes, spills and other moisture sources			
	Premature removal of forms			Surface cracks on wall finishes	crazing		
	Cold joints		Map/pattern cracking				
	Segregation		Efflorescence				
	Honeycombing		Paint peeling				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Mouldiness				
	Cantilevered member cracks		Wall finishes workmanship problem				
	Settlement cracks	Staining					
		Non-structural cracks	Joint cracks				
		<u>Other notes (if available):</u>					


Case Study # Case Study # 29 (I4)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Projections in plan			
	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
	Over-stretched one-way slab			
			Poorly supported or heavily loaded cantilevered slabs	
			Pounding and separation problem	
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
			Discontinuity of columns or shear walls	
			Broken axis columns	
			Irregular column and/or shear-wall plan configuration	
		Vertical structural elementary design fault		
		Short column		
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
		Surface cracks on wall finishes	Surface cracks	crazing
				Map/pattern cracking
				Efflorescence
				Paint peeling
				Mouldiness
				Wall finishes workmanship problem
				Staining
		Non-structural cracks	Joint cracks	
Reinforced Concrete Defects				
Drying shrinkage cracks				
Corrosion of metals embedded in concrete	Corrosion-induced cracking			
	Corrosion-induced spalling			
	Cracks due to embedment of dissimilar metals (handrails)			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			
	Premature removal of forms			
	Cold joints			
	Segregation			
	Honeycombing			
	Improper grades of slab surfaces			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			
<u>Other notes (if available):</u>				
<p style="color: red;">This non-functional hotel was hosting what seemed to be like construction workers who were sleeping there.</p>				


Case Study #30 (15)

Profile		Seismic Design Faults						
		Week column-strong beam						
District:	İskele	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)			
Area:	Boğaztepe			Beam elementary design faults	Slab elementary design faults	Floor discontinuity		
Street name:	Cumhuriyet Sk					Projections in plan		
Latitude:	35°18'56.58"N					Non-continuous beams		
Longitude:	33°56'49.87"E					Non-uniform beam span and cross-section		
Structure age:	<14 years			Absence of vertical support at beams intersection				
	Between 14 and 43 years (1974-2003)			Broken axis beams and frames				
	>43 years (Before 1974)			Over-stretched one-way slab				
Building type:	Residential			Poorly supported or heavily loaded cantilevered slabs				
	Apartment			Pounding and separation problem				
	House	Vertical structural configuration	Irregularity in elevation	Weak storey				
	Dormitory			Soft storey				
Public	Vertical structural element elementary design fault	Discontinuity of columns or shear walls	Broken axis columns					
Commercial			Irregular column and/or shear-wall plan configuration					
Building status:	Under Construction	Short column						
	Occupied	Non-Structural Defects						
	Abandoned	Waterproofing defects, water leakage and seepage						
Reinforced Concrete Defects		Surface defects	dampness	Defected wooden door				
Drying shrinkage cracks				Condensation				
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Rising damp				
	Corrosion-induced spalling			Rain penetration				
	Cracks due to embedment of dissimilar metals (handrails)			Leaking pipes, spills and other moisture sources				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Surface cracks on wall finishes	crazing			
	Premature removal of forms				Map/pattern cracking			
	Cold joints			Efflorescence				
	Segregation			Paint peeling				
	Honeycombing			Mouldiness				
	Improper grades of slab surfaces	Wall finishes workmanship problem						
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Non-structural cracks	Staining					
	Cantilevered member cracks		Joint cracks					
	Settlement cracks		Other notes (if available):					


Case Study #31 (I6)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
Vertical structural configuration	Irregularity in elevation		Over-stretched one-way slab	
			Poorly supported or heavily loaded cantilevered slabs	
	Pounding and separation problem			
	Vertical structural element elementary design fault	Weak storey		
		Soft storey		
Discontinuity of columns or shear walls				
Building type:	Broken axis columns			
	Irregular column and/or shear-wall plan configuration			
	Short column			
Reinforced Concrete Defects		Non-Structural Defects		
District:	İskele	Waterproofing defects, water leakage and seepage		
	Area:	Yarköy (Agios Ilias)	Defected wooden door	
Street name:	No street names were found in the village	Surface defects	dampness	Condensation
Latitude:	35°19'32.95"N			Rising damp
Longitude:	33°55'48.85"E			Rain penetration
Structure age:	<14 years			Date (if available):
	Between 14 and 43 years (1974-2003)			Surface cracks on wall finishes
	>43 years (Before 1974)			
Building type:	Residential		Apartment	Map/pattern cracking
			House	Efflorescence
			Dormitory	Paint peeling
Building status:	Public		Mouldiness	Non-structural cracks
	Commercial	Wall finishes workmanship problem		
	Under Construction	Abandoned	Staining	
Drying shrinkage cracks		Other notes (if available):		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Cracks in RC due to load effects (structural cracks)	Settlement cracks
	Corrosion-induced spalling			
	Cracks due to embedment of dissimilar metals (handrails)			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			
	Premature removal of forms			
	Cold joints			
	Segregation			
	Honeycombing			
Improper grades of slab surfaces				


Case Study #32 (17)

Profile			Seismic Design Faults		
			Week column-strong beam		
			Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
			Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural elementary design fault	Broken axis columns			
Irregular column and/or shear-wall plan configuration					
			Short column		
Non-Structural Defects					
			Waterproofing defects, water leakage and seepage		
			Defected wooden door		
Reinforced Concrete Defects			Surface defects	dampness	Condensation
					Rising damp
					Rain penetration
					Leaking pipes, spills and other moisture sources
				Surface cracks on wall finishes	cr crazing
Map/pattern cracking					
Corrosion of metals embedded in concrete	Efflorescence				
	Paint peeling				
	Mouldiness				
	Wall finishes workmanship problem				
	Staining				
	Non-structural cracks	Joint cracks			
				<u>Other notes (if available):</u>	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
Cracks in RC due to load effects (structural cracks)	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #33 (I8)

Profile		Seismic Design Faults													
		Week column-strong beam													
District:	İskele	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)										
Area:	Yeni İskele (Trikomo)				Beam elementary design faults	Floor discontinuity									
Street name:	Onay Fadıl Demirciler Cd					Projections in plan									
Latitude:	35°16'59.57"N			Slab elementary design faults	Non-continuous beams										
Longitude:	33°53'36.26"E				Non-uniform beam span and cross-section										
Structure age:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%; text-align: center;"><14 years</td> <td>Date (if available):</td> <td></td> </tr> <tr> <td style="text-align: center;">Between 14 and 43 years (1974-2003)</td> <td></td> <td style="background-color: red;"></td> </tr> <tr> <td style="text-align: center;">>43 years (Before 1974)</td> <td></td> <td></td> </tr> </table>		<14 years	Date (if available):		Between 14 and 43 years (1974-2003)			>43 years (Before 1974)			Vertical structural configuration	Irregularity in elevation	Absence of vertical support at beams intersection	
<14 years	Date (if available):														
Between 14 and 43 years (1974-2003)															
>43 years (Before 1974)															
Building type:	Residential		Apartment	Broken axis beams and frames											
		House	Over-stretched one-way slab												
		Dormitory	Poorly supported or heavily loaded cantilevered slabs												
	Public		Pounding and separation problem												
	Commercial		Weak storey												
Building status:	Under Construction		Soft storey												
	Occupied		Discontinuity of columns or shear walls												
	Abandoned		Broken axis columns												
Reinforced Concrete Defects			Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration											
Drying shrinkage cracks				Short column											
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Non-Structural Defects												
	Corrosion-induced spalling		Waterproofing defects, water leakage and seepage												
	Cracks due to embedment of dissimilar metals (handrails)		Defected wooden door												
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Surface defects	dampness	Condensation										
	Premature removal of forms				Rising damp										
	Cold joints				Rain penetration										
	Segregation			Leaking pipes, spills and other moisture sources											
	Honeycombing			Surface cracks on wall finishes	crazing										
	Improper grades of slab surfaces		Map/pattern cracking												
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			Efflorescence											
	Cantilevered member cracks			Paint peeling											
	Settlement cracks			Mouldiness											
			Non-structural cracks	Wall finishes workmanship problem											
				Staining											
				Joint cracks											
			<u>Other notes (if available):</u>												


Case Study #34 (I9)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
					Floor discontinuity	
					Projections in plan	
			Beam elementary design faults	Non-continuous beams		
				Non-uniform beam span and cross-section		
				Absence of vertical support at beams intersection		
		Slab elementary design faults	Over-stretched one-way slab			
			Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem				
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural element elementary design fault	Broken axis columns				
		Irregular column and/or shear-wall plan configuration				
		Short column				
Non-Structural Defects						
Building status:	Waterproofing defects, water leakage and seepage					
	Defected wooden door					
	Condensation					
Reinforced Concrete Defects						
Drying shrinkage cracks						
Corrosion of metals embedded in concrete	Corrosion-induced cracking					
	Corrosion-induced spalling					
	Cracks due to embedment of dissimilar metals (handrails)					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					
Surface defects						
Surface defects	dampness	Leaking pipes, spills and other moisture sources				
		Rising damp				
		Rain penetration				
		Condensation				
	Surface cracks on wall finishes	crazing				
		Map/pattern cracking				
	Efflorescence					
	Paint peeling					
Mouldiness						
Wall finishes workmanship problem						
Staining						
Non-structural cracks		Joint cracks				
<u>Other notes (if available):</u>						


Case Study #35(I10)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural elementary design fault	Broken axis columns			
Irregular column and/or shear-wall plan configuration					
		Short column			
Non-Structural Defects					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	cr crazing	
	Corrosion-induced spalling			Map/pattern cracking	
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling		
	Premature removal of forms		Mouldiness		
	Cold joints		Wall finishes workmanship problem		
	Segregation		Staining		
	Honeycombing				
		Non-structural cracks	Joint cracks		
<u>Other notes (if available):</u>					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #36 (İ11)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
Vertical structural elementary design fault	Discontinuity of columns or shear walls			
	Broken axis columns			
		Irregular column and/or shear-wall plan configuration		
		Short column		
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface cracks on wall finishes	cracking	
	Corrosion-induced spalling		Map/pattern cracking	
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Non-structural cracks	Paint peeling	
	Premature removal of forms		Mouldiness	
	Cold joints		Wall finishes workmanship problem	
	Segregation		Staining	
	Honeycombing		Joint cracks	
	Improper grades of slab surfaces			
Other notes (if available):				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			
District:	İskele			
Area:	Yeni İskele (Trikomo)			
Street name:	Şht. Üstteğmen Mustafa Orhan Cd			
Latitude:	35°17'0.28"N			
Longitude:	33°53'26.69"E			
Structure age:	<14 years	Date (if available):		
	Between 14 and 43 years (1974-2003)			
	>43 years (Before 1974)			
Building type:	Residential	Apartment		
		House		
		Dormitory		
	Public			
Commercial				
Building status:	Under Construction			
	Occupied			
	Abandoned			


Case Study #37 (İ12)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
			Beam elementary design faults	Projections in plan	
				Non-continuous beams	
		Vertical structural configuration	Irregularity in elevation	Non-uniform beam span and cross-section	
				Absence of vertical support at beams intersection	
				Broken axis beams and frames	
		Slab elementary design faults	Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs		
		Pounding and separation problem			
		Vertical structural configuration	Weak storey		
			Soft storey		
			Discontinuity of columns or shear walls		
			Broken axis columns		
		Vertical structural elementary design fault	Irregular column and/or shear-wall plan configuration		
			Short column		
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness		
			Condensation		
			Rising damp		
			Rain penetration		
			Leaking pipes, spills and other moisture sources		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing	
	Corrosion-induced spalling			Map/pattern cracking	
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)			Efflorescence	
	Improper reinforcing steel placement			Paint peeling	
	Premature removal of forms			Mouldiness	
	Cold joints	Non-structural cracks	Wall finishes workmanship problem		
	Segregation		Staining		
	Honeycombing	Joint cracks			
Improper grades of slab surfaces	<u>Other notes (if available):</u>				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #38 (İ13)

Profile			Seismic Design Faults							
			Week column-strong beam							
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)				
						Floor discontinuity				
				Beam elementary design faults	Projections in plan					
					Non-continuous beams					
			Non-uniform beam span and cross-section							
Slab elementary design faults	Absence of vertical support at beams intersection									
	Broken axis beams and frames									
			Over-stretched one-way slab							
			Poorly supported or heavily loaded cantilevered slabs							
			Pounding and separation problem							
			Vertical structural configuration	Irregularity in elevation	Weak storey					
					Soft storey					
				Vertical structural element elementary design fault	Discontinuity of columns or shear walls					
					Broken axis columns					
					Irregular column and/or shear-wall plan configuration					
					Short column					
Non-Structural Defects										
			Waterproofing defects, water leakage and seepage							
			Defected wooden door							
Reinforced Concrete Defects			Surface defects			dampness				
						Condensation				
			Rising damp							
			Rain penetration							
Leaking pipes, spills and other moisture sources										
Surface cracks on wall finishes		crazing								
		Map/pattern cracking								
Efflorescence										
Paint peeling										
Mouldiness										
Wall finishes workmanship problem										
Staining										
			Non-structural cracks		Joint cracks					
Other notes (if available):										
			Non-structural cracks							
								Slab/beam-to column shear (punching shear) cracks		
								Cantilevered member cracks		
Cracks in RC due to load effects (structural cracks)			Non-structural cracks			Settlement cracks				
District:			İskele							
Area:			Yeni İskele (Trikomo)							
Street name:			20 Temmuz Cd							
Latitude:			35°17'7.94"N							
Longitude:			33°53'52.27"E							
Structure age:			<14 years		Date (if available):					
			Between 14 and 43 years (1974-2003)							
			>43 years (Before 1974)							
Building type:			Residential		Apartment					
					House					
					Dormitory					
			Public							
Commercial										
Building status:			Under Construction							
			Occupied							
			Abandoned							


Case Study #39 (İ14)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Broken axis beams and frames					
	Over-stretched one-way slab					
Poorly supported or heavily loaded cantilevered slabs						
Pounding and separation problem						
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural element elementary design fault	Broken axis columns				
Irregular column and/or shear-wall plan configuration						
Short column						
Non-Structural Defects						
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned					
Reinforced Concrete Defects						
Drying shrinkage cracks		Surface defects	dampness	Condensation		
				Rising damp		
				Rain penetration		
				Leaking pipes, spills and other moisture sources		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing		
	Corrosion-induced spalling			Map/pattern cracking		
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling			
	Premature removal of forms		Mouldiness			
	Cold joints		Wall finishes workmanship problem			
	Segregation		Staining			
	Honeycombing		Non-structural cracks		Joint cracks	
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		<u>Other notes (if available):</u>			
	Cantilevered member cracks					
	Settlement cracks					


Case Study #40 (İ15)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Broken axis beams and frames					
	Over-stretched one-way slab					
Poorly supported or heavily loaded cantilevered slabs						
Pounding and separation problem						
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural element elementary design fault	Broken axis columns				
Irregular column and/or shear-wall plan configuration						
Short column						
Non-Structural Defects						
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned					
Reinforced Concrete Defects						
Drying shrinkage cracks			Surface defects	dampness	Condensation	
Corrosion of metals embedded in concrete					Corrosion-induced cracking	Rising damp
					Corrosion-induced spalling	Rain penetration
					Cracks due to embedment of dissimilar metals (handrails)	Leaking pipes, spills and other moisture sources
Construction defects (faulty workmanship): designer, detailer, and contractor				Improper reinforcing steel placement	Surface cracks on wall finishes	Surface cracks crazing
				Premature removal of forms		Map/pattern cracking
				Cold joints	Efflorescence	
				Segregation	Paint peeling	
Honeycombing	Mouldiness					
Improper grades of slab surfaces	Wall finishes workmanship problem					
Cracks in RC due to load effects (structural cracks)			Non-structural cracks		Staining	
			Joint cracks			
			Other notes (if available):			
Slab/beam-to column shear (punching shear) cracks						
Cantilevered member cracks						
Settlement cracks						


Case Study #41 (İ16)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
	Over-stretched one-way slab				
			Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation		Weak storey		
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural elementary design fault	Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
		Short column			
Non-Structural Defects					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	cr crazing	
Map/pattern cracking					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)				
	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		Non-structural cracks		Joint cracks	
<u>Other notes (if available):</u>					


Case Study #42 (İ17)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
District: İskele Area: Mehmetçik (Galateia) Street name: No street names were found Latitude: 35°25'7.67"N Longitude: 34° 4'12.76"E		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Vertical structural elementary design fault	Broken axis columns	
Irregular column and/or shear-wall plan configuration					
Short column					
Non-Structural Defects					
Building status:		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing	
	Corrosion-induced spalling			Map/pattern cracking	
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence		
	Improper reinforcing steel placement		Paint peeling		
	Premature removal of forms		Mouldiness		
	Cold joints		Wall finishes workmanship problem		
	Segregation	Staining			
	Honeycombing	Non-structural cracks	Joint cracks		
Cracks in RC due to load effects (structural cracks)		Other notes (if available):			
		Slab/beam-to column shear (punching shear) cracks			
		Cantilevered member cracks			
		Settlement cracks			


Case Study #43 (I18)

Profile			Seismic Design Faults				
			Week column-strong beam				
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
						Floor discontinuity	
						Projections in plan	
					Beam elementary design faults	Non-continuous beams	
						Non-uniform beam span and cross-section	
				Slab elementary design faults	Absence of vertical support at beams intersection		
					Broken axis beams and frames		
					Over-stretched one-way slab		
							Poorly supported or heavily loaded cantilevered slabs
				Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey					
		Soft storey					
		Discontinuity of columns or shear walls					
	Vertical structural elementary design fault	Broken axis columns					
		Irregular column and/or shear-wall plan configuration					
		Short column					
Non-Structural Defects							
Building status:	Under Construction			Waterproofing defects, water leakage and seepage			
	Occupied			Defected wooden door			
	Abandoned						
Reinforced Concrete Defects							
Drying shrinkage cracks			Surface defects	dampness			
Corrosion of metals embedded in concrete	Corrosion-induced cracking				Condensation		
	Corrosion-induced spalling				Rising damp		
	Cracks due to embedment of dissimilar metals (handrails)				Rain penetration		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Leaking pipes, spills and other moisture sources			
	Premature removal of forms			Surface cracks on wall finishes	crazing		
	Cold joints				Map/pattern cracking		
	Segregation			Efflorescence			
	Honeycombing			Paint peeling			
	Improper grades of slab surfaces			Mouldiness			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Wall finishes workmanship problem				
	Cantilevered member cracks		Staining				
	Settlement cracks		Non-structural cracks	Joint cracks			
			<u>Other notes (if available):</u>				


Case Study #44 (I19)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
District: İskele			Over-stretched one-way slab			
Area: Pamuklu (Tavros)			Poorly supported or heavily loaded cantilevered slabs			
Street name: No street names were found			Pounding and separation problem			
Latitude: 35°23'42.23"N			Vertical structural configuration			
Longitude: 34° 4'38.86"E						
Structure age:	<14 years	Date (if available):	Irregularity in elevation	Weak storey		
	Between 14 and 43 years (1974-2003)			Soft storey		
	>43 years (Before 1974)			Discontinuity of columns or shear walls		
Building type:	Residential	Apartment	Vertical structural elementary design fault	Broken axis columns		
		House		Irregular column and/or shear-wall plan configuration		
		Dormitory				
	Public			Short column		
Commercial			Non-Structural Defects			
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned					
Reinforced Concrete Defects						
Drying shrinkage cracks			Surface defects	dampness	Condensation	
Corrosion of metals embedded in concrete					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
				Surface cracks on wall finishes	crazing	
Map/pattern cracking						
Construction defects (faulty workmanship): designer, detailer, and contractor			Non-structural cracks	Efflorescence		
				Paint peeling		
				Mouldiness		
				Wall finishes workmanship problem		
Cracks in RC due to load effects (structural cracks)			Other notes (if available):	Staining		
				Joint cracks		
Slab/beam-to column shear (punching shear) cracks						
Cantilevered member cracks						
Settlement cracks						


Case Study #45 (İ20)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District:	İskele				
Area:	Pamuklu (Tavros)				
Street name:	No street names were found				
Latitude:	N 35°23.709'				
Longitude:	E 34°4.622'				
Structure age:	<14 years	Date (if available):			
	Between 14 and 43 years (1974-2003)				
	>43 years (Before 1974)				
Building type:	Residential	Apartment			
		House			
		Dormitory			
	Public				
	Commercial				
Building status:	Under Construction				
	Occupied				
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces				
	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
		Vertical structural element elementary design fault	Short column	Discontinuity of columns or shear walls	
				Broken axis columns	
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	crazing	Map/pattern cracking
					Efflorescence
					Paint peeling
				Mouldiness	
				Wall finishes workmanship problem	
				Staining	
		Non-structural cracks		Joint cracks	
<u>Other notes (if available):</u>					


Case Study #46 (İ21)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Projections in plan			
	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
District:	İskele	Over-stretched one-way slab		
Area:	Derince (Vathylakas)	Poorly supported or heavily loaded cantilevered slabs		
Street name:	No street names were found	Pounding and separation problem		
Latitude:	N 35°28.965' (35°28'57.9")	Vertical structural configuration	Irregularity in elevation	Weak storey
Longitude:	E 34°10.945' (34°10'56.7")			Soft storey
Structure age:	<14 years	Date (if available):	Discontinuity of columns or shear walls	
	Between 14 and 43 years (1974-2003)		Broken axis columns	
	>43 years (Before 1974)		Irregular column and/or shear-wall plan configuration	
Building type:	Residential	Apartment	Vertical structural elementary design fault	Short column
		House		
		Dormitory		
	Public	Non-Structural Defects		
Building status:	Commercial	Waterproofing defects, water leakage and seepage		
	Under Construction	Defected wooden door		
	Occupied	Surface defects	dampness	Condensation
Abandoned	Rising damp			
Reinforced Concrete Defects				Rain penetration
Drying shrinkage cracks				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface cracks on wall finishes	Non-structural cracks	crazing
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)	Efflorescence	Joint cracks	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Paint peeling		
	Premature removal of forms	Mouldiness		
	Cold joints	Wall finishes workmanship problem		
	Segregation	Staining		
	Honeycombing			
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Other notes (if available):		
	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			


Case Study #47(I22)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Broken axis beams and frames					
	Over-stretched one-way slab					
			Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem			
District: İskele			Vertical structural configuration	Irregularity in elevation	Weak storey	
					Soft storey	
Discontinuity of columns or shear walls						
Area: Derince (Vathylakas)				Vertical structural elementary design fault	Broken axis columns	
					Irregular column and/or shear-wall plan configuration	
Street name: No street names were found				Short column		
Latitude: 35°28'57.50"N			Non-Structural Defects			
Longitude: 34°10'54.63"E			Waterproofing defects, water leakage and seepage			
Structure age:	<14 years	Date (if available):	Defected wooden door			
	Between 14 and 43 years (1974-2003)		Condensation			
	>43 years (Before 1974)		Rising damp			
Building type:	Residential	Apartment	Rain penetration			
		House	Leaking pipes, spills and other moisture sources			
		Dormitory	Surface cracks on wall finishes			
	Public	crazing				
Commercial			Map/pattern cracking			
Building status:			Efflorescence			
			Paint peeling			
Reinforced Concrete Defects			Mouldiness			
			Wall finishes workmanship problem			
Drying shrinkage cracks			Staining			
			Non-structural cracks			
Corrosion of metals embedded in concrete			Joint cracks			
			Surface defects			
Construction defects (faulty workmanship): designer, detailer, and contractor			Other notes (if available):			
			Surface defects			
Cracks in RC due to load effects (structural cracks)			Surface defects			
			Surface defects			
Slab/beam-to column shear (punching shear) cracks			Surface defects			
			Surface defects			
Cantilevered member cracks			Surface defects			
			Surface defects			
Settlement cracks			Surface defects			
			Surface defects			


Case Study #48 (I23)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District: İskele		Over-stretched one-way slab			
Area: Derince (Vathylakas)		Poorly supported or heavily loaded cantilevered slabs			
Street name: No street names were found		Pounding and separation problem			
Latitude: 35°28'53.97"N		Vertical structural configuration	Irregularity in elevation	Weak storey	
Longitude: 34°10'59.01"E				Soft storey	
Structure age:	<14 years			Date (if available):	Discontinuity of columns or shear walls
	Between 14 and 43 years (1974-2003)			Broken axis columns	
	>43 years (Before 1974)		Irregular column and/or shear-wall plan configuration		
Building type:	Residential	Apartment	Vertical structural elementary design fault	Short column	
		House			
		Dormitory			
	Public	Non-Structural Defects			
Commercial		Waterproofing defects, water leakage and seepage			
Building status:	Under Construction		Defected wooden door		
	Occupied		Dampness		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
Corrosion of metals embedded in concrete				Surface cracks on wall finishes	Rising damp
					Rain penetration
				Construction defects (faulty workmanship): designer, detailer, and contractor	
crazing					
Map/pattern cracking					
Cracks in RC due to load effects (structural cracks)			Other notes (if available):	Efflorescence	
				Paint peeling	
				Mouldiness	
				Wall finishes workmanship problem	
Cracks in RC due to load effects (structural cracks)		Staining			
		Joint cracks			
		Settlement cracks			


Case Study #49 (İ24)

Profile		Seismic Design Faults												
		Week column-strong beam												
District:	İskele	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)									
Area:	Taşlıca (Neta)				Beam elementary design faults	Floor discontinuity								
Street name:	No street names were found					Projections in plan								
Latitude:	35°28'9.85"N		Non-continuous beams											
Longitude:	34°12'52.80"E		Non-uniform beam span and cross-section											
Structure age:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;"><14 years</td> <td>Date (if available):</td> <td></td> </tr> <tr> <td>Between 14 and 43 years (1974-2003)</td> <td></td> <td></td> </tr> <tr> <td>>43 years (Before 1974)</td> <td></td> <td style="background-color: red;"></td> </tr> </table>		<14 years	Date (if available):		Between 14 and 43 years (1974-2003)			>43 years (Before 1974)			Vertical structural configuration	Irregularity in elevation	Absence of vertical support at beams intersection
<14 years	Date (if available):													
Between 14 and 43 years (1974-2003)														
>43 years (Before 1974)														
Building type:	Residential	Broken axis beams and frames												
		Over-stretched one-way slab												
Building status:	Under Construction	Poorly supported or heavily loaded cantilevered slabs												
		Occupied	Pounding and separation problem											
Building status:	Abandoned	Weak storey												
		Commercial	Soft storey											
Building status:	Abandoned	Discontinuity of columns or shear walls												
		Public	Broken axis columns											
Building status:	Abandoned	Irregular column and/or shear-wall plan configuration												
		Commercial	Short column											
Reinforced Concrete Defects		Non-Structural Defects												
Drying shrinkage cracks		Waterproofing defects, water leakage and seepage												
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface defects	dampness	Defected wooden door										
	Corrosion-induced spalling			Condensation										
	Cracks due to embedment of dissimilar metals (handrails)			Rising damp										
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Rain penetration											
	Premature removal of forms		Leaking pipes, spills and other moisture sources											
	Cold joints		Surface cracks on wall finishes	crazing										
	Segregation	Efflorescence	Map/pattern cracking											
	Honeycombing	Paint peeling												
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Mouldiness												
	Cantilevered member cracks	Wall finishes workmanship problem												
	Settlement cracks	Staining												
		Non-structural cracks		Joint cracks										
		<u>Other notes (if available):</u>												


Case Study #50 (İ25)

Profile		Seismic Design Faults																															
		Week column-strong beam																															
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)																												
					Floor discontinuity																												
					Projections in plan																												
			Beam elementary design faults	Non-continuous beams																													
				Non-uniform beam span and cross-section																													
				Absence of vertical support at beams intersection																													
		Slab elementary design faults	Over-stretched one-way slab																														
			Poorly supported or heavily loaded cantilevered slabs																														
		Pounding and separation problem																															
Vertical structural configuration	Irregularity in elevation	Weak storey																															
		Soft storey																															
		Discontinuity of columns or shear walls																															
	Vertical structural element elementary design fault	Broken axis columns																															
		Irregular column and/or shear-wall plan configuration																															
Short column																																	
Non-Structural Defects																																	
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>District:</td> <td style="text-align: center;">İskele</td> </tr> <tr> <td>Area:</td> <td style="text-align: center;">St Andrew (Apostolos Andreas)</td> </tr> <tr> <td>Street name:</td> <td style="text-align: center;">Karpaz Anayolu</td> </tr> <tr> <td>Latitude:</td> <td style="text-align: center;">35°39'28.61"N</td> </tr> <tr> <td>Longitude:</td> <td style="text-align: center;">34°34'27.31"E</td> </tr> <tr> <td rowspan="3">Structure age:</td> <td><14 years</td> <td>Date (if available):</td> </tr> <tr> <td>Between 14 and 43 years (1974-2003)</td> <td></td> </tr> <tr> <td>>43 years (Before 1974)</td> <td></td> </tr> <tr> <td rowspan="4">Building type:</td> <td rowspan="3">Residential</td> <td>Apartment</td> </tr> <tr> <td>House</td> </tr> <tr> <td>Dormitory</td> </tr> <tr> <td>Public</td> <td></td> </tr> <tr> <td>Commercial</td> <td></td> </tr> <tr> <td rowspan="3">Building status:</td> <td>Under Construction</td> </tr> <tr> <td>Occupied</td> </tr> <tr> <td>Abandoned</td> </tr> </table>		District:	İskele	Area:	St Andrew (Apostolos Andreas)	Street name:	Karpaz Anayolu	Latitude:	35°39'28.61"N	Longitude:	34°34'27.31"E	Structure age:	<14 years	Date (if available):	Between 14 and 43 years (1974-2003)		>43 years (Before 1974)		Building type:	Residential	Apartment	House	Dormitory	Public		Commercial		Building status:	Under Construction	Occupied	Abandoned	Waterproofing defects, water leakage and seepage	
		District:	İskele																														
		Area:	St Andrew (Apostolos Andreas)																														
		Street name:	Karpaz Anayolu																														
		Latitude:	35°39'28.61"N																														
		Longitude:	34°34'27.31"E																														
		Structure age:	<14 years	Date (if available):																													
			Between 14 and 43 years (1974-2003)																														
			>43 years (Before 1974)																														
		Building type:	Residential	Apartment																													
House																																	
Dormitory																																	
Public																																	
Commercial																																	
Building status:	Under Construction																																
	Occupied																																
	Abandoned																																
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2" style="text-align: center;">Reinforced Concrete Defects</td> </tr> <tr> <td colspan="2" style="text-align: center;">Drying shrinkage cracks</td> </tr> <tr> <td rowspan="3">Corrosion of metals embedded in concrete</td> <td>Corrosion-induced cracking</td> </tr> <tr> <td>Corrosion-induced spalling</td> </tr> <tr> <td>Cracks due to embedment of dissimilar metals (handrails)</td> </tr> <tr> <td rowspan="6">Construction defects (faulty workmanship): designer, detailer, and contractor</td> <td>Improper reinforcing steel placement</td> </tr> <tr> <td>Premature removal of forms</td> </tr> <tr> <td>Cold joints</td> </tr> <tr> <td>Segregation</td> </tr> <tr> <td>Honeycombing</td> </tr> <tr> <td>Improper grades of slab surfaces</td> </tr> <tr> <td rowspan="3">Cracks in RC due to load effects (structural cracks)</td> <td>Slab/beam-to column shear (punching shear) cracks</td> </tr> <tr> <td>Cantilevered member cracks</td> </tr> <tr> <td>Settlement cracks</td> </tr> </table>		Reinforced Concrete Defects		Drying shrinkage cracks		Corrosion of metals embedded in concrete	Corrosion-induced cracking	Corrosion-induced spalling	Cracks due to embedment of dissimilar metals (handrails)	Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Premature removal of forms	Cold joints	Segregation	Honeycombing	Improper grades of slab surfaces	Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Cantilevered member cracks	Settlement cracks	Defected wooden door												
		Reinforced Concrete Defects																															
		Drying shrinkage cracks																															
		Corrosion of metals embedded in concrete	Corrosion-induced cracking																														
			Corrosion-induced spalling																														
			Cracks due to embedment of dissimilar metals (handrails)																														
		Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement																														
			Premature removal of forms																														
			Cold joints																														
			Segregation																														
Honeycombing																																	
Improper grades of slab surfaces																																	
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks																																
	Cantilevered member cracks																																
	Settlement cracks																																
Surface defects	dampness	Condensation																															
		Rising damp																															
		Rain penetration																															
		Leaking pipes, spills and other moisture sources																															
	Surface cracks on wall finishes	cracking																															
		Map/pattern cracking																															
	Efflorescence																																
	Paint peeling																																
	Mouldiness																																
	Wall finishes workmanship problem																																
Staining																																	
Non-structural cracks	Joint cracks																																
<u>Other notes (if available):</u>																																	


Case Study #51 (L1)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Beam elementary design faults	Projections in plan
			Non-continuous beams		
			Non-uniform beam span and cross-section		
			Slab elementary design faults	Absence of vertical support at beams intersection	
		Broken axis beams and frames			
				Over-stretched one-way slab	
				Poorly supported or heavily loaded cantilevered slabs	
		Pounding and separation problem			
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Vertical structural elementary design fault	Broken axis columns	
				Irregular column and/or shear-wall plan configuration	
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
				Surface cracks on wall finishes	cracking
Efflorescence					
				Paint peeling	
				Mouldiness	
				Wall finishes workmanship problem	
				Staining	
		Non-structural cracks	Joint cracks		
Other notes (if available):					


Case Study #52 (L2)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
Discontinuity of columns or shear walls				
Vertical structural elementary design fault	Broken axis columns			
	Irregular column and/or shear-wall plan configuration			
	Short column			
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
		Surface cracks on wall finishes	crazing	
Map/pattern cracking				
Corrosion of metals embedded in concrete	Corrosion-induced cracking			
	Corrosion-induced spalling			
	Cracks due to embedment of dissimilar metals (handrails)			
	Efflorescence			
	Paint peeling			
	Mouldiness			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			
	Premature removal of forms			
	Cold joints			
	Segregation			
Cracks in RC due to load effects (structural cracks)	Honeycombing			
	Improper grades of slab surfaces			
	Joint cracks			
		Non-structural cracks		
<u>Other notes (if available):</u>				
District:		Lefkoşa (Nicosia)		
Area:		Değirmenlik (Kythrea)		
Street name:		No street names were found in the town		
Latitude:		35°14'23.84"N		
Longitude:		33°29'19.65"E		
Structure age:	<14 years	Date (if available):		
	Between 14 and 43 years (1974-2003)			
	>43 years (Before 1974)		■	
Building type:	Residential	Apartment		
		House	■	
		Dormitory		
	Public			
	Commercial			
Building status:	Under Construction			
	Occupied			
	Abandoned		■	


Case Study #53 (L3)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Projections in plan	
			Beam elementary design faults	Non-continuous beams	
				Non-uniform beam span and cross-section	
				Absence of vertical support at beams intersection	
		Slab elementary design faults	Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs		
		Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural element elementary design fault	Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
Short column					
Non-Structural Defects		Waterproofing defects, water leakage and seepage			
Building status:	Under Construction	Defected wooden door			
	Occupied	Condensation			
	Abandoned	Rising damp			
Reinforced Concrete Defects		Surface defects	Rain penetration		
Drying shrinkage cracks			Leaking pipes, spills and other moisture sources		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing	
	Corrosion-induced spalling			Map/pattern cracking	
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling		
	Premature removal of forms		Mouldiness		
	Cold joints		Wall finishes workmanship problem		
	Segregation		Staining		
	Honeycombing		Non-structural cracks	Joint cracks	
	Improper grades of slab surfaces	<u>Other notes (if available):</u>			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #54 (L4)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
					Projections in plan
		Structural configuration	Horizontal structural configuration	Beam elementary design faults	Non-continuous beams
					Non-uniform beam span and cross-section
Absence of vertical support at beams intersection					
Structural configuration	Horizontal structural configuration	Slab elementary design faults	Broken axis beams and frames		
			Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs		
		Pounding and separation problem			
Structure age:	<14 years	Date (if available):	Weak storey		
	Between 14 and 43 years (1974-2003)		Soft storey		
	>43 years (Before 1974)		Discontinuity of columns or shear walls		
Building type:	Residential	Apartment	Broken axis columns		
		House	Irregular column and/or shear-wall plan configuration		
		Dormitory			
	Public		Short column		
	Commercial				
Non-Structural Defects					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Condensation		
	Corrosion-induced spalling		Rising damp		
	Cracks due to embedment of dissimilar metals (handrails)		Rain penetration		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Leaking pipes, spills and other moisture sources		
	Premature removal of forms		Surface cracks on wall finishes		
	Cold joints		crazing		
	Segregation		Map/pattern cracking		
	Honeycombing		Efflorescence		
	Improper grades of slab surfaces		Paint peeling		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Mouldiness			
	Cantilevered member cracks	Wall finishes workmanship problem			
	Settlement cracks	Staining			
		Non-structural cracks	Joint cracks		
<u>Other notes (if available):</u>					


Case Study #55 (L5)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
			Poorly supported or heavily loaded cantilevered slabs	
			Pounding and separation problem	
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
				Discontinuity of columns or shear walls
			Vertical structural elementary design fault	Broken axis columns
				Irregular column and/or shear-wall plan configuration
		Short column		
Non-Structural Defects				
Building status:		Under Construction		
		Waterproofing defects, water leakage and seepage		
		Occupied		
		Defected wooden door		
		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete			Surface cracks on wall finishes	Cracking
				cr crazing
				Map/pattern cracking
				Efflorescence
				Paint peeling
				Mouldiness
			Wall finishes workmanship problem	
			Staining	
		Non-structural cracks	Joint cracks	
Reinforced Concrete Defects				
Drying shrinkage cracks				
Construction defects (faulty workmanship): designer, detailer, and contractor		Improper reinforcing steel placement		
		Premature removal of forms		
		Cold joints		
		Segregation		
		Honeycombing		
		Improper grades of slab surfaces		
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks		
		Cantilevered member cracks		
		Settlement cracks		
Other notes (if available):				


Case Study #56 (L6)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District:	Lefkoşa				
Area:	Yiğitler (Arsos)				
Street name:	No street names were found				
Latitude:	35° 5'17.64"N				
Longitude:	33°37'39.63"E				
Structure age:	<14 years	Date (if available):			
	Between 14 and 43 years (1974-2003)				
	>43 years (Before 1974)				
Building type:	Residential	Apartment			
		House			
		Dormitory			
	Public				
	Commercial				
Building status:	Under Construction				
	Occupied				
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes		cr crazing
	Corrosion-induced spalling				Map/pattern cracking
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)				Efflorescence
	Improper reinforcing steel placement				Paint peeling
	Premature removal of forms				Mouldiness
	Cold joints				Wall finishes workmanship problem
	Segregation			Staining	
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Non-structural cracks		Joint cracks	
	Cantilevered member cracks				
	Settlement cracks				
				Other notes (if available):	


Case Study #57 (L7)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
Over-stretched one-way slab					
Poorly supported or heavily loaded cantilevered slabs					
Pounding and separation problem					
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
Vertical structural elementary design fault	Discontinuity of columns or shear walls				
	Broken axis columns				
Irregular column and/or shear-wall plan configuration					
Short column					
Non-Structural Defects					
Building status:	Under Construction	Waterproofing defects, water leakage and seepage			
	Occupied	Defected wooden door			
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Rising damp	
	Corrosion-induced spalling			Rain penetration	
	Cracks due to embedment of dissimilar metals (handrails)			Leaking pipes, spills and other moisture sources	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Surface cracks on wall finishes	cr crazing
	Premature removal of forms		Efflorescence	Map/pattern cracking	
	Cold joints		Paint peeling		
	Segregation		Mouldiness		
	Honeycombing		Wall finishes workmanship problem		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Non-structural cracks	Staining	
	Cantilevered member cracks	Joint cracks			
	Settlement cracks	Other notes (if available):			


Case Study #58 (L8)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
District: Lefkoşa Area: Erdemli (Tremetousia) Street name: No street names were found Latitude: 35° 5'4.14"N Longitude: 33°36'17.01"E		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Vertical structural elementary design fault	Broken axis columns	
		Irregular column and/or shear-wall plan configuration			
		Short column			
Non-Structural Defects					
Building status:		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Dampness			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
				Surface cracks on wall finishes	crazing
Corrosion of metals embedded in concrete				Map/pattern cracking	
				Efflorescence	
Construction defects (faulty workmanship): designer, detailer, and contractor				Paint peeling	
				Mouldiness	
				Wall finishes workmanship problem	
				Staining	
				Non-structural cracks	Joint cracks
Cracks in RC due to load effects (structural cracks)		Other notes (if available):			
		The house is for sale			
		Slab/beam-to column shear (punching shear) cracks Cantilevered member cracks Settlement cracks			


Case Study #59 (L9)

Profile			Seismic Design Faults					
			Week column-strong beam					
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
Floor discontinuity								
Projections in plan								
Beam elementary design faults	Non-continuous beams							
	Non-uniform beam span and cross-section							
	Absence of vertical support at beams intersection							
Slab elementary design faults	Broken axis beams and frames							
	Over-stretched one-way slab							
	Poorly supported or heavily loaded cantilevered slabs							
			Pounding and separation problem					
Vertical structural configuration	Irregularity in elevation	Weak storey						
		Soft storey						
		Discontinuity of columns or shear walls						
	Vertical structural element elementary design fault	Broken axis columns						
Irregular column and/or shear-wall plan configuration								
			Short column					
Non-Structural Defects								
			Waterproofing defects, water leakage and seepage					
			Defected wooden door					
Reinforced Concrete Defects			Surface defects			dampness		
						Condensation		
			Rising damp					
			Rain penetration					
Drying shrinkage cracks			Leaking pipes, spills and other moisture sources					
Corrosion of metals embedded in concrete			Surface cracks on wall finishes			crazing		
						Map/pattern cracking		
Cracks due to embedment of dissimilar metals (handrails)			Efflorescence					
Construction defects (faulty workmanship): designer, detailer, and contractor			Non-structural cracks			Paint peeling		
						Mouldiness		
			Improper reinforcing steel placement			Wall finishes workmanship problem		
			Premature removal of forms			Staining		
Cold joints			Joint cracks					
Segregation								
Honeycombing								
Improper grades of slab surfaces			<u>Other notes (if available):</u>					
Cracks in RC due to load effects (structural cracks)						Slab/beam-to column shear (punching shear) cracks		
						Cantilevered member cracks		
Settlement cracks								


Case Study #60 (L10)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
				Pounding and separation problem	
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
Discontinuity of columns or shear walls					
Vertical structural elementary design fault	Broken axis columns				
	Irregular column and/or shear-wall plan configuration				
	Short column				
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
Rain penetration					
Leaking pipes, spills and other moisture sources					
			Surface cracks on wall finishes	cr crazing	
		Map/pattern cracking			
		Non-structural cracks	Efflorescence		
			Paint peeling		
		Non-structural cracks	Mouldiness		
			Wall finishes workmanship problem		
		Non-structural cracks	Staining		
			Joint cracks		
Reinforced Concrete Defects					
Drying shrinkage cracks					
		Non-structural cracks	Corrosion-induced cracking		
			Corrosion-induced spalling		
			Cracks due to embedment of dissimilar metals (handrails)		
		Non-structural cracks	Improper reinforcing steel placement		
			Premature removal of forms		
			Cold joints		
			Segregation		
			Honeycombing		
		Non-structural cracks	Improper grades of slab surfaces		
			Slab/beam-to column shear (punching shear) cracks		
			Cantilevered member cracks		
		Non-structural cracks	Settlement cracks		
<u>Other notes (if available):</u>					


Case Study #61 (L11)

Profile		Seismic Design Faults					
		Week column-strong beam					
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
Floor discontinuity							
Projections in plan							
Beam elementary design faults	Non-continuous beams						
	Non-uniform beam span and cross-section						
	Absence of vertical support at beams intersection						
Slab elementary design faults	Over-stretched one-way slab						
	Poorly supported or heavily loaded cantilevered slabs						
		Pounding and separation problem					
		Vertical structural configuration	Irregularity in elevation	Weak storey			
				Soft storey			
			Discontinuity of columns or shear walls				
Vertical structural elementary design fault	Broken axis columns						
	Irregular column and/or shear-wall plan configuration						
	Short column						
Non-Structural Defects							
		Waterproofing defects, water leakage and seepage					
		Defected wooden door					
Reinforced Concrete Defects		Surface defects	dampness	Condensation			
				Rising damp			
				Rain penetration			
				Leaking pipes, spills and other moisture sources			
			Surface cracks on wall finishes	crazing			
Map/pattern cracking							
		Efflorescence					
		Paint peeling					
		Mouldiness					
		Wall finishes workmanship problem					
		Staining					
		Non-structural cracks	Joint cracks				
Other notes (if available):							
					Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks
							Cantilevered member cracks
		Settlement cracks					


Case Study #62 (L12)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
			Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural elementary design fault	Broken axis columns			
Irregular column and/or shear-wall plan configuration					
			Short column		
Non-Structural Defects					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	cr crazing	
	Corrosion-induced spalling			Map/pattern cracking	
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence		
	Improper reinforcing steel placement		Paint peeling		
	Premature removal of forms		Mouldiness		
	Cold joints		Wall finishes workmanship problem		
	Segregation	Staining			
	Honeycombing	Non-structural cracks	Joint cracks		
Improper grades of slab surfaces		Other notes (if available):			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #63 (L13)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem			
District: Lefkoşa		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
Discontinuity of columns or shear walls					
Area: Hamitköy			Vertical structural element elementary design fault	Broken axis columns	
				Irregular column and/or shear-wall plan configuration	
Street name: Anittepe Cd			Short column		
		Non-Structural Defects			
Latitude: 35°12'52.53"N		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Longitude: 33°22'24.62"E		Surface defects	dampness	Condensation	
				Rising damp	
Rain penetration					
Leaking pipes, spills and other moisture sources					
Structure age:			Surface cracks on wall finishes	Surface cracks	
		cr crazing			
Date (if available): 2004-2005		Non-structural cracks	Map/pattern cracking		
			Efflorescence		
Between 14 and 43 years (1974-2003)		Paint peeling			
		Mouldiness			
>43 years (Before 1974)		Wall finishes workmanship problem			
		Staining			
Building type:		Joint cracks			
		Other notes (if available):			
Apartment					
				House	
Dormitory					
				Public	
Commercial					
				Under Construction	
Occupied					
				Abandoned	
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete		Slab/beam-to column shear (punching shear) cracks			
				Cantilevered member cracks	
Improper reinforcing steel placement					
		Premature removal of forms			
Cold joints					
		Segregation			
Honeycombing					
		Improper grades of slab surfaces			
Slab/beam-to column shear (punching shear) cracks					
		Cantilevered member cracks			
Settlement cracks					


Case Study #64 (L14)

Profile			Seismic Design Faults				
			Week column-strong beam				
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
Floor discontinuity							
Projections in plan							
Beam elementary design faults	Non-continuous beams						
	Non-uniform beam span and cross-section						
Slab elementary design faults	Absence of vertical support at beams intersection						
	Broken axis beams and frames						
	Over-stretched one-way slab						
				Pounding and separation problem			
				Vertical structural configuration	Irregularity in elevation	Weak storey	
			Soft storey				
			Discontinuity of columns or shear walls				
			Vertical structural element elementary design fault		Broken axis columns		
					Irregular column and/or shear-wall plan configuration		
			Short column				
Non-Structural Defects							
Building status:			Under Construction			Waterproofing defects, water leakage and seepage	
			Occupied			Defected wooden door	
			Abandoned				
Reinforced Concrete Defects							
Drying shrinkage cracks			Surface defects	dampness	Condensation		
					Rising damp		
Rain penetration							
Leaking pipes, spills and other moisture sources							
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Surface cracks on wall finishes	crazing		
	Corrosion-induced spalling		Map/pattern cracking				
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling				
	Premature removal of forms		Mouldiness				
	Cold joints		Wall finishes workmanship problem				
	Segregation		Staining				
	Honeycombing		Non-structural cracks	Joint cracks			
	Improper grades of slab surfaces						
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		<u>Other notes (if available):</u> The building is used as fruits storage.				
	Cantilevered member cracks						
	Settlement cracks						


Case Study #65/103 (L15/C3)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem	
			Vertical structural configuration	Irregularity in elevation
		Soft storey		
		Discontinuity of columns or shear walls		
		Vertical structural elementary design fault		Broken axis columns
				Irregular column and/or shear-wall plan configuration
		Short column		
Non-Structural Defects				
Building status:		Under Construction		
		Waterproofing defects, water leakage and seepage		
		Occupied		
		Defected wooden door		
		Abandoned		
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
				Surface cracks on wall finishes
			Map/pattern cracking	
Corrosion of metals embedded in concrete			Corrosion-induced cracking	
			Corrosion-induced spalling	
			Cracks due to embedment of dissimilar metals (handrails)	
Construction defects (faulty workmanship): designer, detailer, and contractor			Improper reinforcing steel placement	
		Premature removal of forms		
		Cold joints		
		Segregation		
		Honeycombing		
		Non-structural cracks	Improper grades of slab surfaces	
			Joint cracks	
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks		
		Cantilevered member cracks		
		Settlement cracks		
<u>Other notes (if available):</u>				
<p style="color: red;">The building is not finished except for the ground floor where it is furnished and occupied. Thus it is considered a shared case study between Lefcosa case study section and the under construction case study section.</p>				


Case Study #66 (L16)

Profile			Seismic Design Faults					
			Week column-strong beam					
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
						Floor discontinuity		
					Beam elementary design faults	Projections in plan		
				Non-continuous beams				
				Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection							
	Broken axis beams and frames							
			Over-stretched one-way slab					
			Poorly supported or heavily loaded cantilevered slabs					
			Pounding and separation problem					
			Vertical structural configuration	Irregularity in elevation	Weak storey			
					Soft storey			
				Discontinuity of columns or shear walls				
				Broken axis columns				
			Vertical structural elementary design fault	Irregular column and/or shear-wall plan configuration				
					Short column			
Non-Structural Defects								
			Waterproofing defects, water leakage and seepage					
			Defected wooden door					
Reinforced Concrete Defects			Surface defects	dampness	Condensation			
					Rising damp			
					Rain penetration			
					Leaking pipes, spills and other moisture sources			
	Corrosion of metals embedded in concrete	Surface cracks on wall finishes	crazing					
		Map/pattern cracking						
	Construction defects (faulty workmanship): designer, detailer, and contractor	Efflorescence						
		Paint peeling						
		Mouldiness						
		Wall finishes workmanship problem						
		Staining						
		Non-structural cracks		Joint cracks				
<u>Other notes (if available):</u>								
						Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	
							Cantilevered member cracks	
							Settlement cracks	


Case Study #67 (L17)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Over-stretched one-way slab					
	Poorly supported or heavily loaded cantilevered slabs					
			Pounding and separation problem			
District: Lefkoşa Area: Goenyeli Street name: Taşkınsu Sk Latitude: 35°12'41.64"N Longitude: 33°17'35.24"E			Vertical structural configuration	Irregularity in elevation	Weak storey	
					Soft storey	
					Discontinuity of columns or shear walls	
				Vertical structural elementary design fault	Broken axis columns	
			Irregular column and/or shear-wall plan configuration			
			Short column			
Non-Structural Defects						
Building status:			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects						
Drying shrinkage cracks			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete				Surface cracks on wall finishes	crazing	
					Map/pattern cracking	
Construction defects (faulty workmanship): designer, detailer, and contractor				Efflorescence		
				Paint peeling		
				Mouldiness		
				Wall finishes workmanship problem		
			Staining			
			Non-structural cracks	Joint cracks		
<u>Other notes (if available):</u>						
Cracks in RC due to load effects (structural cracks)			The profile picture shows the rear facade as the front facade had lots of parking cars.			
			Slab/beam-to column shear (punching shear) cracks			
			Cantilevered member cracks			
			Settlement cracks			


Case Study #68 (L18)

Profile		Seismic Design Faults							
		Week column-strong beam							
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)				
Floor discontinuity									
Projections in plan									
Beam elementary design faults	Non-continuous beams								
	Non-uniform beam span and cross-section								
Slab elementary design faults	Absence of vertical support at beams intersection								
	Broken axis beams and frames								
	Over-stretched one-way slab								
			Pounding and separation problem						
			Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey							
		Discontinuity of columns or shear walls							
		Vertical structural elementary design fault		Broken axis columns					
				Irregular column and/or shear-wall plan configuration					
		Short column							
Non-Structural Defects									
		Waterproofing defects, water leakage and seepage							
		Defected wooden door							
Reinforced Concrete Defects		Surface defects	dampness	Condensation					
				Rising damp					
				Rain penetration					
				Leaking pipes, spills and other moisture sources					
		Surface defects	Surface cracks on wall finishes	crazing					
				Map/pattern cracking					
			Efflorescence						
		Surface defects	Non-structural cracks	Paint peeling					
				Mouldiness					
				Wall finishes workmanship problem					
				Staining					
		Joint cracks							
Other notes (if available):									
						Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks	
								Cantilevered member cracks	
		Settlement cracks							
District:		Lefkoşa							
Area:		Goenyeli							
Street name:		Sazlıka Sk							
Latitude:		35°12'40.60"N							
Longitude:		33°17'36.01"E							
Structure age:		<14 years	Date (if available):						
		Between 14 and 43 years (1974-2003)							
		>43 years (Before 1974)							
Building type:		Residential	Apartment						
			House						
			Dormitory						
		Public							
		Commercial							
Building status:		Under Construction							
		Occupied							
		Abandoned							


Case Study #69 (L19)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Beam elementary design faults	Projections in plan
			Non-continuous beams		
			Non-uniform beam span and cross-section		
			Slab elementary design faults	Absence of vertical support at beams intersection	
		Broken axis beams and frames			
				Over-stretched one-way slab	
				Poorly supported or heavily loaded cantilevered slabs	
		Pounding and separation problem			
		Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
		Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
		Short column			
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Condensation			
		Rising damp			
		Rain penetration			
		Leaking pipes, spills and other moisture sources			
		crazing			
		Map/pattern cracking			
		Efflorescence			
		Paint peeling			
		Mouldiness			
		Wall finishes workmanship problem			
		Staining			
		Joint cracks			
		Reinforced Concrete Defects			
Drying shrinkage cracks					
Corrosion of metals embedded in concrete		Corrosion-induced cracking			
		Corrosion-induced spalling			
		Cracks due to embedment of dissimilar metals (handrails)			
Construction defects (faulty workmanship): designer, detailer, and contractor		Improper reinforcing steel placement			
		Premature removal of forms			
		Cold joints			
		Segregation			
		Honeycombing			
		Improper grades of slab surfaces			
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks			
		Cantilevered member cracks			
		Settlement cracks			
<u>Other notes (if available):</u>					


Case Study #70 (L20)

Profile		Seismic Design Faults					
		Week column-strong beam					
District:	Lefkoşa	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
Area:	Goenyeli			Beam elementary design faults	Floor discontinuity		
Street name:	Yaşar Doğu Sk				Projections in plan		
Latitude:	35°12'46.35"N				Non-continuous beams		
Longitude:	33°18'0.86"E			Non-uniform beam span and cross-section			
Structure age:	<14 years			Absence of vertical support at beams intersection			
	Date (if available):	Broken axis beams and frames					
	Between 14 and 43 years (1974-2003)	Slab elementary design faults	Over-stretched one-way slab				
	>43 years (Before 1974)	Pounding and separation problem	Poorly supported or heavily loaded cantilevered slabs				
Building type:	Residential	Vertical structural configuration	Irregularity in elevation	Weak storey			
	Apartment	Vertical structural element elementary design fault	Irregularity in elevation	Soft storey			
	House			Discontinuity of columns or shear walls			
Dormitory	Broken axis columns						
	Public			Irregular column and/or shear-wall plan configuration			
	Commercial			Short column			
Reinforced Concrete Defects		Non-Structural Defects					
Building status:	Under Construction	Waterproofing defects, water leakage and seepage					
	Occupied	Defected wooden door					
	Abandoned	Condensation					
Drying shrinkage cracks		Surface defects	dampness	Rising damp			
Corrosion of metals embedded in concrete				Rain penetration			
				Leaking pipes, spills and other moisture sources			
Construction defects (faulty workmanship): designer, detailer, and contractor				Surface cracks on wall finishes		crazing	
				Map/pattern cracking			
			Efflorescence				
Cracks in RC due to load effects (structural cracks)			Paint peeling				
			Mouldiness				
			Wall finishes workmanship problem				
			Staining				
Cold joints		Non-structural cracks	Joint cracks				
Segregation		Other notes (if available): The profile picture shows the rear facade as the front facade is covered with vegetation.					
Honeycombing							
Improper grades of slab surfaces							
Slab/beam-to column shear (punching shear) cracks							
Cantilevered member cracks							
Settlement cracks							


Case Study #71 (L21)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
District: Lefkoşa Area: Goenyeli Street name: Yaşar Doğu Sk Latitude: 35°12'45.84"N Longitude: 33°17'59.29"E		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Vertical structural elementary design fault	Broken axis columns	
Irregular column and/or shear-wall plan configuration					
Short column					
Non-Structural Defects					
Building status: Under Construction Occupied Abandoned		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)				
	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces				
	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
		Non-structural cracks	Joint cracks		
		Settlement cracks			
<u>Other notes (if available):</u>					


Case Study #72 (L22)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
Vertical structural element elementary design fault	Broken axis columns			
	Irregular column and/or shear-wall plan configuration			
		Short column		
Reinforced Concrete Defects		Non-Structural Defects		
Building status:	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
	Abandoned			
Drying shrinkage cracks		Surface defects	dampness	
			Condensation	
			Rising damp	
			Rain penetration	
			Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing
	Corrosion-induced spalling			Map/pattern cracking
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)			Efflorescence
	Improper reinforcing steel placement			Paint peeling
	Premature removal of forms			Mouldiness
	Cold joints	Non-structural cracks	Wall finishes workmanship problem	
	Segregation		Staining	
	Honeycombing	Joint cracks		
Improper grades of slab surfaces	Other notes (if available):			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			


Case Study #73 (L23)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs		
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
			Discontinuity of columns or shear walls	
			Broken axis columns	
		Vertical structural elementary design fault	Irregular column and/or shear-wall plan configuration	
			Short column	
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
		Corrosion of metals embedded in concrete	Surface cracks on wall finishes	crazing
Map/pattern cracking				
Construction defects (faulty workmanship): designer, detailer, and contractor	Efflorescence			
	Paint peeling			
	Mouldiness			
	Wall finishes workmanship problem			
	Staining			
			Non-structural cracks	Joint cracks
<u>Other notes (if available):</u>				
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks		
		Cantilevered member cracks		
		Settlement cracks		


Case Study #74 (L24)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District:	Lefkoşa				
Area:	Goenyeli				
Street name:	Şht. Hüseyin Amca Cd				
Latitude:	35°12'54.84"N				
Longitude:	33°17'48.26"E				
Structure age:	<14 years	Date (if available):	2002-2003		
		Between 14 and 43 years (1974-2003)			
	>43 years (Before 1974)				
	Building type:	Residential	Apartment		
House					
Dormitory					
Public					
Commercial					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
Corrosion of metals embedded in concrete				Surface cracks on wall finishes	Rising damp
					Rain penetration
				Leaking pipes, spills and other moisture sources	
			Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Non-structural cracks
Map/pattern cracking					
Premature removal of forms	Efflorescence				
Cold joints	Paint peeling				
Segregation	Mouldiness				
Honeycombing	Wall finishes workmanship problem				
Improper grades of slab surfaces	Staining				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Joint cracks			
	Cantilevered member cracks				
	Settlement cracks				
<u>Other notes (if available):</u>					


Case Study #75 (L25)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
District: Lefkoşa Area: Alayköy Sanayi Bölgesi Street name: No street names were found Latitude: 35°12'21.96"N Longitude: 33°16'5.66"E		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Vertical structural element elementary design fault	Broken axis columns	
				Irregular column and/or shear-wall plan configuration	
				Short column	
Non-Structural Defects					
Building status:		Under Construction			
		Occupied			
		Abandoned			
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
Non-Structural Defects					
Building status:		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
		Surface cracks on wall finishes	Surface cracks		
			crazing		
				Map/pattern cracking	
				Efflorescence	
		Paint peeling			
		Mouldiness			
		Wall finishes workmanship problem			
		Staining			
		Non-structural cracks	Joint cracks		
<u>Other notes (if available):</u>					


Case Study #76(G1)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem			
District: Girne Area: Bahçeli (Kalograia) Street name: No street names were found Latitude: 35°20'29.67"N Longitude: 33°37'40.73"E		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
				Discontinuity of columns or shear walls	
			Vertical structural element elementary design fault	Broken axis columns	
				Irregular column and/or shear-wall plan configuration	
		Short column			
Non-Structural Defects					
Building status:		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects					
Drying shrinkage cracks					
Surface defects	dampness	Condensation			
		Rising damp			
		Rain penetration			
Leaking pipes, spills and other moisture sources					
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	crazing			
		Map/pattern cracking			
	Efflorescence				
Construction defects (faulty workmanship): designer, detailer, and contractor	Paint peeling				
	Mouldiness				
	Wall finishes workmanship problem				
	Staining				
	Non-structural cracks		Joint cracks		
<u>Other notes (if available):</u>					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #77 (G2)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs		
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
			Discontinuity of columns or shear walls	
			Broken axis columns	
		Vertical structural elementary design fault	Irregular column and/or shear-wall plan configuration	
			Short column	
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
		crazing		
		Map/pattern cracking		
		Efflorescence		
		Paint peeling		
		Mouldiness		
		Wall finishes workmanship problem		
		Staining		
		Non-structural cracks	Joint cracks	
Other notes (if available):				


Case Study #78 (G3)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
			Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs		
			Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
			Discontinuity of columns or shear walls		
			Broken axis columns		
			Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration	
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
				Drying shrinkage cracks	
Map/pattern cracking					
Corrosion of metals embedded in concrete		Efflorescence			
		Paint peeling			
		Mouldiness			
Construction defects (faulty workmanship): designer, detailer, and contractor		Wall finishes workmanship problem			
		Staining			
		Non-structural cracks	Joint cracks		
		Other notes (if available):			
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks			
		Cantilevered member cracks			
		Settlement cracks			


Case Study #79 (G4)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Projections in plan			
	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
		Pounding and separation problem		
		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
Discontinuity of columns or shear walls				
Vertical structural element elementary design fault	Broken axis columns			
	Irregular column and/or shear-wall plan configuration			
	Short column			
		Non-Structural Defects		
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
Rain penetration				
Leaking pipes, spills and other moisture sources				
Corrosion of metals embedded in concrete	Surface cracks on wall finishes		Non-structural cracks	Surface cracks
		Map/pattern cracking		
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks in RC due to load effects (structural cracks)	Non-structural cracks	Surface cracks	Efflorescence
				Paint peeling
				Mouldiness
				Wall finishes workmanship problem
				Staining
				Joint cracks
				Other notes (if available):
Cracks in RC due to load effects (structural cracks)	Cracks in RC due to load effects (structural cracks)	Non-structural cracks	Surface cracks	Slab/beam-to column shear (punching shear) cracks
				Cantilevered member cracks
				Settlement cracks


Case Study #80 (G5)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
District:	Girne	Over-stretched one-way slab				
Area:	Esentepe (Agios Amvrosios)					
Street name:	No street names were found	Poorly supported or heavily loaded cantilevered slabs				
Latitude:	35°20'38.28"N					
Longitude:	33°34'41.61"E	Pounding and separation problem				
Structure age:	<14 years			Date (if available):		
	Between 14 and 43 years (1974-2003)					
	>43 years (Before 1974)					
Building type:	Residential	Apartment	Irregularity in elevation	Weak storey		
		House		Soft storey		
		Dormitory	Discontinuity of columns or shear walls			
	Public	Vertical structural element elementary design fault	Broken axis columns			
Commercial	Irregular column and/or shear-wall plan configuration					
Building status:	Under Construction	Short column				
	Occupied	Non-Structural Defects				
	Abandoned	Waterproofing defects, water leakage and seepage				
Reinforced Concrete Defects		Defected wooden door				
Drying shrinkage cracks			Surface defects	dampness	Condensation	
					Rising damp	
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface cracks on wall finishes		Non-structural cracks	Joint cracks	Rain penetration
	Corrosion-induced spalling					Leaking pipes, spills and other moisture sources
	Cracks due to embedment of dissimilar metals (handrails)		cracking			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				Map/pattern cracking	
	Premature removal of forms				Efflorescence	
	Cold joints				Paint peeling	
	Segregation				Mouldiness	
	Honeycombing				Wall finishes workmanship problem	
	Improper grades of slab surfaces				Staining	
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	<u>Other notes (if available):</u>				
	Cantilevered member cracks					
	Settlement cracks					



Case Study #81 (G6)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
					Floor discontinuity	
			Beam elementary design faults	Non-continuous beams		
				Non-uniform beam span and cross-section		
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
District:	Girne					
Area:	Arapköy (Klepini)					
Street name:	Beş Parmaklar Cd					
Latitude:	N 35°18.022' (35°18'1.3")					
Longitude:	E 33°26.124' (33°26'7.4")					
Structure age:	<14 years	Date (if available):				
	Between 14 and 43 years (1974-2003)	2004-2005				
	>43 years (Before 1974)					
Building type:	Residential	Apartment				
		House				
		Dormitory				
	Public					
	Commercial					
Building status:	Under Construction		Non-Structural Defects			
	Occupied		Waterproofing defects, water leakage and seepage			
	Abandoned		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation		
Drying shrinkage cracks				Rising damp		
				Rain penetration		
				Leaking pipes, spills and other moisture sources		
				Surface cracks on wall finishes	crazing	
			Map/pattern cracking			
Corrosion of metals embedded in concrete	Corrosion-induced cracking					
	Corrosion-induced spalling					
	Cracks due to embedment of dissimilar metals (handrails)					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					
		Non-structural cracks		Joint cracks		
<u>Other notes (if available):</u>						


Case Study #82 (G7)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
			Pounding and separation problem			
			Vertical structural configuration	Irregularity in elevation	Weak storey	
					Soft storey	
				Vertical structural element elementary design fault	Discontinuity of columns or shear walls	
					Broken axis columns	
			Irregular column and/or shear-wall plan configuration			
			Short column			
			Non-Structural Defects			
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
			Surface cracks on wall finishes	Non-structural cracks	cracking	
					Map/pattern cracking	
			Efflorescence			
			Paint peeling			
			Mouldiness			
			Wall finishes workmanship problem			
			Staining			
			Joint cracks			
			Reinforced Concrete Defects			
Drying shrinkage cracks						
Corrosion of metals embedded in concrete	Corrosion-induced cracking					
	Corrosion-induced spalling					
	Cracks due to embedment of dissimilar metals (handrails)					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					
			<u>Other notes (if available):</u>			


Case Study #83 (G8)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District:	Girne	Pounding and separation problem			
Area:	Ozanköy or Kazafana (Kazafani or Kazaphani)	Vertical structural configuration	Irregularity in elevation	Weak storey	
Street name:	Zafer Caddesi			Soft storey	
Latitude:	35°18'29.44"N	Vertical structural element elementary design fault	Vertical structural element elementary design fault	Discontinuity of columns or shear walls	
Longitude:	33°21'1.46"E			Broken axis columns	
Structure age:	<14 years	Non-Structural Defects	Surface defects	dampness	Waterproofing defects, water leakage and seepage
	Between 14 and 43 years (1974-2003)				Defected wooden door
	>43 years (Before 1974)				Condensation
Building type:	Residential	Surface cracks on wall finishes	Non-structural cracks	Joint cracks	Rising damp
	Apartment				Rain penetration
	House				Leaking pipes, spills and other moisture sources
Dormitory	Cracking due to embedment of dissimilar metals (handrails)	Efflorescence	Map/pattern cracking		
Public	Building status:	Paint peeling	Staining		
Commercial		Under Construction	Wall finishes workmanship problem		
Reinforced Concrete Defects		Other notes (if available):			
Drying shrinkage cracks		<p style="text-align: center; color: red; font-weight: bold;">BU BİNA 21-11-1986 TARİHİNDE HİZMETE AÇILMIŞTIR 8-6-2001 TARİHİNDE RESTORE EDİLMİŞTİR</p>			
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Non-structural cracks	
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Joint cracks			
	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #84 (G9)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
		Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem			
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
Vertical structural elementary design fault	Discontinuity of columns or shear walls				
	Broken axis columns				
		Irregular column and/or shear-wall plan configuration			
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Surface cracks on wall finishes	cracking				
	Map/pattern cracking				
		Efflorescence			
		Paint peeling			
		Mouldiness			
		Wall finishes workmanship problem			
		Staining			
		Non-structural cracks	Joint cracks		
Other notes (if available):					
				Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks
					Cantilevered member cracks
					Settlement cracks


Case Study #85 (G10)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem	
Vertical structural configuration	Irregularity in elevation		Weak storey	
		Soft storey		
		Discontinuity of columns or shear walls		
	Vertical structural elementary design fault	Broken axis columns		
Irregular column and/or shear-wall plan configuration				
		Short column		
		Non-Structural Defects		
Building status:	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
	Abandoned			
Reinforced Concrete Defects		Surface defects	dampness	Condensation
Drying shrinkage cracks				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
			Corrosion of metals embedded in concrete	Corrosion-induced cracking
Corrosion-induced spalling	Map/pattern cracking			
Cracks due to embedment of dissimilar metals (handrails)	Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling	
	Premature removal of forms		Mouldiness	
	Cold joints		Wall finishes workmanship problem	
	Segregation	Staining		
	Honeycombing			
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Non-structural cracks	Joint cracks	
	Slab/beam-to column shear (punching shear) cracks	Other notes (if available):		
	Cantilevered member cracks			
Settlement cracks				


Case Study #86(G11)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Broken axis beams and frames					
	Over-stretched one-way slab					
			Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem			
District:	Girne		Vertical structural configuration	Irregularity in elevation	Weak storey	
	Area:	Girne (Kyrenia)			Soft storey	
		Street name:			20 Temmuz Kordonboyu Caddesi	
Latitude:	35°20'31.46"N			Broken axis columns		
Longitude:	33°19'9.66"E			Vertical structural elementary design fault	Irregular column and/or shear-wall plan configuration	
Structure age:	<14 years	Date (if available):				Short column
	Between 14 and 43 years (1974-2003)			Non-Structural Defects		
	>43 years (Before 1974)			Waterproofing defects, water leakage and seepage		
Building type:	Residential	Apartment		Defected wooden door		
		House		Dampness		
		Dormitory		Condensation		
		Public		Rising damp		
		Commercial		Rain penetration		
Building status:	Under Construction			Leaking pipes, spills and other moisture sources		
	Occupied			Surface cracks on wall finishes	crazing	
	Abandoned			Map/pattern cracking		
Reinforced Concrete Defects			Surface defects	Efflorescence		
Drying shrinkage cracks				Paint peeling		
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Mouldiness		
	Corrosion-induced spalling			Wall finishes workmanship problem		
	Cracks due to embedment of dissimilar metals (handrails)			Staining		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Non-structural cracks	Joint cracks	
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
Improper grades of slab surfaces				<u>Other notes (if available):</u>		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					


Case Study #87 (G12)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District:	Girne				
Area:	Aşağı Taşkent or Kaynakköy (Sychari or Sichari)				
Street name:	No street names were found				
Latitude:	35°16'2.68"N				
Longitude:	33°22'58.68"E				
Structure age:	<14 years	Date (if available):			
	Between 14 and 43 years (1974-2003)				
	>43 years (Before 1974)				
Building type:	Residential	Apartment			
		House			
		Dormitory			
	Public				
	Commercial				
Building status:	Under Construction				
	Occupied				
	Abandoned				
Reinforced Concrete Defects		Non-Structural Defects			
Drying shrinkage cracks		Waterproofing defects, water leakage and seepage			
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface defects	dampness	Defected wooden door	
	Corrosion-induced spalling			Condensation	
	Cracks due to embedment of dissimilar metals (handrails)			Rising damp	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Surface cracks on wall finishes		Rain penetration	
	Premature removal of forms		Leaking pipes, spills and other moisture sources		
	Cold joints	Non-structural cracks	Surface cracks	cracking	
	Segregation		Map/pattern cracking		
	Honeycombing		Efflorescence		
	Improper grades of slab surfaces		Paint peeling		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Mouldiness		
	Cantilevered member cracks		Wall finishes workmanship problem		
	Settlement cracks		Staining		
		Other notes (if available):			


Case Study #88 (G13)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem	
			Vertical structural configuration	Irregularity in elevation
		Soft storey		
		Discontinuity of columns or shear walls		
		Vertical structural elementary design fault		Broken axis columns
				Irregular column and/or shear-wall plan configuration
		Short column		
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
			Rain penetration	
			Leaking pipes, spills and other moisture sources	
		Corrosion of metals embedded in concrete	Surface cracks on wall finishes	crazing
Map/pattern cracking				
Construction defects (faulty workmanship): designer, detailer, and contractor		Efflorescence		
		Paint peeling		
		Mouldiness		
		Wall finishes workmanship problem		
		Staining		
		Non-structural cracks	Joint cracks	
Other notes (if available):				
Cracks in RC due to load effects (structural cracks)		Slab/beam-to column shear (punching shear) cracks		
		Cantilevered member cracks		
		Settlement cracks		


Case Study #89(G14)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
	Over-stretched one-way slab				
			Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation		Weak storey		
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural elementary design fault	Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	cr crazing			
		Map/pattern cracking			
		Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Non-structural cracks	Paint peeling			
		Mouldiness			
		Wall finishes workmanship problem			
		Staining			
		Joint cracks			
Cracks in RC due to load effects (structural cracks)		Other notes (if available):			
		Drying shrinkage cracks			
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces				
	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
		Settlement cracks			


Case Study #90 (G15)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
District: Girne		Over-stretched one-way slab				
Area: Dikmen (Dikomo)		Poorly supported or heavily loaded cantilevered slabs				
Street name: Dr. Fazil Küçük Cd		Pounding and separation problem				
Latitude: 35°16'22.70"N		Vertical structural configuration	Irregularity in elevation	Weak storey		
Longitude: 33°18'45.48"E				Soft storey		
Structure age:	<14 years	Date (if available):		Discontinuity of columns or shear walls		
	Between 14 and 43 years (1974-2003)			Broken axis columns		
	>43 years (Before 1974)			Irregular column and/or shear-wall plan configuration		
Building type:	Residential	Apartment		Short column		
		House				
	Public					
Commercial		Non-Structural Defects				
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned		Condensation			
Reinforced Concrete Defects		Surface defects	dampness	Rising damp		
Drying shrinkage cracks				Rain penetration		
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Leaking pipes, spills and other moisture sources		
	Corrosion-induced spalling			Surface cracks on wall finishes	crazing	
	Cracks due to embedment of dissimilar metals (handrails)		Map/pattern cracking			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Efflorescence			
	Premature removal of forms		Paint peeling			
	Cold joints		Mouldiness			
	Segregation		Wall finishes workmanship problem			
	Honeycombing		Staining			
	Improper grades of slab surfaces		Non-structural cracks	Joint cracks		
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		<u>Other notes (if available):</u>			
	Cantilevered member cracks					
	Settlement cracks					


Case Study #91 (G16)

Profile		Seismic Design Faults		
		Week column-strong beam		
Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
			Floor discontinuity	
			Projections in plan	
		Beam elementary design faults	Non-continuous beams	
			Non-uniform beam span and cross-section	
	Absence of vertical support at beams intersection			
	Slab elementary design faults	Over-stretched one-way slab		
		Poorly supported or heavily loaded cantilevered slabs		
			Pounding and separation problem	
	Vertical structural configuration	Irregularity in elevation	Weak storey	
Soft storey				
Discontinuity of columns or shear walls				
Vertical structural elementary design fault		Broken axis columns		
		Irregular column and/or shear-wall plan configuration		
		Short column		
Non-Structural Defects				
Building status:	Under Construction		Waterproofing defects, water leakage and seepage	
	Occupied		Defected wooden door	
	Abandoned			
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	
			Condensation	
			Rising damp	
			Rain penetration	
			Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)			Efflorescence
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Paint peeling
	Premature removal of forms			Mouldiness
	Cold joints	Non-structural cracks	Wall finishes workmanship problem	
	Segregation		Staining	
	Honeycombing	Joint cracks		
	Improper grades of slab surfaces			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Other notes (if available): The house is for sale.		
	Cantilevered member cracks			
	Settlement cracks			


Case Study #92 (G17)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Beam elementary design faults	Projections in plan					
	Slab elementary design faults	Non-continuous beams				
Non-uniform beam span and cross-section						
Absence of vertical support at beams intersection						
Broken axis beams and frames						
Over-stretched one-way slab						
Poorly supported or heavily loaded cantilevered slabs						
			Pounding and separation problem			
			Vertical structural configuration	Irregularity in elevation	Weak storey	
					Soft storey	
			Vertical structural elementary design fault	Vertical structural elementary design fault	Discontinuity of columns or shear walls	
					Broken axis columns	
			Irregular column and/or shear-wall plan configuration			
			Short column			
Non-Structural Defects						
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
			Map/pattern cracking			
			Surface cracks on wall finishes	Non-structural cracks	Efflorescence	
					Paint peeling	
			Surface cracks on wall finishes	Non-structural cracks	Mouldiness	
					Wall finishes workmanship problem	
			Staining			
			Joint cracks			
Other notes (if available):						
			Other notes (if available):			
District:	Girne					
Area:	Girne (Kyrenia)					
Street name:	Naci Talat Cd					
Latitude:	35°20'11.54"N					
Longitude:	33°18'23.95"E					
Structure age:	<14 years	Date (if available):				
	Between 14 and 43 years (1974-2003)					
	>43 years (Before 1974)					
Building type:	Residential	Apartment				
		House				
		Dormitory				
	Public					
	Commercial					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned					
Reinforced Concrete Defects						
Drying shrinkage cracks						
Corrosion of metals embedded in concrete	Corrosion-induced cracking					
	Corrosion-induced spalling					
	Cracks due to embedment of dissimilar metals (handrails)					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
	Improper grades of slab surfaces					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					


Case Study #93 (G18)

Profile			Seismic Design Faults					
			Week column-strong beam					
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
Floor discontinuity								
Beam elementary design faults	Projections in plan							
	Non-continuous beams							
	Non-uniform beam span and cross-section							
Slab elementary design faults	Absence of vertical support at beams intersection							
	Broken axis beams and frames							
District: Girne			Pounding and separation problem					
Area: Karaođlanođlu (Agios Georgios)			Vertical structural configuration	Irregularity in elevation	Weak storey			
Street name: Karaođlanođlu Caddesi					Soft storey			
Latitude: 35°20'37.88"N			Vertical structural configuration	Irregularity in elevation	Discontinuity of columns or shear walls			
Longitude: 33°15'42.93"E					Vertical structural element elementary design fault	Broken axis columns		
Structure age:						Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration	
			Building type:				Short column	
Building status:			Non-Structural Defects					
			Under Construction			Waterproofing defects, water leakage and seepage		
						Defected wooden door		
Occupied			Surface defects	dampness	Condensation			
Abandoned					Rising damp			
Reinforced Concrete Defects					Rain penetration			
					Drying shrinkage cracks			Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete			Surface defects	Surface cracks on wall finishes	crazing			
					Corrosion-induced cracking	Map/pattern cracking		
Cracks in RC due to load effects (structural cracks)			Surface defects	Surface cracks on wall finishes	Efflorescence			
					Corrosion-induced spalling	Paint peeling		
Construction defects (faulty workmanship): designer, detailer, and contractor			Surface defects	Non-structural cracks	Mouldiness			
					Cracks due to embedment of dissimilar metals (handrails)	Wall finishes workmanship problem		
					Improper reinforcing steel placement	Staining		
					Premature removal of forms	Joint cracks		
Cracks in RC due to load effects (structural cracks)			Other notes (if available):					
			Cold joints					
			Segregation					
Honeycombing								
Improper grades of slab surfaces								
Slab/beam-to column shear (punching shear) cracks								
Cantilevered member cracks								
Settlement cracks								


Case Study #94(G19)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Absence of vertical support at beams intersection		Slab elementary design faults	Over-stretched one-way slab		
Broken axis beams and frames			Poorly supported or heavily loaded cantilevered slabs		
District: Girne		Pounding and separation problem			
Area: Karaoğlanoğlu (Agios Georgios)		Vertical structural configuration	Irregularity in elevation	Weak storey	
Street name: Karaoğlanoğlu Caddesi				Soft storey	
Latitude: 35°20'37.55"N			Vertical structural element elementary design fault	Discontinuity of columns or shear walls	
Longitude: 33°15'44.01"E				Broken axis columns	
Structure age:		Irregular column and/or shear-wall plan configuration			
Building type:		Short column			
Building status:		Non-Structural Defects			
Under Construction		Waterproofing defects, water leakage and seepage			
Occupied		Defected wooden door			
Abandoned		Condensation			
Reinforced Concrete Defects		Rising damp			
Drying shrinkage cracks		Rain penetration			
Corrosion of metals embedded in concrete		Leaking pipes, spills and other moisture sources			
Cracks due to embedment of dissimilar metals (handrails)		Surface defects	dampness	Surface cracks on wall finishes	
Improper reinforcing steel placement				crazing	
Premature removal of forms			Map/pattern cracking		
Cold joints			Efflorescence		
Segregation		Paint peeling			
Honeycombing		Mouldiness			
Improper grades of slab surfaces		Wall finishes workmanship problem			
Slab/beam-to column shear (punching shear) cracks		Staining			
Cantilevered member cracks		Non-structural cracks			
Settlement cracks		Joint cracks			
Cracks in RC due to load effects (structural cracks)		<u>Other notes (if available):</u>			


Case Study #95 (G20)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Over-stretched one-way slab					
	Poorly supported or heavily loaded cantilevered slabs					
			Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural element elementary design fault	Broken axis columns				
Irregular column and/or shear-wall plan configuration						
			Short column			
			Non-Structural Defects			
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	cr crazing				
		Map/pattern cracking				
		Efflorescence				
Construction defects (faulty workmanship): designer, detailer, and contractor	Non-structural cracks	Paint peeling				
		Mouldiness				
		Wall finishes workmanship problem				
		Staining				
		Joint cracks				
			<u>Other notes (if available):</u>			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					
District:	Girne					
Area:	Alsancak (Karavas)					
Street name:	Ankara Cd					
Latitude:	35°20'47.44"N					
Longitude:	33°12'20.04"E					
Structure age:	<14 years	Date (if available):				
	Between 14 and 43 years (1974-2003)					
	>43 years (Before 1974)					
Building type:	Residential	Apartment				
		House				
		Dormitory				
	Public					
Commercial						
Building status:	Under Construction					
	Occupied					
	Abandoned					


Case Study #96 (G21)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
			Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation		Weak storey		
		Soft storey			
Discontinuity of columns or shear walls					
Vertical structural elementary design fault		Broken axis columns			
	Irregular column and/or shear-wall plan configuration				
		Short column			
Non-Structural Defects					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	cr crazing	
	Corrosion-induced spalling			Map/pattern cracking	
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling		
	Premature removal of forms		Mouldiness		
	Cold joints		Wall finishes workmanship problem		
	Segregation		Staining		
	Honeycombing				
Cracks in RC due to load effects (structural cracks)		Improper grades of slab surfaces		Non-structural cracks	Joint cracks
		Slab/beam-to column shear (punching shear) cracks			
		Cantilevered member cracks		Other notes (if available):	
		Settlement cracks			


Case Study #97 (G22)

Profile			Seismic Design Faults							
			Week column-strong beam							
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)				
Floor discontinuity										
Beam elementary design faults	Projections in plan									
	Non-continuous beams									
	Non-uniform beam span and cross-section									
Slab elementary design faults	Absence of vertical support at beams intersection									
	Broken axis beams and frames									
			Over-stretched one-way slab							
			Poorly supported or heavily loaded cantilevered slabs							
			Pounding and separation problem							
Vertical structural configuration	Irregularity in elevation	Weak storey								
		Soft storey								
		Discontinuity of columns or shear walls								
	Vertical structural elementary design fault	Broken axis columns								
Irregular column and/or shear-wall plan configuration										
			Short column							
Non-Structural Defects										
			Waterproofing defects, water leakage and seepage							
			Defected wooden door							
Reinforced Concrete Defects			dampness	Condensation						
				Rising damp						
			Rain penetration							
			Leaking pipes, spills and other moisture sources							
Surface defects	Surface cracks on wall finishes	crazing								
		Map/pattern cracking								
			Efflorescence							
			Paint peeling							
			Mouldiness							
			Wall finishes workmanship problem							
			Staining							
			Non-structural cracks	Joint cracks						
Other notes (if available):										
						Cracks in RC due to load effects (structural cracks)			Slab/beam-to column shear (punching shear) cracks	
									Cantilevered member cracks	
Settlement cracks										


Case Study #98(G23)

Profile			Seismic Design Faults		
			Week column-strong beam		
			Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
District:	Girne				
Area:	Sadrazamköy (Livera)				
Street name:	No street names were found				
Latitude:	35°23'9.85"N				
Longitude:	32°57'48.79"E				
Structure age:	<14 years	Date (if available):			
		2004~2007			
	Between 14 and 43 years (1974-2003)				
>43 years (Before 1974)					
Building type:	Residential	Apartment			
		House			
		Dormitory			
	Public				
Commercial					
Building status:	Under Construction				
	Occupied				
	Abandoned				
Reinforced Concrete Defects			Non-Structural Defects		
Drying shrinkage cracks			Waterproofing defects, water leakage and seepage		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Defected wooden door		
	Corrosion-induced spalling		Condensation		
	Cracks due to embedment of dissimilar metals (handrails)		Rising damp		
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Rain penetration		
	Premature removal of forms		Leaking pipes, spills and other moisture sources		
	Cold joints		Surface defects		
	Segregation				
	Honeycombing		dampness		
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Surface cracks on wall finishes		
	Cantilevered member cracks		crazing		
	Settlement cracks		Map/pattern cracking		
			Efflorescence		
			Paint peeling		
			Mouldiness		
			Wall finishes workmanship problem		
			Staining		
			Non-structural cracks	Joint cracks	
			<u>Other notes (if available):</u>		


Case Study #99 (G24)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
		Poorly supported or heavily loaded cantilevered slabs		
		Pounding and separation problem		
District: Girne		Vertical structural configuration	Irregularity in elevation	Weak storey
				Soft storey
Discontinuity of columns or shear walls				
Area: Sadrazamköy (Livera)			Vertical structural element elementary design fault	Broken axis columns
				Irregular column and/or shear-wall plan configuration
Street name: No street names were found			Short column	
Latitude: 35°23'23.20"N		Non-Structural Defects		
Longitude: 32°56'57.67"E		Waterproofing defects, water leakage and seepage		
Structure age:	<14 years	Date (if available):		
	Between 14 and 43 years (1974-2003)	2004~2007		
	>43 years (Before 1974)			
Building type:	Residential	Apartment		
		House		
		Dormitory		
	Public			
Commercial				
Building status:		Defected wooden door		
Under Construction		Condensation		
Occupied		Rising damp		
Abandoned		Rain penetration		
Reinforced Concrete Defects		Leaking pipes, spills and other moisture sources		
Drying shrinkage cracks		Surface defects	dampness	cr crazing
				Map/pattern cracking
Corrosion of metals embedded in concrete			Surface cracks on wall finishes	Efflorescence
				Paint peeling
Construction defects (faulty workmanship): designer, detailer, and contractor		Non-structural cracks	Mouldiness	
			Wall finishes workmanship problem	
			Staining	
			Joint cracks	
			Cracks in RC due to load effects (structural cracks)	
Slab/beam-to column shear (punching shear) cracks				
Cantilevered member cracks				
		Settlement cracks		


Case Study #100 (G25)

Profile		Seismic Design Faults										
		Week column-strong beam										
District:	Girne (Kyrenia)	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)							
Area:	Arapköy (Klepini)				Floor discontinuity							
Street name:	Beş Parmaklar Cd				Projections in plan							
Latitude:	35°18'6.72"N			Beam elementary design faults	Non-continuous beams							
Longitude:	33°26'9.65"E				Non-uniform beam span and cross-section							
Structure age:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%; text-align: center;"><14 years</td> <td>Date (if available):</td> <td style="text-align: center;">December 2004</td> </tr> <tr> <td style="text-align: center;">Between 14 and 43 years (1974-2003)</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">>43 years (Before 1974)</td> <td></td> <td></td> </tr> </table>				<14 years	Date (if available):	December 2004	Between 14 and 43 years (1974-2003)			>43 years (Before 1974)	
<14 years	Date (if available):	December 2004										
Between 14 and 43 years (1974-2003)												
>43 years (Before 1974)												
Building type:	Residential	Apartment	Broken axis beams and frames									
		House	Over-stretched one-way slab									
		Dormitory	Poorly supported or heavily loaded cantilevered slabs									
	Public	Pounding and separation problem										
Commercial	Vertical structural configuration	Irregularity in elevation	Weak storey									
Building status:			Under Construction	Soft storey								
		Occupied	Discontinuity of columns or shear walls									
Abandoned		Broken axis columns										
Reinforced Concrete Defects		Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration	Short column								
Drying shrinkage cracks				Non-Structural Defects								
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Waterproofing defects, water leakage and seepage										
	Corrosion-induced spalling	Defected wooden door										
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)	Surface defects	dampness	Condensation								
	Improper reinforcing steel placement			Rising damp								
	Premature removal of forms			Rain penetration								
	Cold joints			Leaking pipes, spills and other moisture sources								
	Segregation	Surface cracks on wall finishes	cr crazing									
	Honeycombing		Map/pattern cracking									
Improper grades of slab surfaces		Efflorescence										
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Paint peeling									
	Cantilevered member cracks		Mouldiness									
	Settlement cracks		Wall finishes workmanship problem									
		Non-structural cracks	Staining									
			Joint cracks									
		<u>Other notes (if available):</u>										
		<p style="color: red;">This case study is about a suspended project called Amaranta valley project which contain many unfinished houses due to technical and legal problems.</p>										


Case Study #101 (C1)

Profile		Seismic Design Faults															
		Week column-strong beam															
District:	Mağusa	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)												
Area:	Gazimağusa Sanayi Bölgesi (Famagusta Greater Industrial Area)				Beam elementary design faults	Floor discontinuity											
Street name:	Yeni Hastane Yolu					Projections in plan											
Latitude:	N 35°8.646' (35°8'38.8")			Non-continuous beams													
Longitude:	E 33°54.189' (33°54'11.3")			Non-uniform beam span and cross-section													
Structure age:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;"><14 years</td> <td>Date (if available):</td> <td style="background-color: red;"></td> </tr> <tr> <td></td> <td style="text-align: center;">2004 ~ 2007</td> <td></td> </tr> <tr> <td colspan="3" style="text-align: center;">Between 14 and 43 years (1974-2003)</td> </tr> <tr> <td colspan="3" style="text-align: center;">>43 years (Before 1974)</td> </tr> </table>			<14 years	Date (if available):			2004 ~ 2007		Between 14 and 43 years (1974-2003)			>43 years (Before 1974)			Slab elementary design faults	Absence of vertical support at beams intersection
<14 years	Date (if available):																
	2004 ~ 2007																
Between 14 and 43 years (1974-2003)																	
>43 years (Before 1974)																	
Building type:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td rowspan="3" style="text-align: center;">Residential</td> <td>Apartment</td> <td></td> </tr> <tr> <td>House</td> <td></td> </tr> <tr> <td>Dormitory</td> <td></td> </tr> <tr> <td colspan="2">Public</td> <td></td> </tr> <tr> <td colspan="2">Commercial</td> <td style="background-color: red;"></td> </tr> </table>	Residential	Apartment		House		Dormitory		Public			Commercial			Pounding and separation problem	Broken axis beams and frames	
Residential	Apartment																
	House																
	Dormitory																
Public																	
Commercial																	
Building status:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Under Construction</td> <td style="background-color: red;"></td> </tr> <tr> <td>Occupied</td> <td></td> </tr> <tr> <td>Abandoned</td> <td></td> </tr> </table>	Under Construction		Occupied		Abandoned		Vertical structural configuration	Irregularity in elevation	Over-stretched one-way slab							
Under Construction																	
Occupied																	
Abandoned																	
Reinforced Concrete Defects		Weak storey															
Drying shrinkage cracks		Soft storey															
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Discontinuity of columns or shear walls															
	Corrosion-induced spalling	Broken axis columns															
	Cracks due to embedment of dissimilar metals (handrails)	Irregular column and/or shear-wall plan configuration															
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement	Vertical structural element elementary design fault	Short column														
	Premature removal of forms	Non-Structural Defects															
	Cold joints	Waterproofing defects, water leakage and seepage															
	Segregation	Defected wooden door															
	Honeycombing	Condensation															
	Improper grades of slab surfaces	Rising damp															
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Rain penetration															
	Cantilevered member cracks	Leaking pipes, spills and other moisture sources															
	Settlement cracks	Surface defects															
		Surface defects	dampness	Surface cracks on wall finishes													
				Non-structural cracks	crazing												
					Map/pattern cracking												
		Efflorescence															
		Paint peeling															
		Mouldiness															
		Wall finishes workmanship problem															
		Staining															
		Joint cracks															
		<u>Other notes (if available):</u>															


Case Study #102 (C2)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
	Vertical structural element elementary design fault	Broken axis columns		
Irregular column and/or shear-wall plan configuration				
		Short column		
Non-Structural Defects				
Building status:	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
	Abandoned			
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	cracking
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling	
	Premature removal of forms		Mouldiness	
	Cold joints		Wall finishes workmanship problem	
	Segregation	Staining		
	Honeycombing	Joint cracks		
		Non-structural cracks		
			Other notes (if available):	
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			


Case Study #103 (C3)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
District: Mağusa		Pounding and separation problem		
Area: Gazimağusa Sanayi Bölgesi (Famagusta Greater Industrial Area)				
Street name: Yeni Hastane Yolu		Vertical structural configuration	Irregularity in elevation	Weak storey
Latitude: N 35°8.717' (35°8'43.0")				Soft storey
Longitude: E 33°53.985' (33°53'59.1")		Vertical structural element elementary design fault	Vertical structural element elementary design fault	Discontinuity of columns or shear walls
Structure age:				Broken axis columns
Structure age: <14 years Date (if available): Between 14 and 43 years (1974-2003) >43 years (Before 1974)		Non-Structural Defects		
		Building type: Residential: Apartment, House, Dormitory Public Commercial		Waterproofing defects, water leakage and seepage
Building status:				Defected wooden door
Reinforced Concrete Defects Drying shrinkage cracks		Surface defects	dampness	Condensation
				Under Construction Occupied Abandoned
Corrosion of metals embedded in concrete: Corrosion-induced cracking Corrosion-induced spalling Cracks due to embedment of dissimilar metals (handrails)		Surface cracks on wall finishes	Leaking pipes, spills and other moisture sources	
				Construction defects (faulty workmanship): designer, detailer, and contractor: Improper reinforcing steel placement Premature removal of forms Cold joints Segregation Honeycombing Improper grades of slab surfaces
Cracks in RC due to load effects (structural cracks): Slab/beam-to column shear (punching shear) cracks Cantilevered member cracks Settlement cracks		Other notes (if available):		


Case Study #104 (C4)

Profile		Seismic Design Faults					
		Week column-strong beam					
District:	Mağusa	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
Area:	Sakarya				Beam elementary design faults	Floor discontinuity	
Street name:	Hasan Barboçoli Sk					Projections in plan	
Latitude:	35° 8'1.39"N			Non-continuous beams			
Longitude:	33°55'10.08"E			Non-uniform beam span and cross-section			
Structure age:	<14 years			Slab elementary design faults	Absence of vertical support at beams intersection		
	Date (if available): 2014 ~ 2015		Broken axis beams and frames				
	Between 14 and 43 years (1974-2003)		Over-stretched one-way slab				
	>43 years (Before 1974)		Poorly supported or heavily loaded cantilevered slabs				
Building type:	Residential		Pounding and separation problem				
	Apartment	Vertical structural configuration	Irregularity in elevation	Weak storey			
	House			Soft storey			
	Dormitory		Vertical structural element elementary design fault	Discontinuity of columns or shear walls			
	Public			Broken axis columns			
	Commercial	Short column					
Building status:	Under Construction	Non-Structural Defects					
	Occupied	Waterproofing defects, water leakage and seepage					
	Abandoned	Defected wooden door					
Reinforced Concrete Defects		Surface defects	dampness	Condensation			
Drying shrinkage cracks				Surface cracks on wall finishes	Rising damp		
Corrosion of metals embedded in concrete	Corrosion-induced cracking				Leaking pipes, spills and other moisture sources	Rain penetration	
	Corrosion-induced spalling					Non-structural cracks	Joint cracks
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)				crazing		Efflorescence
	Improper reinforcing steel placement		Map/pattern cracking				
	Premature removal of forms		Efflorescence	Paint peeling			
	Cold joints		Paint peeling	Mouldiness			
	Segregation		Mouldiness	Wall finishes workmanship problem			
Honeycombing	Wall finishes workmanship problem		Staining				
Improper grades of slab surfaces	Staining						
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks	Other notes (if available):					
	Cantilevered member cracks						
	Settlement cracks						


Case Study #105 (C5)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
Slab elementary design faults	Absence of vertical support at beams intersection					
	Broken axis beams and frames					
	Over-stretched one-way slab					
				Poorly supported or heavily loaded cantilevered slabs		
				Pounding and separation problem		
			Vertical structural configuration	Irregularity in elevation	Inter-storey strength irregularity (Weak storey)	
					Inter-storey stiffness irregularity (Soft storey)	
					Discontinuity columns or shear walls	
				Vertical structural element elementary design fault	Broken axis columns	
					Irregular column and/or shear-wall plan configuration	
			Short column			
Non-Structural Defects						
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
	Corrosion of metals embedded in concrete	Corrosion-induced cracking				
		Corrosion-induced spalling				
		Cracks due to embedment of dissimilar metals (handrails)				
	Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
		Premature removal of forms				
		Cold joints				
		Segregation				
		Honeycombing				
		Improper grades of slab surfaces				
	Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
		Cantilevered member cracks				
		Settlement cracks				
			Other notes (if available):			


Case Study #106 (C6)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
	Pounding and separation problem				
Vertical structural configuration	Irregularity in elevation		Weak storey		
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural element elementary design fault	Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
		Short column			
	Non-Structural Defects				
			Waterproofing defects, water leakage and seepage		
			Defected wooden door		
	Reinforced Concrete Defects		Surface defects	dampness	Condensation
Rising damp					
Rain penetration					
Leaking pipes, spills and other moisture sources					
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	crazing			
		Map/pattern cracking			
Construction defects (faulty workmanship): designer, detailer, and contractor	Efflorescence				
	Paint peeling				
	Mouldiness				
	Wall finishes workmanship problem				
	Staining				
	Non-structural cracks			Joint cracks	
<u>Other notes (if available):</u>					
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				


Case Study #107 (C7)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
	Poorly supported or heavily loaded cantilevered slabs				
		Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey			
		Soft storey			
		Discontinuity of columns or shear walls			
	Vertical structural elementary design fault	Broken axis columns			
Irregular column and/or shear-wall plan configuration					
		Short column			
Non-Structural Defects					
Building status:	Under Construction		Waterproofing defects, water leakage and seepage		
	Occupied		Defected wooden door		
	Abandoned				
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
		Surface defects	Surface cracks on wall finishes	crazing	
				Map/pattern cracking	
			Efflorescence		
			Paint peeling		
			Mouldiness		
			Wall finishes workmanship problem		
		Staining			
		Non-structural cracks	Joint cracks		
<u>Other notes (if available):</u>					


Case Study #108 (C8)

Profile			Seismic Design Faults				
			Week column-strong beam				
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
						Floor discontinuity	
						Projections in plan	
				Beam elementary design faults	Non-continuous beams		
					Non-uniform beam span and cross-section		
					Absence of vertical support at beams intersection		
			Slab elementary design faults	Over-stretched one-way slab			
				Poorly supported or heavily loaded cantilevered slabs			
				Pounding and separation problem			
Vertical structural configuration	Irregularity in elevation	Weak storey					
		Soft storey					
		Discontinuity of columns or shear walls					
	Vertical structural element elementary design fault	Broken axis columns					
		Irregular column and/or shear-wall plan configuration					
		Short column					
Non-Structural Defects			Waterproofing defects, water leakage and seepage				
Reinforced Concrete Defects			Defected wooden door				
			Surface defects	dampness	Condensation		
					Rising damp		
					Rain penetration		
					Leaking pipes, spills and other moisture sources		
Surface cracks on wall finishes	cr crazing						
	Map/pattern cracking						
	Efflorescence						
Non-structural cracks	Paint peeling						
	Mouldiness						
	Wall finishes workmanship problem						
	Staining						
	Joint cracks						
	Other notes (if available):						
District:	Mağusa						
Area:	Karakol						
Street name:	İsmet İnönü Blv						
Latitude:	35° 8'19.51"N						
Longitude:	33° 55'3.70"E						
Structure age:	<14 years	Date (if available):					
	Between 14 and 43 years (1974-2003)	Late 2015					
	>43 years (Before 1974)						
Building type:	Residential	Apartment					
		House					
		Dormitory					
	Public						
	Commercial						
Building status:	Under Construction						
	Occupied						
	Abandoned						
Corrosion of metals embedded in concrete	Corrosion-induced cracking						
	Corrosion-induced spalling						
	Cracks due to embedment of dissimilar metals (handrails)						
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement						
	Premature removal of forms						
	Cold joints						
	Segregation						
	Honeycombing						
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces						
	Slab/beam-to column shear (punching shear) cracks						
	Cantilevered member cracks						
	Settlement cracks						


Case Study #109 (C9)

Profile		Seismic Design Faults		
		Week column-strong beam		
Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
			Floor discontinuity	
			Projections in plan	
		Beam elementary design faults	Non-continuous beams	
			Non-uniform beam span and cross-section	
			Absence of vertical support at beams intersection	
	Slab elementary design faults	Broken axis beams and frames		
		Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs	
			Pounding and separation problem	
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
	Vertical structural element elementary design fault	Broken axis columns		
		Irregular column and/or shear-wall plan configuration		
		Short column		
Non-Structural Defects				
Building status:	Under Construction			
	Occupied			
	Abandoned			
Reinforced Concrete Defects				
Drying shrinkage cracks				
Corrosion of metals embedded in concrete	Corrosion-induced cracking			
	Corrosion-induced spalling			
	Cracks due to embedment of dissimilar metals (handrails)			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			
	Premature removal of forms			
	Cold joints			
	Segregation			
	Honeycombing			
Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			
Surface Defects				
Surface defects	dampness	Waterproofing defects, water leakage and seepage		
		Defected wooden door		
		Condensation		
		Rising damp		
		Rain penetration		
	Surface cracks on wall finishes	Leaking pipes, spills and other moisture sources		
		crazing		
		Map/pattern cracking		
		Efflorescence		
		Paint peeling		
Non-structural cracks	Mouldiness			
	Wall finishes workmanship problem			
	Staining			
	Joint cracks			
<u>Other notes (if available):</u>				


Case Study #110 (C10)

Profile		Seismic Design Faults		
		Week column-strong beam		
Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
			Floor discontinuity	
			Projections in plan	
		Beam elementary design faults	Non-continuous beams	
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
	Slab elementary design faults	Broken axis beams and frames		
		Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs	
			Pounding and separation problem	
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
	Vertical structural elementary design fault	Broken axis columns		
		Irregular column and/or shear-wall plan configuration		
		Short column		
Non-Structural Defects				
Building status:	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
	Abandoned			
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	
				Condensation
				Rising damp
				Rain penetration
			Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)			Efflorescence
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement			Paint peeling
	Premature removal of forms			Mouldiness
	Cold joints		Wall finishes workmanship problem	
	Segregation		Staining	
	Honeycombing			
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Non-structural cracks	Joint cracks	
	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			
Other notes (if available):				
Apartment name: UZUN 23				


Case Study #111 (C11)

Profile			Seismic Design Faults		
			Week column-strong beam		
			Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity					
Projections in plan					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
	Over-stretched one-way slab				
				Poorly supported or heavily loaded cantilevered slabs	
				Pounding and separation problem	
Vertical structural configuration	Irregularity in elevation	Inter-storey strength irregularity (Weak storey)			
		Inter-storey stiffness irregularity (Soft storey)			
		Discontinuity of columns or shear walls			
		Broken axis columns			
		Irregular column and/or shear-wall plan configuration			
	Vertical structural element elementary design fault	Short column			
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Condensation			
Surface defects	dampness	Rising damp			
		Rain penetration			
		Leaking pipes, spills and other moisture sources			
		Surface cracks on wall finishes	crazing		
			Map/pattern cracking		
			Efflorescence		
			Paint peeling		
			Mouldiness		
			Wall finishes workmanship problem		
			Staining		
		Non-structural cracks	Joint cracks		
Reinforced Concrete Defects			<u>Other notes (if available):</u>		
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
District:	Mağusa				
Area:	Karakol				
Street name:	M. Abdullah Sk				
Latitude:	35° 7'56.90"N				
Longitude:	33°55'49.67"E				
Structure age:	<14 years	Date (if available):			
		2015			
	Between 14 and 43 years (1974-2003)				
>43 years (Before 1974)					
Building type:	Residential	Apartment			
		House			
		Dormitory			
	Public				
Commercial					
Building status:	Under Construction				
	Occupied				
	Abandoned				


Case Study #112 (C12)

Profile		Seismic Design Faults			
		Week column-strong beam			
District:	Mağusa	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Area:	Çanakkale				Floor discontinuity
Street name:	Hacı Bektaş Sk			Beam elementary design faults	Projections in plan
Latitude:	35° 7'44.46"N				Non-continuous beams
Longitude:	33°55'4.14"E		Non-uniform beam span and cross-section		
Structure age:	<14 years		Vertical structural configuration	Irregularity in elevation	Absence of vertical support at beams intersection
	Between 14 and 43 years (1974-2003)				Broken axis beams and frames
	>43 years (Before 1974)				Over-stretched one-way slab
Building type:	Residential		Vertical structural element elementary design fault	Vertical structural element elementary design fault	Poorly supported or heavily loaded cantilevered slabs
					Apartment
		House			Inter-storey strength irregularity (Weak storey)
	Dormitory	Inter-storey stiffness irregularity (Soft storey)			
	Public			Discontinuity of columns or shear walls	
	Commercial			Broken axis columns	
Building status:	Under Construction	Non-Structural Defects			
	Occupied	Waterproofing defects, water leakage and seepage			
	Abandoned	Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
Drying shrinkage cracks				Rising damp	
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Rain penetration	
	Corrosion-induced spalling			Leaking pipes, spills and other moisture sources	
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)		Surface cracks on wall finishes	crazing	
	Improper reinforcing steel placement			Map/pattern cracking	
	Premature removal of forms		Efflorescence		
	Cold joints		Paint peeling		
	Segregation		Mouldiness		
	Honeycombing		Wall finishes workmanship problem		
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Non-structural cracks	Staining		
	Slab/beam-to column shear (punching shear) cracks		Joint cracks		
	Cantilevered member cracks		<u>Other notes (if available):</u>		
	Settlement cracks				


Case Study #113 (C13)

Profile			Seismic Design Faults				
			Week column-strong beam				
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
						Floor discontinuity	
						Projections in plan	
					Beam elementary design faults	Non-continuous beams	
						Non-uniform beam span and cross-section	
				Slab elementary design faults	Absence of vertical support at beams intersection		
					Broken axis beams and frames		
					Over-stretched one-way slab		
							Poorly supported or heavily loaded cantilevered slabs
				Pounding and separation problem			
			Inter-storey strength irregularity (Weak storey)				
			Inter-storey stiffness irregularity (Soft storey)				
			Discontinuity of columns or shear walls				
			Broken axis columns				
			Irregular column and/or shear-wall plan configuration				
			Short column				
Non-Structural Defects							
			Waterproofing defects, water leakage and seepage				
			Defected wooden door				
			Condensation				
			Rising damp				
			Rain penetration				
			Leaking pipes, spills and other moisture sources				
Reinforced Concrete Defects							
Drying shrinkage cracks							
Corrosion of metals embedded in concrete	Corrosion-induced cracking						
	Corrosion-induced spalling						
	Cracks due to embedment of dissimilar metals (handrails)						
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement						
	Premature removal of forms						
	Cold joints						
	Segregation						
	Honeycombing						
	Improper grades of slab surfaces						
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks						
	Cantilevered member cracks						
	Settlement cracks						
			Surface defects				
			dampness				
			Surface cracks on wall finishes	crazing			
				Map/pattern cracking			
				Efflorescence			
				Paint peeling			
				Mouldiness			
				Wall finishes workmanship problem			
				Staining			
			Non-structural cracks	Joint cracks			
<u>Other notes (if available):</u>							


Case Study #114 (C14)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Non-continuous beams				
	Non-uniform beam span and cross-section				
	Absence of vertical support at beams intersection				
Slab elementary design faults	Broken axis beams and frames				
	Over-stretched one-way slab				
				Poorly supported or heavily loaded cantilevered slabs	
		Pounding and separation problem			
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
			Vertical structural elementary design fault	Discontinuity of columns or shear walls	
				Broken axis columns	
		Irregular column and/or shear-wall plan configuration			
		Short column			
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
		Surface cracks on wall finishes		crazing	
				Map/pattern cracking	
		Efflorescence			
		Paint peeling			
		Mouldiness			
		Wall finishes workmanship problem			
		Staining			
		Non-structural cracks	Joint cracks		
		Reinforced Concrete Defects			
		Drying shrinkage cracks			
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
		Improper grades of slab surfaces			
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		Other notes (if available):			


Case Study #115 (C15)

Profile		Seismic Design Faults								
		Week column-strong beam								
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)					
Floor discontinuity										
Projections in plan										
Beam elementary design faults	Non-continuous beams									
	Non-uniform beam span and cross-section									
	Absence of vertical support at beams intersection									
Slab elementary design faults	Over-stretched one-way slab									
	Poorly supported or heavily loaded cantilevered slabs									
		Pounding and separation problem								
District:	Mağusa	Vertical structural configuration	Irregularity in elevation	Weak storey						
Area:	Çanakkale			Soft storey						
Street name:	No street names were found			Discontinuity of columns or shear walls						
Latitude:	35° 7'19.23"N		Vertical structural element elementary design fault	Broken axis columns						
Longitude:	33°55'22.74"E			Irregular column and/or shear-wall plan configuration						
Structure age:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%; text-align: center;"><14 years</td> <td>Date (if available):</td> </tr> <tr> <td></td> <td style="text-align: center;">March 2016</td> </tr> <tr> <td colspan="2" style="text-align: center;">Between 14 and 43 years (1974-2003)</td> </tr> <tr> <td colspan="2" style="text-align: center;">>43 years (Before 1974)</td> </tr> </table>			<14 years	Date (if available):		March 2016	Between 14 and 43 years (1974-2003)		>43 years (Before 1974)
<14 years	Date (if available):									
	March 2016									
Between 14 and 43 years (1974-2003)										
>43 years (Before 1974)										
Building type:	Residential	Apartment								
		House								
		Dormitory								
	Public									
	Commercial	Non-Structural Defects								
Building status:	Waterproofing defects, water leakage and seepage									
	Defected wooden door									
	Abandoned									
Reinforced Concrete Defects		Surface defects	dampness	Condensation						
Drying shrinkage cracks				Rising damp						
Corrosion of metals embedded in concrete	Corrosion-induced cracking			Rain penetration						
	Corrosion-induced spalling			Leaking pipes, spills and other moisture sources						
Construction defects (faulty workmanship): designer, detailer, and contractor	Cracks due to embedment of dissimilar metals (handrails)		Surface cracks on wall finishes	crazing						
	Improper reinforcing steel placement			Map/pattern cracking						
	Premature removal of forms		Efflorescence							
	Cold joints		Paint peeling							
	Segregation		Mouldiness							
	Honeycombing		Wall finishes workmanship problem							
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces	Non-structural cracks	Staining							
	Slab/beam-to column shear (punching shear) cracks		Joint cracks							
	Cantilevered member cracks	<u>Other notes (if available):</u>								
Settlement cracks										


Case Study #116 (C16)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)	
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Over-stretched one-way slab					
	Poorly supported or heavily loaded cantilevered slabs					
		Pounding and separation problem				
Structure age:	<14 years	Date (if available):				
		Mid 2016				
	Between 14 and 43 years (1974-2003)					
	>43 years (Before 1974)					
Building type:	Residential	Apartment				
		House				
		Dormitory				
	Public					
		Commercial				
Building status:	Under Construction		Waterproofing defects, water leakage and seepage			
	Occupied		Defected wooden door			
	Abandoned					
Reinforced Concrete Defects						
Drying shrinkage cracks		Surface defects	dampness	Condensation		
				Rising damp		
				Rain penetration		
				Leaking pipes, spills and other moisture sources		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing		
	Corrosion-induced spalling			Map/pattern cracking		
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling			
	Premature removal of forms		Mouldiness			
	Cold joints		Wall finishes workmanship problem			
	Segregation		Staining			
	Honeycombing					
	Improper grades of slab surfaces					
		Non-structural cracks	Joint cracks			
Other notes (if available):						
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					


Case Study #117 (C17)

Profile			Seismic Design Faults			
			Week column-strong beam			
			Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity						
Projections in plan						
Beam elementary design faults	Non-continuous beams					
	Non-uniform beam span and cross-section					
	Absence of vertical support at beams intersection					
Slab elementary design faults	Over-stretched one-way slab					
	Poorly supported or heavily loaded cantilevered slabs					
Pounding and separation problem						
Vertical structural configuration	Irregularity in elevation	Weak storey				
		Soft storey				
		Discontinuity of columns or shear walls				
	Vertical structural elementary design fault	Broken axis columns				
		Irregular column and/or shear-wall plan configuration				
	Short column					
Non-Structural Defects						
			Waterproofing defects, water leakage and seepage			
			Defected wooden door			
Reinforced Concrete Defects			Surface defects	dampness	Condensation	
					Rising damp	
					Rain penetration	
					Leaking pipes, spills and other moisture sources	
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	Cracking	crazing			
		Corrosion-induced spalling	Map/pattern cracking			
		Cracks due to embedment of dissimilar metals (handrails)	Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement					
	Premature removal of forms					
	Cold joints					
	Segregation					
	Honeycombing					
Cracks in RC due to load effects (structural cracks)	Improper grades of slab surfaces					
	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
		Settlement cracks				
Other notes (if available):						
District:	Mağusa					
Area:	Çanakkale					
Street name:	Sht. İbrahim Kazım Cd					
Latitude:	35° 7'31.93"N					
Longitude:	33°55'20.07"E					
Structure age:	<14 years	Date (if available):				
	Between 14 and 43 years (1974-2003)	2017				
	>43 years (Before 1974)					
Building type:	Residential	Apartment				
		House				
		Dormitory				
	Public					
	Commercial					
Building status:	Under Construction					
	Occupied					
	Abandoned					


Case Study #118 (C18)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
Floor discontinuity					
Beam elementary design faults	Projections in plan				
	Non-continuous beams				
	Non-uniform beam span and cross-section				
Slab elementary design faults	Absence of vertical support at beams intersection				
	Broken axis beams and frames				
	Over-stretched one-way slab				
			Pounding and separation problem		
			Vertical structural configuration	Irregularity in elevation	Weak storey
		Soft storey			
		Discontinuity of columns or shear walls			
		Vertical structural element elementary design fault		Broken axis columns	
				Irregular column and/or shear-wall plan configuration	
		Short column			
Non-Structural Defects					
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
Reinforced Concrete Defects		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
		Corrosion of metals embedded in concrete	Surface cracks on wall finishes	crazing	
Map/pattern cracking					
Construction defects (faulty workmanship): designer, detailer, and contractor	Efflorescence				
	Paint peeling				
	Mouldiness				
	Wall finishes workmanship problem				
	Staining				
	Non-structural cracks		Joint cracks		
Other notes (if available):					
				Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks
					Cantilevered member cracks
					Settlement cracks


Case Study #119 (C19)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Projections in plan	
			Beam elementary design faults	Non-continuous beams	
				Non-uniform beam span and cross-section	
				Absence of vertical support at beams intersection	
		Slab elementary design faults	Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs		
				Pounding and separation problem	
		Vertical structural configuration	Irregularity in elevation	Weak storey	
				Soft storey	
			Discontinuity of columns or shear walls		
			Broken axis columns		
		Vertical structural element elementary design fault	Irregular column and/or shear-wall plan configuration		
			Short column		
		Non-Structural Defects			
		Waterproofing defects, water leakage and seepage			
		Defected wooden door			
		Surface defects	dampness	Condensation	
				Rising damp	
				Rain penetration	
				Leaking pipes, spills and other moisture sources	
		Surface cracks on wall finishes	Non-structural cracks	crazing	
				Map/pattern cracking	
				Efflorescence	
				Paint peeling	
				Mouldiness	
				Wall finishes workmanship problem	
				Staining	
				Joint cracks	
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking				
	Corrosion-induced spalling				
	Cracks due to embedment of dissimilar metals (handrails)				
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement				
	Premature removal of forms				
	Cold joints				
	Segregation				
	Honeycombing				
	Improper grades of slab surfaces				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks				
	Cantilevered member cracks				
	Settlement cracks				
		<u>Other notes (if available):</u>			


Case Study #120 (C20)

Profile		Seismic Design Faults				
		Week column-strong beam				
		Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)		
				Floor discontinuity		
Structural configuration	Beam elementary design faults	Vertical structural configuration	Irregularity in elevation	Projections in plan		
				Non-continuous beams		
				Non-uniform beam span and cross-section		
				Absence of vertical support at beams intersection		
	Slab elementary design faults	Vertical structural element elementary design fault	Vertical structural element elementary design fault	Broken axis beams and frames		
				Over-stretched one-way slab		
			Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem				
District: Mağusa						
Area: Tuzla (Enkomi)						
Street name: Sadık Cemil Sk						
Latitude: 35° 9'16.43"N						
Longitude: 33°53'44.12"E						
Structure age:	<14 years	Date (if available):				
		2015				
	Between 14 and 43 years (1974-2003)					
	>43 years (Before 1974)					
Building type:	Residential	Apartment				
		House				
		Dormitory				
	Public					
	Commercial					
Building status:	Under Construction					
	Occupied					
	Abandoned					
Non-Structural Defects						
		Waterproofing defects, water leakage and seepage				
		Defected wooden door				
		Surface defects	dampness	Condensation		
				Rising damp		
				Rain penetration		
				Leaking pipes, spills and other moisture sources		
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	crazing		
	Corrosion-induced spalling			Map/pattern cracking		
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence			
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling			
	Premature removal of forms		Mouldiness			
	Cold joints		Wall finishes workmanship problem			
	Segregation		Staining			
	Honeycombing		Non-structural cracks	Joint cracks		
	Improper grades of slab surfaces					
<u>Other notes (if available):</u>						
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks					
	Cantilevered member cracks					
	Settlement cracks					


Case Study #121 (C21)

Profile		Seismic Design Faults										
		Week column-strong beam										
District:	Mağusa	Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)							
Area:	Tuzla (Enkomi)				Floor discontinuity							
Street name:	No street names were found				Projections in plan							
Latitude:	35° 9'18.67"N			Beam elementary design faults	Non-continuous beams							
Longitude:	33°53'23.00"E				Non-uniform beam span and cross-section							
Structure age:	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%; text-align: center;"><14 years</td> <td>Date (if available):</td> <td style="text-align: center;">2017</td> </tr> <tr> <td colspan="3" style="text-align: center;">Between 14 and 43 years (1974-2003)</td> </tr> <tr> <td colspan="3" style="text-align: center;">>43 years (Before 1974)</td> </tr> </table>				<14 years	Date (if available):	2017	Between 14 and 43 years (1974-2003)			>43 years (Before 1974)	
<14 years	Date (if available):		2017									
Between 14 and 43 years (1974-2003)												
>43 years (Before 1974)												
Building type:	Residential		Apartment	Broken axis beams and frames								
		House	Over-stretched one-way slab									
		Dormitory	Poorly supported or heavily loaded cantilevered slabs									
	Public	Pounding and separation problem										
Commercial	Vertical structural configuration	Irregularity in elevation	Weak storey									
Building status:			Under Construction	Soft storey								
			Occupied	Discontinuity of columns or shear walls								
			Abandoned	Broken axis columns								
Reinforced Concrete Defects		Vertical structural elementary design fault	Irregular column and/or shear-wall plan configuration	Irregular column and/or shear-wall plan configuration								
Drying shrinkage cracks				Short column								
Corrosion of metals embedded in concrete		Non-Structural Defects										
		Waterproofing defects, water leakage and seepage										
Construction defects (faulty workmanship): designer, detailer, and contractor		Defected wooden door										
		Surface defects	dampness	Condensation								
				Rising damp								
				Rain penetration								
Leaking pipes, spills and other moisture sources												
Cracks in RC due to load effects (structural cracks)		Surface cracks on wall finishes	Non-structural cracks	Cracking								
				Map/pattern cracking								
Cracks in RC due to load effects (structural cracks)		Efflorescence										
		Paint peeling										
		Mouldiness										
Cracks in RC due to load effects (structural cracks)		Wall finishes workmanship problem										
		Staining										
		Joint cracks										
Other notes (if available):												


Case Study #122 (C22)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Beam elementary design faults	Projections in plan			
	Non-continuous beams			
	Non-uniform beam span and cross-section			
Slab elementary design faults	Absence of vertical support at beams intersection			
	Broken axis beams and frames			
District: <b style="color: red;">Mağusa		Pounding and separation problem		
				Area: <b style="color: red;">Tuzla (Enkomi)
Street name: <b style="color: red;">No street names were found		Vertical structural configuration		
Latitude: <b style="color: red;">35° 9'18.93"N				
Longitude: <b style="color: red;">33°53'23.79"E		Irregularity in elevation	Weak storey	
Structure age:			Soft storey	
			Discontinuity of columns or shear walls	
Building type:		Vertical structural elementary design fault	Broken axis columns	
			Irregular column and/or shear-wall plan configuration	
		Short column		
Building status:		Non-Structural Defects		
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
Drying shrinkage cracks				Rising damp
				Rain penetration
Corrosion of metals embedded in concrete				Leaking pipes, spills and other moisture sources
			Surface cracks on wall finishes	crazing
Construction defects (faulty workmanship): designer, detailer, and contractor				Map/pattern cracking
			Efflorescence	
Cracks in RC due to load effects (structural cracks)			Paint peeling	
			Mouldiness	
			Wall finishes workmanship problem	
Cracks in RC due to load effects (structural cracks)		Non-structural cracks	Staining	
			Joint cracks	
		Cracks in RC due to load effects (structural cracks)		Other notes (if available):
Settlement cracks				


Case Study #123 (C23)

Profile		Seismic Design Faults		
		Weak column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Broken axis beams and frames			
	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
			Pounding and separation problem	
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
Vertical structural element elementary design fault	Broken axis columns			
	Irregular column and/or shear-wall plan configuration			
	Short column			
Non-Structural Defects				
Building status:	Under Construction	Waterproofing defects, water leakage and seepage		
	Occupied	Defected wooden door		
	Abandoned			
Reinforced Concrete Defects				
Drying shrinkage cracks		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Corrosion-induced cracking		Surface cracks on wall finishes	cracking
	Corrosion-induced spalling			Map/pattern cracking
	Cracks due to embedment of dissimilar metals (handrails)		Efflorescence	
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Paint peeling	
	Premature removal of forms		Mouldiness	
	Cold joints		Wall finishes workmanship problem	
	Segregation	Staining		
	Honeycombing			
	Improper grades of slab surfaces			
		Non-structural cracks	Joint cracks	
<u>Other notes (if available):</u>				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			

Case Study #124 (C24)

Profile		Seismic Design Faults		
		Week column-strong beam		
		Structural configuration	Horizontal structural configuration	Irregularity in plan
Floor discontinuity				
Projections in plan				
Beam elementary design faults	Non-continuous beams			
	Non-uniform beam span and cross-section			
	Absence of vertical support at beams intersection			
Slab elementary design faults	Over-stretched one-way slab			
	Poorly supported or heavily loaded cantilevered slabs			
		Pounding and separation problem		
Vertical structural configuration	Irregularity in elevation	Weak storey		
		Soft storey		
		Discontinuity of columns or shear walls		
	Vertical structural elementary design fault	Broken axis columns		
Irregular column and/or shear-wall plan configuration				
		Short column		
Non-Structural Defects				
		Waterproofing defects, water leakage and seepage		
		Defected wooden door		
Reinforced Concrete Defects		Surface defects	dampness	Condensation
				Rising damp
				Rain penetration
				Leaking pipes, spills and other moisture sources
Corrosion of metals embedded in concrete	Surface cracks on wall finishes	cr crazing		
		Map/pattern cracking		
Construction defects (faulty workmanship): designer, detailer, and contractor	Efflorescence			
	Paint peeling			
	Mouldiness			
	Wall finishes workmanship problem			
	Staining			
	Joint cracks			
		Non-structural cracks		
<u>Other notes (if available):</u>				
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks			
	Cantilevered member cracks			
	Settlement cracks			

Case Study #65/125 (L15/C25)

Profile		Seismic Design Faults			
		Week column-strong beam			
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)
					Floor discontinuity
				Projections in plan	
			Beam elementary design faults	Non-continuous beams	
				Non-uniform beam span and cross-section	
				Absence of vertical support at beams intersection	
		Slab elementary design faults	Broken axis beams and frames		
			Over-stretched one-way slab		
		Poorly supported or heavily loaded cantilevered slabs			
Pounding and separation problem					
Weak storey					
Soft storey					
Discontinuity of columns or shear walls					
Broken axis columns					
Irregular column and/or shear-wall plan configuration					
Short column					
Non-Structural Defects					
Under Construction		Waterproofing defects, water leakage and seepage			
Occupied		Defected wooden door			
Abandoned					
Reinforced Concrete Defects					
Drying shrinkage cracks					
Corrosion of metals embedded in concrete	Corrosion-induced cracking	Surface defects	dampness	Condensation	
	Corrosion-induced spalling			Rising damp	
	Cracks due to embedment of dissimilar metals (handrails)			Improper reinforcing steel placement	Rain penetration
Premature removal of forms				Leaking pipes, spills and other moisture sources	
Construction defects (faulty workmanship): designer, detailer, and contractor	Cold joints		Surface cracks on wall finishes	crazing	
	Segregation			Map/pattern cracking	
	Honeycombing	Efflorescence			
	Improper grades of slab surfaces	Paint peeling			
		Mouldiness			
Non-structural cracks	Joint cracks				
Other notes (if available):					
Cracks in RC due to load effects (structural cracks)		<p>The building is not finished except for the ground floor where it is furnished and occupied. Thus it is considered a shared case study between Lefcosa case study section and the under construction case study section.</p>			
Slab/beam-to column shear (punching shear) cracks					
Cantilevered member cracks					
Settlement cracks					

5.5 Findings and Discussion

5.5.1 Sample 1: Completed Buildings

5.5.1.1 Building Ages of the Case Study Sample




Figure 5.1: Pie Chart Showing the Statistics for Ages of the Case Studies

While roaming around North Cyprus looking for case studies, it was found that the easiest buildings to find are of those aged between 14 and 43 years old. Thus this age range composed the majority of the case studies in all the four cities (60% overall).

It is difficult to find intensely defected buildings that are younger than 14 years old, thus they composed the minority of the case studies with an overall percentage of 18%. However, in the cities of Lefkoşa and Girne this age group was not the minority with percentages of 24% and 32% respectively. This could be because these 2 cities are larger in urban than Mağusa and İskele which results for a higher demand for developments and thus more chance to find defected new buildings (see Table 1.1).

On the other hand, old buildings (buildings before 1974) are quite easy to find in North Cyprus. They are mostly abandoned and excessively defected. They composed 22% of the overall sample. Worthy to mention, the district of Mağusa included the highest percentage of old building at 40% followed by İskele at 24%. This is not a surprise since Mağusa contains the famous ghost city named Maraş/Varosha. The area around this ghost city and the areas near the border between the Turkish Republic of North Cyprus and the Republic of Cyprus contain abundant of old buildings.

5.5.1.2 Building Type




Figure 5.2: Pie Chart Showing the Statistics for Building Types of the Case Studies

Residential Building types composed the majority of the case studies (87%). They varied between houses (58%), apartments (25%) and apartments with commercial shops on the ground floor (4%). The house type represented the majority of the residential buildings in all the cities except for Mağusa where apartment case studies were more than house ones (52% apartment type residential buildings in Mağusa). Apartments with commercial shops composed 4% and existed only in the cities of İskele and Girne with a percentage of 12% (3 cases) and 4% (1 case) respectively.

On the other hand, commercial type buildings composed only 12% of the sample and varied between 8% in both Lefkoşa and Girne (2 cases each), 12% (3 cases) in İskele and 20% (5 cases) in Mağusa. There was only a single case of public building type in the city on Mağusa.

5.5.1.3 Building Status




Figure 5.3: Pie Chart Showing the Statistics for Status of the Case Studies (Whether Occupied or Abandoned) and the Ages of Abandoned Buildings for Mağusa, İskele and Lefkoşa Districts




Figure 5.4: Pie Chart Showing the Statistics for Status of the Case Studies (Whether Occupied or Abandoned) and the Ages of Abandoned Buildings for Girne District and Overall

For relevance issues, abandoned building were kept minimum (18% of the case studies were abandoned buildings). There are 3 abandoned buildings for each district (12% per district) except for the district of Mağusa which has 9 (36% of Gazimagiusa case studies). No surprise, most of these abandoned building are older than 43 years (72% of the abandoned building are older than 43 years old) as abandoned buildings younger than 43 years old made 28% of the total abandoned buildings.

5.5.1.4 Defects




Figure 5.6: Bar Chart Showing the Occurrence of Defects in Mağusa District (M1-M25)

Mağusa had the highest percentage of crazing (72%). Besides, it had the highest corrosion-induced cracking and spalling with percentages of 80% and 60% respectively. This is reasonable since Mağusa's sample contained the most numbers of old buildings. Moreover it had the highest percentage of dampness due to leaking pipes, spills and other moisture sources (40%). This is reasonable since Mağusa's sample contained the highest number of apartments. On the other hand it had the lowest settlement cracks and rising damp (8% and 52% respectively).




Figure 5.7: Bar Chart Showing the Occurrence of Defects in İskele District (İ1- İ25)

İskele had the highest percentage of settlement cracks (24%), but the lowest crazing and map/pattern cracking (32% and 20% respectively). Additionally, it had the lowest percentage of dampness due to leaking pipes, spills and other moisture sources (12%). This is reasonable since İskele's sample contained the least number of apartments.




Figure 5.8: Bar Chart Showing the Occurrence of Defects in Lefkoşa District (L1-L25)

Lefkoşa had the least rain penetrations dampness (76%), besides the least corrosion-induced cracking with a percentage of 44%. This is reasonable since Lefkoşa is not a coastal city. However, it had the highest rising damp with a percentage of 84% and as a result the highest percentage of efflorescence with a percentage of 80%.




Figure 5.9: Bar Chart Showing the Occurrence of Defects in Girne District (G1-G25)

Girne had the highest drying shrinkage cracks with a percentage of 48% compared to 28% each for the other cities. Additionally, it had the highest rain penetration dampness with a percentage of 96%.




Figure 5.10: Bar Chart Showing the Overall Occurrence of Defects (M1-M25, I1-I25, L1-L25 and G1-G25)

Joint cracks and crazing were fairly evident in the building of the sample having percentages of 59 % and 57% respectively. On the other hand, map/pattern cracking was found to be less than crazing by having a percentage of 40% (compared to 57% for crazing).

The surface defects of staining and paint peeling were the most common defects found having percentages of 91% and 92% respectively. While segregation was the least common having a percentage of 1% each. The reason for this could be because segregation would be hard to detect in this sample since the buildings here are mostly completed so any form of segregation would be covered under finishes. However, they are much easier to detect in the buildings under construction sample (see section 5.5.2).

33% of the buildings had drying shrinkage cracks. 6% of the buildings were found to have cracks due to embedment of dissimilar metals which can be found around metal handrails. Corrosion-induced cracking were found to be in 56% of the building, while corrosion-induced spalling which can be consider as a severe of the former one were found to be at 36%. Mouldiness also shares the same percentage of corrosion-induced spalling (36%).

Efflorescence and one of its causes; rising damp, were found to be at 68% and 65% respectively. Dampness due to rain penetration was the most common type of dampness with a percentage of 86%. Dampness due to leaking pipes, spills and other moisture sources was found in quarter of the sample (25%). The structural cracks of settlement cracks were found in 15% of the building of the sample.

Honeycombing (8%), cold joints and improper reinforcing steel placement (5% each) are all construction defects. Therefore their detectibly if exited is difficult in such a sample of completed buildings as they would have been hidden under finishes. Finally, defected wooden doors and improper grades of slab surfaces were found in 2% only each of the buildings. The reason for this could be because in order to detect improper grades of slab surfaces, it must be raining during the day of inspection for water bonds to form.

5.5.1.4.1 Corrosion Statistics

First of all, it is noticeable that Lefkoşa had the least corrosion problems among the four district. This is understandable since it is the only non-costal (inland) districts in North Cyprus.

56% of the buildings in the sample had corrosion-induced cracks. However, what about the relation between the age of the building and corrosion? The following table can give us an idea of the chance of corrosion in relation to age.

Table 5.1: Relationship Between Corrosion and Age of Case Study

	Age Groups of Case Studies		
	>43 years old	Between 14 and 43 years old	<14 years old
Number of corroded buildings	19	33	4
Percentage of corroded building per age group	19 corroded out of 22 (86.36%)	33 corroded out of 60 (55.00%)	4 corroded out of 18 (22.22%)

It can be concluded from the table above that the older the building, the more it is prone to corrosion problems. One of the reasons for this could be because of the improvement of construction practice quality, such as the stop of usage of sea water, aggregate and sand as well as the improvement concrete quality used in construction in North Cyprus overtime. The factor of time should not be forgotten also, as corrosion develops and becomes more sever overtime.

5.5.2 Sample 2: Buildings Under Construction

Table 5.2: Statistics for the Under Construction Case Study Group (C1-C25)

Under Construction Case Studies (C1-C25)			
	Defect or Design Fault *	Number of Case Studies Involved (Out of 25 Total)	Percentage of Occurrence %
Seismic Design Faults	Week column-strong beam	1	4.00%
	Torsional Irregularity (Torsion eccentricity)	3	12.00%
	Floor discontinuity	1	4.00%
	Non-continuous beams	12	48.00%
	Non-uniform beam span and cross-section	5	20.00%
	Absence of vertical support at beams intersection	1	4.00%
	Broken axis beams and frames	17	68.00%
	Over-stretched one-way slab	1	4.00%
	Poorly supported or heavily loaded cantilevered slabs	2	8.00%
	Inter-storey strength irregularity (Weak storey)	2	8.00%
	Inter-storey stiffness irregularity (Soft storey)	3	12.00%
	Discontinuity of columns or shear walls	1	4.00%
	Broken axis columns	2	8.00%
	Irregular column plan configuration	9	36.00%
Short column	7	28.00%	
Concrete Defects	Drying shrinkage cracks	2	8.00%
	Improper reinforcing steel placement	7	28.00%
	Cold joints	19	76.00%
	Segregation	3	12.00%
	Honeycombing	19	76.00%

* Not all are listed. Some concrete defects are hard to detect at the time of inspection. Additionally, some seismic design faults are hard to detect without the provision of plans and dimensions.




Figure 5.11: Bar Chart Showing the Statistics for the Under Construction Case Study Group (C1-C25)

The concrete defects of honeycombing and cold joint were found to be the most common defects among the under construction sample with a percentage of 76% each (nearly three quarters of the sample). The second common concrete defect was found to be the improper placement of reinforcing steel at 28% followed by segregation (12%) and drying shrinkage cracks (8%).

On the other hand, the most common design flaws were found to be related to beams; namely: broken axis beams at 68% followed by non-continuous beams at 48%. The third and fourth most common design flaws were related to columns; namely: irregular column plan configuration (36%) and short column (28%) respectively. Non-uniform beam span and cross-sections was found in 20% of the sample.

Torsional irregularity and soft storey were found in 12% each, while broken axis columns, weak storey and poorly supported or heavily loaded cantilevered slabs were found in 8% each. The least common design flaws were: floor discontinuity, discontinuity of columns or shear walls, over-stretched one-way slab and weak column-strong beam which each of them were found in only 4% of the sample.

All of the building in this sample are younger than 14 years old except for two which are between 14 and 43 years old in which the sole case of weak column-strong beam design fault was found in one of them.

Chapter 6

CONCLUSION AND RECOMMENDATION

6.1 Conclusion

There are numerous problems in the process of constructing a safe and sustainable building in North Cyprus, such as, lack of site control or supervision, inexperienced, and unqualified workers employed in the construction industry, lack of soil investigation and lack of experienced and aware engineers and site control. These problems can be solved and avoided by considering the recommendations.

Training programs for workers can be very useful in assisting the quality control of construction. Water isolation problem can be solved by choosing the correct materials for isolation and construction. Seminars and conferences can help engineers, architects and other professionals in construction industry to be updated with design requirements, construction methods and applications. Having the necessary knowledge and awareness the people in the industry will be better qualified for designing and construction works which will be built to the required quality avoiding unnecessary construction problems.

Some owners tend to cut on the costs of construction control. The lack of construction control is one of the main reasons for the defects. Other reasons are: poor workmanship due to rapid construction and lack of qualified workers, inadequate material quality, environmental effects and lack of periodic maintenance.

On the other hand, as North Cyprus has poor building maintenance culture and concept, more awareness should be developed on the importance of good and systematic building maintenance. Maintenance of building is a complicated process and costly but if it is carried out wisely it could save money besides potential extended life span of the building. The maintenance process must involve two types of maintenance i.e. preventive maintenance and corrective maintenance, but it should always be minded that prevention is always better than cure. Architects, engineers, planners etc. should study the potential maintenance and operational problem before working out the design.

Owners should be aware of the importance of construction control as cutting the cost of construction control will later increase the repair and maintenance expenses. North Cyprus need major updates in quality control at all processes of construction. New rules and regulations restricting construction control should be added. Also, the variety of structural systems need to be increased to help in solving some of the problems by reducing the inadequate applications in construction industry by adding alternative systems, such as, pre-fabricated RC, pre-stressed RC and steel framed structures. However, qualified people and imported materials are required to design and construct such systems. Besides, it is very difficult to change the well settles long going construction culture in the country.

The following are the recommendations to overcome construction problems and inadequacies:

- Wrong detailing should be minimized or preferably avoided in projects.
- Inexperienced labourers should be trained according to their skills.

- Soil investigation should be carried out and the foundation design is based on the results of soil investigation. Construction work should not start on site without any soil investigation.
- Design codes and good practice guide for construction should be informed.
- People involved in all levels of construction should have enough knowledge and experience about their work area and they should continuously develop themselves through the regularly hold seminars and training sessions.
- There should be stricter rules for better control of the design and construction process.

In addition, seismic design faults can lead to defects that can be brought out only after the event of an earthquake. Therefore, designers should be aware of them. The design of the structural system is a critical stage as it is decisive in the behaviour of the building during an earthquake. This thesis can act as a reference, especially for students, about building defects, seismic behaviour of RC buildings and common seismic design faults.

Nevertheless, there are noticeable improvements over time relating to building defects in North Cyprus. For example after using readily mixed concrete instead of on site mixed concrete, it can be said that the concrete quality improved. Also less intensity of corrosion cracks occurred in building after abandoning the usage of water, sand and aggregate from the sea in mixing concrete. Similarly, less seismic design faults are noticed in new buildings compares to old ones. For example, the weak column-strong beam design fault found only in a relatively older building.

6.2 Recommendations for Future Studies

This thesis was carried out by a solo researcher. It would be recommended for future studies to carry out similar researches carried by a team and covering larger number of case studies and including regions that have not been included in this thesis, such as the district of Güzelyurt and Lefke. It is also recommended for future research to be cooperated with some governmental authority to allow for the possibility of attaining detailed drawings and floor plans of case studies for more detailed data, identification and analysis of seismic design faults and other defects.

REFERENCES

ACI 201.2R-01, Guide to Durable Concrete.

ACI 224R-01, Control of Cracking in Concrete Structures.

Alsulaimani, G. J., Kaleemullah, M., Basunbul, I. A., & Rasheeduzzafar. (1990). Influence of Corrosion and Cracking on Bond Behavior and Strength of Reinforced-Concrete Members. *ACI Structural Journal*, 87(2), pp 220.

American Institute of Civil Engineers (2006). Minimum Design Forces for Buildings and Other Structures (ASCE/SEI 7-05).

Arnold, C. (1984). Building configuration: the architecture of seismic design. *Bulletin of the New Zealand National Society for Earthquake Engineering*, 17: 2, 83–88.

Celikag, M., & Naimi, S. (2011). Building Construction in North Cyprus: Problems and Alternatives Solutions. *Proceedings of the Twelfth East Asia-Pacific Conference on Structural Engineering and Construction (Easec12)*, 14, 7. doi:10.1016/j.proeng.2011.07.286.

Celikag, M., & Ozbilen, M. (2007). Inadequate Applications of Construction Industry in North Cyprus and Recommendations. In *11th International Conference on Inspection Appraisal, Repair and Maintenance of Structures (Vol. 14-17)*, Kyrenia, North Cyprus, PP.109-115.

Charleson, A. (2008). *Seismic Design for Architects* (First ed.). Oxford, UK: Elsevier Ltd.

Chin-man, L. (2002). *Building Maintenance Guidebook*. Hong Kong.

Curtis, C. (2013). What is Punching Shear? Retrieved from: <http://evstudio.com/what-is-punching-shear/>

Douglas J. & Ramson B. (2006). *Understanding building failures*. 3rd. Taylor and Francis, London: 222-232.

Emmons, P. H. (1993). *Concrete Repair and Maintenance Illustrated* (N. Smit Ed.). Kingaton, Massachusetts, United States of America: R.S.Means Company.

European Committee for Standardization (2004). *Eurocode 8: Design of Structures for Earthquake Resistance – Part 1: General Rules, Seismic Actions and Rules for Buildings* (BS EN 1998–1:2004).

Kitagawa, Y. & Takino, F. (1994). Chapter 24 Japan. In *International handbook of earthquake engineering: Codes, programs, and examples*. (Paz, M. Ed.). US: Chapman & Hall.

Naimi, s., & Celikag, m. (2010). Problems of Reinforce Concrete Building Construction in North Cyprus. *Proceedings of the 12th international conference on inspection appraisal repairs and maintenance of structures*, vols 1 and 2, 821-828.

Ozay, G., & Ozay, N. (2005). The Most Common Defects on Housing Surfaces in Northern Cyprus. World Congress on Housing. Transforming Housing Environments through Design. Pretoria, South Africa.

Ozmen, C., & Unay, A. I. (2007). Commonly encountered seismic design faults due to the architectural design of residential buildings in Turkey. *Building and Environment*, 42(3), 1406-1416. doi:10.1016/j.buildenv.2005.09.029

Sacramento, P. V. P., Ferreira, M. P., Oliveira, D. R. C., and Melo, G. S. S. A.. (2012). Punching strength of reinforced concrete flat slabs without shear reinforcement. *Revista IBRACON de Estruturas e Materiais*, 5(5), 659-691. <https://dx.doi.org/10.1590/S1983-4195201200050000>

Sassu, M., & De Falco, A. (2014). Legal Disputes and Building Defects: Data from Tuscany. *Journal of Performance of Constructed Facilities*, 28(4), 8. doi:10.1061/(asce)cf.1943-5509.0000520

Specifications for Buildings to Be Built in Seismic Zones. (Ministry of Public Works and Settlement, 1997, 2007). Ankara, Turkey.

Suffian, A. (2013). Some Common Maintenance Problems and Building Defects: Our Experiences. 2nd International Conference on Rehabilitation and Maintenance in Civil Engineering (Icrmcce), 54, 101-108. doi:10.1016/j.proeng.2013.03.009.

Trotman, P., Sanders, C., & Harrison, H. (2004). Understanding Dampness: Effects, Causes, Diagnosis and Remedies (illustrated ed.). UK: BRE Bookshop.

TS 500 Turkish Standards “Requirements for Design and Construction of Reinforced Concrete structures” February 2000. Ankara, Turkey.

United States Geological Survey (USGS). <https://earthquake.usgs.gov/>

Özmen, C. (2008). A Comparative Structural And Architectural Analysis Of Earthquake Resistant Design Principles Applied In Reinforced Concrete Residential Buildings In Turkey. (PHD Thesis), Middle East Technical University, Ankara, Turkey.

Özbilen, M., (2004). Inadequate applications of construction industry in North Cyprus and Recommendations. Famagusta, MS. Thesis, Turkish Republic of Northern Cyprus: Eastern Mediterranean University.

APPENDIX

Appendix A: Case Study Checklist Sample

Case Study # ?								
Profile		Seismic Design Faults						
<div style="border: 2px solid red; padding: 10px; text-align: center; color: red; font-weight: bold;"> INSERT PROFILE PICTURE HERE </div>		Week column-strong beam						
		Structural configuration	Horizontal structural configuration	Irregularity in plan	Torsional Irregularity (Torsion eccentricity)			
					Floor discontinuity			
				Projections in plan				
			Beam elementary design faults	Non-continuous beams				
				Non-uniform beam span and cross-section				
Absence of vertical support at beams intersection								
Slab elementary design faults	Over-stretched one-way slab							
	Poorly supported or heavily loaded cantilevered slabs							
		Pounding and separation problem						
District:		Vertical structural configuration	Irregularity in elevation	Weak storey				
Area:				Soft storey				
Street name:				Discontinuity of columns or shear walls				
Latitude:			Vertical structural elementary design fault	Broken axis columns				
Longitude:				Irregular column and/or shear-wall plan configuration				
Structure age:	<table border="1" style="width: 100%;"> <tr> <td style="width: 30%;"><input type="checkbox"/> <14 years</td> <td>Date (if available):</td> </tr> <tr> <td colspan="2"><input type="checkbox"/> Between 14 and 43 years (1974-2003)</td> </tr> <tr> <td colspan="2"><input type="checkbox"/> >43 years (Before 1974)</td> </tr> </table>			<input type="checkbox"/> <14 years	Date (if available):	<input type="checkbox"/> Between 14 and 43 years (1974-2003)		<input type="checkbox"/> >43 years (Before 1974)
<input type="checkbox"/> <14 years	Date (if available):							
<input type="checkbox"/> Between 14 and 43 years (1974-2003)								
<input type="checkbox"/> >43 years (Before 1974)								
Building type:	Residential	Apartment	Non-Structural Defects					
		House						
		Dormitory						
	Public	Waterproofing defects, water leakage and seepage						
	Commercial	Defected wooden door						
Building status:	Under Construction		Surface defects	dampness				
	Occupied				Condensation			
	Abandoned				Rising damp			
		Rain penetration						
Reinforced Concrete Defects				Surface cracks on wall finishes				
Drying shrinkage cracks								
Corrosion of metals embedded in concrete	Corrosion-induced cracking		crazing					
	Corrosion-induced spalling							
	Cracks due to embedment of dissimilar metals (handrails)		Map/pattern cracking					
Construction defects (faulty workmanship): designer, detailer, and contractor	Improper reinforcing steel placement		Efflorescence					
	Premature removal of forms		Paint peeling					
	Cold joints		Mouldiness					
	Segregation		Wall finishes workmanship problem					
	Honeycombing		Staining					
	Improper grades of slab surfaces							
Cracks in RC due to load effects (structural cracks)	Slab/beam-to column shear (punching shear) cracks		Non-structural cracks	Joint cracks				
	Cantilevered member cracks							
	Settlement cracks							
Other notes (if available):								